Office	PM State of New Mexico	Form C-103 of 5
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION	30-045-33436
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE X FEE 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	201100 1 0, 1 1111 0 , 0 00	NM V073920000
87505 SUNDRY NOTI	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPORTION OF THE PROP	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	Boeing
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well  Other	8. Well Number 3
2. Name of Operator Robert L. Bay	less, Producer LLC, 621 17th Street, Ste 2300,	9. OGRID Number
3. Address of Operator same	<u>J293</u>	150182 10. Pool name or Wildcat
3. Madress of operator same		Basin Dakota / Blanco Mesaverde
4. Well Location		
Unit Letter B:	itel from the fine that	
Section 2	Township 26N Range 8W NW	
	11. Elevation (Show whether DR, RKB, RT, GR, 6183 GR	etc.)
12. Check A	Appropriate Box to Indicate Nature of Not	ice, Report or Other Data
NOTICE OF IN	TENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL V	
TEMPORARILY ABANDON	<del></del>	DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEN	
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM  OTHER:	☐ OTHER:	
		s, and give pertinent dates, including estimated date
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple	e Completions: Attach wellbore diagram of
proposed completion or rec	ompletion.	
Robert L. Bayless, Produc	cer LLC plugged and abandoned the subject v	vell. Work was completed 02/23/2023.
	ging report and final WBD.	70 Work Mad 60pietod 62/20/2020.
Spud Date:	Rig Release Date:	
Spud Bute.	Tag Release Bate.	
I hereby certify that the information	above is true and complete to the best of my know	ledge and belief.
111110	1	
SIGNATURE //	TITLE Production & Regu	latory Analyst DATE 04/18/2023
751		
Type or print name <u>Helen Trujillo</u> <b>For State Use Only</b>	E-mail address: notices@i	rlbayless.com PHONE: 505-326-2659
<del></del>	Kuchling Danite Oil and Oc	4/04/0000
APPROVED BY: Wonica Conditions of Approval (if any):	Kushling TITLE Deputy Oil and Ga	s Inspector DATE 4/24/2023

### **AS PLUGGED REPORT**

# Boeing #3

### As Plugged on 2/23/2023

Basin Dakota / Blanco Mesaverde Unit B, 661' FNL & 1608' FEL, Section 2, T26N, R8W San Juan County, NM, API #30-045-33436

**2/13/23.** Travel to location. Road rig and equipment to location. Held JSA. RU Rig and pumping equipment. Check pressures on well; 780# on Casing, 10# on Tubing, and 0# on BH. RU relief lines and blow down well to pit. Work rod string free and LD 2 rods. Shut in well and SDFD.

**2/14/23**. Travel to location. Held JSA. Check well pressures; 780# on Casing, 420# on Tubing, and 0# on BH; blow down to pit. Wait on Hot Oil truck, truck broke down. Shut in well and SDFS.

**2/15/23**. Travel to location. Held JSA. Check well pressures; Tubing 500#, Casing 700#, and BH 0#, blow down well to pit. RU Poor Boys Hot Oil, load 50 bbls of water to preheat, pump down tubing and released pump. Attempt to pressure test tubing, pumped 30 bbls, test failed. RD Hot Oil. Start to LD rods, 98 7/8" and 170 3/4" and tubing pump. Change from rod tools to tubing tools. Shut in well and SDFD.

**2/16/23.** Travel to location. Held JSA. Check well for pressures; Tubing 0#, Casing 50# and BH 0#, Blow down well to pit. ND wellhead and NU BOP and RU work floor. TOOH with production tubing, 203 joints and 12' MA. TIH with 4-1/2" casing scraper and safety valve and pressure test casing every 40'. RIH 70 stands, secure location and SDFD.

**2/17/23.** Travel to location. Held JSA. Check well pressures; 0# on tubing, 0 # on casing, 0# on BH; opened well to pit. Finish TIH with casing scraper to 6580' and pressure test tubing, tested good. Fish safety valve and TOOH and LD casing scraper. TIH w/ 4-1/2" CR and set @ 6532', release and sting out.

**Plug #1** Dakota top: Mix and pump 20 sxs of Class G cement @ 15.8 ppg from 6532'. POOH and LD 8 joints, stand back 95 stands. Shut in well and SDFD.

**2/20/23.** Travel to location. Held JSA. Check well pressures; no pressures. PU tagging sub and TIH, tagged Plug #1 @ 6220'. LD 25 joints to next plug.

**Plug #2 Gallup top:** Mix and pump 16 sxs Class G cement @ 15.8 ppg inside casing from 5435' to 5230'. POOH and LD 7 joints and stand back 79 stands. WOC for 4 hours. TIH

Page 1 of 2

and tag Plug #2 @ 5134'. TOOH and LD 24 joints and stand back 67 stands. Shut in well and SDFD.

**2/21/23.** Travel to location. Held JSA. Check well pressures and open to pit; no pressures. PU 4-1/2" CR and TIH and set @ 4410', release and sting out. Establish circulation with 33 bbls, pumped total of 73 bbls. Pressure test casing to 600#, tested good.

**Plug #3 Mancos top:** Mix and pump 12 sxs Class G cement @ 15.8 ppg inside casing from 4410' to 4256'. LD 18 joints to next plug.

**Plug #4 Mesaverde top:** Mix and pump 12 sxs Class G cement @ 15.8 ppg inside casing from 3816' to 3662'. LD 18 joints to next plug.

**Plug #5 Chacra top:** Mix and pump 12 sxs Class G cement @ 15.8 ppg from 3230' to 3076'. LD 30 joints and TOOH standing back 34 stands and LD stinger. TIH with 34 stands. Shut in well and SDFD.

**2/22/23**. Travel to location. Held JSA. Check well pressures and open well to pit; no pressures. Establish circulation w/ 2 bbls.

Plug #6 Pictured Cliffs through Ojo Alamo intervals and tops: Mix and pump 72 sxs Class G cement @ 15.8 ppg inside casing from 2236' to 1372'. LD 57 joints to next plug and circulate w/ 3 bbls.


**Plug #7 Surface Casing shoe and surface:** Mix and pump 30 sxs Class G cement @ 15.8 ppg inside casing from 378' to surface. LD 11 joints and WOC. NMOCD shut down due to bad weather. Shut in well and SDFD.

**2/23/23**. Travel to location. Held JSA. Check well pressures and open well to pit; no pressures. Open BOP and measure TOC @ 40' in production casing. ND BOP. RU welder to cut off well head and install P&A marker. TOC in BH 18'. RU pump to poly pipe and top off annuli with 25 sxs Class G cement @ 15.8 ppg. RD and MOL.

## Boeing #3

## As Plugged on 2/23/2023

Basin Dakota / Blanco Mesaverde Unit B, 661' FNL & 1608' FEL, Section 2, T26N, R8W San Juan County, NM, API #30-045-33436



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 208807

#### **CONDITIONS**

Operator:	OGRID:
ROBERT L BAYLESS PRODUCER LLC	150182
621 17th Street, Suite 2300	Action Number:
Denver, CO 80293	208807
	Action Type:
	[C-103] Sub. Plugging (C-103P)

#### CONDITIONS

Created By	Condition	Condition Date
mkuehling	well plugged 2/23/2023 - please submit 103Q	4/24/2023