

District I (575) 202 (161	State of New Mexico	Page 1 of Form C-10	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 201 WELL API NO.	
District II - (575) 748-1283	OIL CONCEDUATION DIVIGION	30-005-10522	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Cato San Andres Unit	
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)  1. Type of Well: Oil Well	CATION FOR PERMIT" (FORM C-101) FOR SUCH  Gas Well  Other	8. Well Number 032	
2. Name of Operator	das wen Other	9. OGRID Number	
Cano Petro of New Mexico, Inc		330485	
<ol> <li>Address of Operator</li> <li>801 Cherry Street Suite 3200 Un</li> </ol>	it 25 Fort Worth, TX 76102	10. Pool name or Wildcat Cato; San Andres	
4. Well Location		THE RESERVE OF THE PERSON OF T	
Unit Letter E	1980feet from theN line and	660_feet from the W_ line	
Section 10	Township 08S Range 30E	NMPM County Chaves	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.		
	4071	4	
OTTIER.	OTHER:		
of starting any proposed we proposed completion or rec	leted operations. (Clearly state all pertinent details, an ork). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated dompletions: Attach wellbore diagram of	
13. Describe proposed or comp of starting any proposed we proposed completion or rec NMOCD plugged well accor	Rig Release Date:	ompletions: Attach wellbore diagram of	
13. Describe proposed or comp of starting any proposed we proposed completion or rec NMOCD plugged well accor	eleted operations. (Clearly state all pertinent details, and ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  ding to attached EOW report and plugged WBD.	ompletions: Attach wellbore diagram of	
13. Describe proposed or comp of starting any proposed we proposed completion or rec NMOCD plugged well accor	Rig Release Date:  Rig Release Date:	empletions: Attach wellbore diagram of	
13. Describe proposed or compof starting any proposed we proposed completion or recommod NMOCD plugged well according to the proposed starting any proposed well according to the proposed completion or recommod numbers.  Spud Date:	Rig Release Date:  Rig Release Date:  TITLE Authorized Representative	ge and belief.  DATE 5/4/22	







### Cano Petro Inc./NMOCD OWP

# Plug And Abandonment End Of Well Report Cato San Andres Unit #032

1980' FNL & 660' FWL, Section 10, T8S, R30E Chaves County, NM / API 30-005-10522

#### Work Summary:

- 4/19/22 Made NMOCD P&A operations notifications at 9:00 AM MST.
- 4/20/22 Prepped location with backhoe. MOL and R/U P&A rig. Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Secured and shut-in well for the day.
- 4/21/22 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. Removed horse's head in preparation to pull rods. Worked stuck sucker rod pump free. L/D 133 ¾" sucker rods, and sucker rod pump. N/D wellhead, N/U BOP and function tested. Worked stuck tubing. Attempted to release tubing anchor but was unsuccessful. Waited on orders from NMOCD on how to proceed. Secured and shut-in well for the day.
- Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. R/U wireline services. RIH through 2-3/8" tubing with gauge ring to a depth of 3,280'. RIH and jet cut tubing at 3,220'. L/D 103 joints of 2-3/8" tubing. P/U casing scraper and work string and round tripped above fish top to a depth of 3,215'. Worked through tight spots at 50' and 60' TIH and TOOH. NMOCD requested to TIH with mule shoe sub to spot cement. TIH with mule shoe sub to 3,211'. R/U cementing services. Circulated wellbore clean with 60 bbls of fresh water. Pumped plug #1 from 3,211'-2,837' to cover the San Andres perforations and formation top. L/D tubing up to next plug depth. TOOH with remaining tubing. WOC overnight. Secured and shut-in well for the day.

4/27/22

Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. R/U wireline services. RIH to run CBL and tagged up at 490'. Wireline could not make any further progress down wellbore. Attempted to pressure test production casing to 500 psi in which it failed to hold pressure. TIH and tagged plug #1 top at 2,847'. Spotted 9.5 ppg mud spacer from 2,847'-1,595'. L/D tubing up to next plug depth. R/U cementing services. Pumped plug #2 from 1,595'-920' to cover the Yates and Rustler formation tops. L/D tubing up to next plug depth. TOOH with remaining tubing. WOC 4 hours. R/U wireline services. RIH and tagged up at 490'. NMOCD requested to perforate at 485' and attempt to circulate cement to surface. R/U wireline services. RIH and perforated squeeze holes at 485'. Attempted to establish circulation down production casing through perforations at 485' and back around and out Bradenhead valve at surface but was unsuccessful. TIH to tag plug #2 top but tagged up at 464'. Worked tubing but could not make any further progress down wellbore. TOOH with tubing. Secured and shut-in well for the day.

4/28/22

Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. R/U cementing services. Attempted to establish circulation down production casing through perforations at 485' and back around and out Bradenhead valve at surface but was unsuccessful. Pumped cement down production casing through perforations at 485' in an attempt to circulate to surface. Pumped 136 sx of cement without circulating back to surface. WOC 4 hours. R/U cementing services. Successfully established injection rate into perforations at 485'. Pumped cement down production casing and into perforations at 485'. When pumping cement slips on 4 ½" production casing started to move. Displaced water to perforations at 485'. Secured and shut-in well for the day.

4/29/22

Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. TIH and tagged plug #3 top at 467'. Attempted to pressure test production casing in which it failed to hold pressure. L/D work string to surface. R/U wireline services. RIH and perforated squeeze holes at 465'. Attempted to establish injection rate into perforations at 465' but was unsuccessful. RIH and perforated squeeze holes at 408'. Attempted to establish injection rate into perforations at 408' but was unsuccessful. RIH and perforated squeeze holes at 200'. Successfully established circulation down production casing through perforations at 200' and back around and out Bradenhead valve at surface. TIH to 467'. R/U cementing services. Pumped surface plug from 467' to perforations at 200' and successfully circulated cement through perforations at 200' and back around and out Bradenhead valve at surface. N/D BOP, N/U wellhead. Secured and shut-in well for the day.

5/2/22

Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. Dug out wellhead with backhoe. Performed wellhead cut-off. Cement was at surface in 8-5/8" surface casing annulus. Ran weighted tally tape down 4 ½" production casing and tagged cement 20' down. Ran ¾" poly pipe down 4 ½" production casing. R/U cementing services. Topped-off well with 6 sx of cement. Installed subsurface P&A marker per NMOCD regulations. Photographed the P&A marker in place and recorded its location via GPS coordinates. Back filled P&A marker. R/D and MOL.

#### Plug Summary:

# Plug #1:(San Andres Perforations and Formation Top 3,211'-2,847', 25 Sacks Type III Cement)

Mixed 25 sx Type III cement and spotted a balanced plug to cover the San Andres perforations and formation top.

## Plug #2:(Yates and Rustler Formation Tops 1,595'-920', 45 Sacks Type III Cement)

Mixed 45 sx Type III cement and spotted a balanced plug to cover the Yates and Rustler formation tops.

## Plug #3: (Surface Casing Shoe 485'-Surface, 246 Sacks Type III Cement(6 sx for Top-off))

RIH and tagged up at 490'. NMOCD requested to perforate at 485' and attempt to circulate cement to surface. R/U wireline services. RIH and perforated squeeze holes at 485'. Attempted to establish circulation down production casing through perforations at 485' and back around and out Bradenhead valve at surface but was unsuccessful. TIH to tag plug #2 top but tagged up at 464'. Worked tubing but could not make any further progress down wellbore. TOOH with tubing. R/U cementing services. Attempted to establish circulation down production casing through perforations at 485' and back around and out Bradenhead valve at surface but was unsuccessful. Pumped cement down production casing through perforations at 485' in an attempt to circulate to surface. Pumped 136 sx of cement without circulating back to surface. WOC 4 hours. R/U cementing services. Successfully established injection rate into perforations at 485'. Pumped cement down production casing and into perforations at 485'. When pumping cement slips on 4 1/2" production casing started to move. Displaced water to perforations at 485'. TIH and tagged plug #3 top at 467'. Attempted to pressure test production casing in which it failed to hold pressure. L/D work string to surface. R/U wireline services. RIH and perforated squeeze holes at 465'. Attempted to establish injection rate into perforations at 465'

but was unsuccessful. RIH and perforated squeeze holes at 408'. Attempted to establish injection rate into perforations at 408' but was unsuccessful. RIH and perforated squeeze holes at 200'. Successfully established circulation down production casing through perforations at 200' and back around and out Bradenhead valve at surface. TIH to 467'. R/U cementing services. Pumped surface plug from 467' to perforations at 200' and successfully circulated cement through perforations at 200' and back around and out Bradenhead valve at surface. N/D BOP, N/U wellhead. Dug out wellhead with backhoe. Performed wellhead cut-off. Cement was at surface in 8-5/8" surface casing annulus. Ran weighted tally tape down 4 1/2" production casing and tagged cement 20' down. Ran 34" poly pipe down 4 ½" production casing. R/U cementing services. Topped-off well with 6 sx of cement. Installed subsurface P&A marker per NMOCD regulations. Photographed the P&A marker in place and recorded its location via GPS coordinates. Back filled P&A marker. R/D and MOL.

rical contract planting and religion

program in the state of the sta

### **End of Well Wellbore Diagram**

Cato San Andres Unit #032 API #: 30-005-10522 Chaves County, New Mexico

#### Plug 3

485 feet - Surface 485 feet plug 246 sacks of Type III Cement 6 sks of Type III Top off

#### Plug 2

1595 feet - 920 feet 675 feet plug 45 sacks of Type III Cement

#### <u>Plug 1</u> 3211 feet - 2847 feet

364 feet plug 25 sacks of Type III Cement

#### **Perforations**


3261 feet - 3288 feet
 3331 feet - 3336 feet
 3342 feet - 3346 feet
 3353 feet - 3380 feet

#### **Surface Casing**

8.625" 24# @ 458 ft

#### **Formation**

Rustler - 1072 ft Yates - 1545 ft San Andres - 3211 ft



Production Casing 4.5" 9.5# @ 3410 ft

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 105041

#### **CONDITIONS**

Operator:	OGRID:
J.A. Drake Well Service Inc.	330485
607 W Pinon	Action Number:
Farmington, NM 87401	105041
	Action Type:
	[C-103] Sub. Plugging (C-103P)

#### CONDITIONS

Created By		Condition Date
john.harrison	None	5/3/2023