Received by UCD.S1/10/2022 10:25:26 AM U.S. Department of the Interior		Sundry Print Report		
BUREAU OF LAND MANAGEMENT				
Well Name: SKELLY UNIT	Well Location: T17S / R31E / SEC 21 / NWNW /	County or Parish/State: EDDY / NM		
Well Number: 952	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:		
Lease Number: NMNM98122	Unit or CA Name: SKELLY UT - GLORIETA-YESO	Unit or CA Number: NMNM71030C		
US Well Number: 3001532895	Well Status: Water Injection Well	Operator: SPUR ENERGY PARTNERS LLC		

Notice of Intent

Sundry ID: 2699757

Type of Submission: Notice of Intent

Date Sundry Submitted: 10/26/2022

Date proposed operation will begin: 11/15/2022

Type of Action: Workover Operations Time Sundry Submitted: 07:52 5

Procedure Description: This well is down with either a HIT or packer leak. We plan to repair the damaged/broke equipment and return the well to injection. Please find procedures and WBD attached for your review. Thank you.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Skelly_952_HIT_or_Packer_Leak_Procedure_and_WBD_20221026075215.pdf

R	eceived by OCD: 11/10/2022 10:25:26 AM Well Name: SKELLY UNIT	Well Location: T17S / R31E / SEC 21 / NWNW /	County or Parish/State: EDDy /2 of 5 NM
	Well Number: 952	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
	Lease Number: NMNM98122	Unit or CA Name: SKELLY UT - GLORIETA-YESO	Unit or CA Number: NMNM71030C
	US Well Number: 3001532895	Well Status: Water Injection Well	Operator: SPUR ENERGY PARTNERS LLC

Conditions of Approval

Specialist Review

Workover_or_Vertical_Deepen_COA_20221109155240.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: SARAH CHAPMAN

Name: SPUR ENERGY PARTNERS LLC

Title: Regulatory Directory

Street Address: 9655 KATY FREEWAY, SUITE 500

City: Houston State: TX

Phone: (832) 930-8613

Email address: SCHAPMAN@SPUREPLLC.COM

Field

Representative Name: Street Address: City: Phone: Email address:

State:

BLM Point of Contact

BLM POC Name: Jonathon W Shepard BLM POC Phone: 5752345972 Disposition: Approved Signature: Jonathon Shepard Signed on: OCT 26, 2022 07:52 AM

BLM POC Title: Petroleum Engineer

Zip:

BLM POC Email Address: jshepard@blm.gov

Disposition Date: 11/09/2022


- 1. RIH with 2.25F profile Plug and set in packer at 9347'. If successful, pressure up on tubing to confirm HIT or Packer issue.
- 2. If HIT is confirmed continue with HIT Procedure, if packer leak is found, continue with packer leak procedure

HIT Procedure

- 1. MIRU Pulling unit
- 2. Ensure well pressure is 0, kill if needed, ND Tree, NU BOP
- 3. Release from on/off tool at ~9,345' and POOH with 3-1/2" Lined Tubing
- 4. Send on/off tool to shop to be re-dressed
- 5. RIH with 3-1/2" Lined Tubing and on/off top piece while hydrotesting
- 6. 3ft above on/off tool, Circulate packer fluid
- Latch onto packer at ~9,345', test backside, if good test, continue, if test is unsuccessful, contact engineer
- 8. ND BOP, NU tree
- 9. Retrieve plug in the packer
- 10. Conduct MIT test before resuming injection

Packer Leak Procedure

- 1. MIRU Pulling unit
- 2. Kill well with kill mud or MI Snubbing unit for well control
- 3. Ensure well pressure is 0 and ND WH and NU BOP or NU snubbing unit
- 4. Release packer at 9,347' POOH with 3-1/2" Lined Tubing
- 5. MI new packer with POP installed
- 6. RIH with new packer and 3-1/2" Lined Tubing and on/off tool while hydrotesting
- 7. Set packer back at 9,347', release from packer and pull up 3ft, Circulate packer fluid
- Latch onto packer at ~9,347', test backside, if good test, continue, if test is unsuccessful, contact engineer
- 9. ND BOP, NU tree
- 10. Conduct MIT and pump out POP before resuming injection



CREATED ON 6/28/2021 UBCARES CA 40/28/2829 Bit TABK 3023 AM

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	157678
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

CONDITIONS			
	Created By	Condition	Condition Date
	mgebremichael	The packer is required to be set within 100 ft. of the top perforation/ open hole.	5/30/2023

Page 5 of 5

Action 157678