

Well Name: YOUNG DEEP UNIT	Well Location: T18S / R32E / SEC 9 / NENE /	County or Parish/State: LEA / NM
Well Number: 08	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMLC064009D	Unit or CA Name: YOUNG DEEP UNIT - BONE SP	Unit or CA Number: NMNM71067B
US Well Number: 3002527535	Well Status: Producing Oil Well	Operator: MATADOR PRODUCTION COMPANY

Notice of Intent

Sundry ID: 2729874

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 05/09/2023

Time Sundry Submitted: 01:02

Date proposed operation will begin: 05/20/2023

Procedure Description: Matador is requesting to plug and abandon the Young Deep Unit #008, per the required BLM COAs, following the procedure below: • Notify BLM 24 hrs before MIRU. • Safety mtg, MIRU, check pressures, ND wellhead, NU & test BOPs, POOH w/ rods & tbg. • RIH & set CIBP at 8,375'; Pressure test csg to 500 psi for 30 minutes; Circulate and displace hole w/ MLF. • Spot 25 sks Class H cmt on top of CIBP; WOC & Tag. • Perf & Sqz 50 sks of CI C cmt at 6,258'; WOC & Tag. (Bone Spring) • Spot 125 sk balanced plug of CI C cmt at 5,500'. (Old Cement Squeeze) • Perf & Sqz 50 sks of CI C cmt at 3,650'; WOC & Tag. (Intermediate Shoe) • Perf & Sqz 200 sks of CI C cmt at 2,750'; WOC & Tag. (Salt Section) • Perf @ 720' & Sqz CI C cmt to surface on all strings. (Surface Shoe) • Cut off wellhead and ensure cmt to surface on all csg strings. • Install dry hole marker per BLM/NMOCD specifications. *Current and proposed wellbore diagrams attached **Mud laden fluid (MLF) mixed at 25sx/100 bbls water will be spotted between each plug.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

- Young_Deep_Unit__008_Planned_P_A_WBD_20230509130238.pdf
- Young_Deep_Unit__008_Current_WBD_20230509130226.pdf

Well Name: YOUNG DEEP UNIT	Well Location: T18S / R32E / SEC 9 / NENE /	County or Parish/State: LEA / NM
Well Number: 08	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMLC064009D	Unit or CA Name: YOUNG DEEP UNIT - BONE SP	Unit or CA Number: NMNM71067B
US Well Number: 3002527535	Well Status: Producing Oil Well	Operator: MATADOR PRODUCTION COMPANY

Conditions of Approval

Specialist Review

Young_Deep_Unit_8_Revised__P_A_Procedure__and_COA_20230609161702.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: BRETT JENNINGS

Signed on: MAY 09, 2023 01:02 PM

Name: MATADOR PRODUCTION COMPANY

Title: Regulatory Analyst

Street Address: 5400 LBJ FREEWAY, STE 1500

City: DALLAS

State: TX

Phone: (972) 629-2160

Email address: BRETT.JENNINGS@MATADORRESOURCES.COM

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: ZOTA M STEVENS

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345998

BLM POC Email Address: ZSTEVENS@BLM.GOV

Disposition: Approved

Disposition Date: 06/09/2023

Signature: ZOTA Stevens

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

**Permanent Abandonment of Federal Wells
Conditions of Approval (LPC Habitat)**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.** Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:

From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo “interim” reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo “final” reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any/all contaminants, scrap/trash, equipment, pipelines and powerlines **(Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure)**. Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip (across the slope and seed as specified in the original APD COA. **This will apply to well pads, facilities, and access roads.** Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

- have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos
Supervisory Petroleum Engineering Tech/Environmental Protection Specialist
575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias
Environmental Protection Specialist
575-234-6230

Crisha Morgan
Environmental Protection Specialist
575-234-5987

Jose Martinez-Colon
Environmental Protection Specialist
575-234-5951

Mark Mattozzi
Environmental Protection Specialist
575-234-5713

Robert Duenas
Environmental Protection Specialist
575-234-2229

Revised Plugging Procedure


Matador is requesting to plug and abandon the Young Deep Unit #008, per the required BLM COAs, following the procedure below:

- Notify BLM 24 hrs before MIRU.
- Safety mtg, MIRU, check pressures, ND wellhead, NU & test BOPs, POOH w/ rods & tbg.
- RIH and TAG CIBP at 8625'.
- RIH & set CIBP at 8,375'; Pressure test csg to 500 psi for 30 minutes; Circulate and displace hole w/ MLF.
- Spot 25 sks Class H cmt on top of CIBP; WOC & Tag.
- Perf & Sqz 50 sks of Cl C cmt at 6,258'; WOC & Tag. (T/Bone Spring)
- Spot 125 sk balanced plug of Cl C cmt at 5,500'. (Old Cement Squeeze)
- Perf & Sqz Cl C cmt from 4100' to 3900'.
- Perf & Sqz 50 sks of Cl C cmt at 3,650'; WOC & Tag. (Intermediate Shoe)
- Perf & Sqz 200 sks of Cl C cmt at 2,750'; WOC & Tag. (Salt Section)
- Perf @ 720' & Sqz Cl C cmt to surface on all strings. (Surface Shoe)
- Cut off wellhead and ensure cmt to surface on all csg strings.
- Install dry hole marker per BLM/NMOCD specifications.

*Current and proposed wellbore diagrams attached

**Mud laden fluid (MLF) mixed at 25sx/100 bbls water will be spotted between each plug.

MATADOR RESOURCES
 Young Deep Unit #8
 660' FNL & 860' FEL Sec 9 - 18S - 32E
 Lea County, NM
 API: 30-025-27535
 Current WELLBORE SCHEMATIC
 Spudded: 10/05/1981



Casing Information						
	Hole Size	Casing Size	Type	Weight lb/ft	Joints	Depth Set
Surface	17 1/2	13 3/8	ST&C J-55	48	10	666
Intermediate	11	8 5/8	ST&C J-55	24 + 32	88	3600
Production	7 7/8	5 1/2	LT&C J-55	15 1/2 + 17	213	8,710
	DV Tool Marker Jt. Float Collar					

Cementing Record						
Surface	750 sx Cl "C" (Circulated)					
Intermediate	1400 sx 65/35 "C" & 200 sx "C" (300sx back)					
Production	350 sx 65/35 Cl "H"					

Tubing		Rods		Geologic Markers	
Joints	257, TAC, 8 SN, SND SCRN, BP	Total	338	Rustler	1189
Diam.	2 3/8	7/8"	118	Yates	2697
Grade		3/4"	199	Bowers	3575
Weight		7/8"	21	Queen	3830
Packer		1"		Prenrose	4066
PBTD	8625	Pony	6', 4'	Grayburg	4346
TAC	8247	Pump		Bone Springs	6208
SN	8503	2 x 1 1/2 x 24' w/CW & BOC		1st BS Sand	7862
BP	8527			1st BS Sand (Base)	8081
				2nd BS Sand	8558

(12/99) Located holes from 4,754' - 5,204'; Set packer at 5,645 & Sqz 250 SXS LITE PREMIUM PLUS & 150 SXS CLASS C; Tag @ 4,836' drill out to CIBP

(11/99) Shot Sqz holes at 6,925'; Sqz 430 sks Class H cmt & tag at 6,210'

(10/99) Perfs: 8,432' - 56'; 2SPF 30 Holes

(10/99) Set CIBP @ 8,625'

(2/94) Frac Open hole (8,713' - 8,902')

(11/81) Perfs: 8,430' - 54' 48 Holes

(3/86) Perfs: 8,468' - 96'; 25holes

(10/87) Sqzd Perfs: 8,430'-96'

(10/99) Perfs: 8,432' - 36'; 8,446' - 56'; 2SPF 30 Holes

Acdz 250 gal w/ 10% Acetic; 7500 gal 20% DS-30


Acdz w/ 4400 gal of 15% SRA + 50 Ball Sealers

Acdz 6000 gal

11/87 Drilled 85' OH lateral
 KOP @ 8,713' North 1° East True
 85' 4-1/2" Lateral (8,713' - 8,798')

10/87 Drilled 180' OH lateral
 KOP @ 8,902' North 75° East True 180' 4-1/2" Lateral (8,902' - 9,082')

TD @ 9,082'




Matador is requesting to plug and abandon the Young Deep Unit #008, per the required BLM COAs, following the procedure below:

- Notify BLM 24 hrs before MIRU.
- Safety mtg, MIRU, check pressures, ND wellhead, NU & test BOPs, POOH w/ rods & tbg.
- RIH & set CIBP at 8,375'; Pressure test csg to 500 psi for 30 minutes; Circulate and displace hole w/ MLF.
- Spot 25 sks Class H cmt on top of CIBP; WOC & Tag.
- Perf & Sqz 50 sks of CI C cmt at 6,258'; WOC & Tag. (Bone Spring)
- Spot 125 sk balanced plug of CI C cmt at 5,500'. (Old Cement Squeeze)
- Perf & Sqz 50 sks of CI C cmt at 3,650'; WOC & Tag. (Intermediate Shoe)
- Perf & Sqz 200 sks of CI C cmt at 2,750'; WOC & Tag. (Salt Section)
- Perf @ 720' & Sqz CI C cmt to surface on all strings. (Surface Shoe)
- Cut off wellhead and ensure cmt to surface on all csg strings.
- Install dry hole marker per BLM/NMOCD specifications.

*Current and proposed wellbore diagrams attached

**Mud laden fluid (MLF) mixed at 25sx/100 bbls water will be spotted between each plug.

MATADOR RESOURCES
 Young Deep Unit #8
 660' FNL & 860' FEL Sec 9 - 18S - 32E
 Lea County, NM
 API: 30-025-27535
 Current WELLBORE SCHEMATIC
 Spudded: 10/05/1981



Casing Information						
	Hole Size	Casing Size	Type	Weight lb/ft	Joints	Depth Set
Surface	17 1/2	13 3/8	ST&C J-55	48	10	666
Intermediate	11	8 5/8	ST&C J-55	24 + 32	88	3600
Production	7 7/8	5 1/2	LT&C J-55	15 1/2 + 17	213	8,710
	DV Tool Marker Jt. Float Collar					

Cementing Record						
Surface	750 sx Cl "C" (Circulated)					
Intermediate	1400 sx 65/35 "C" & 200 sx "C" (300sx back)					
Production	350 sx 65/35 Cl "H"					

Tubing		Rods		Geologic Markers	
Joints	257, TAC, 8 SN, SND SCRIN, BP	Total	338	Rustler	1189
Diam.	2 3/8	7/8"	118	Yates	2697
Grade		3/4"	199	Bowers	3575
Weight		7/8"	21	Queen	3830
Packer		1"		Prenrose	4066
PBTD	8625	Pony	6', 4'	Grayburg	4346
TAC	8247	Pump		Bone Springs	6208
SN	8503	2 x 1 1/2 x 24' w/CW & BOC		1st BS Sand	7862
BP	8527			1st BS Sand (Base)	8081
				2nd BS Sand	8558

(12/99) Located holes from 4,754' - 5,204'; Set packer at 5,645 & Sqz 250 SXS LITE PREMIUM PLUS & 150 SXS CLASS C; Tag @ 4,836' drill out to CIBP

(11/99) Shot Sqz holes at 6,925'; Sqz 430 sks Class H cmt & tag at 6,210'

(10/99) Perfs: 8,432' - 56'; 2SPF 30 Holes

(10/99) Set CIBP @ 8,625'

(2/94) Frac Open hole (8,713' - 8,902')

(11/81) Perfs: 8,430' - 54' 48 Holes

(3/86) Perfs: 8,468' - 96'; 25holes

(10/87) Sqzd Perfs: 8,430'-96'

(10/99) Perfs: 8,432' - 36'; 8,446' - 56'; 2SPF 30 Holes

Acidz 250 gal w/ 10% Acetic; 7500 gal 20% DS-30

Acidz w/ 4400 gal of 15% SRA + 50 Ball Sealers


Acidz 6000 gal

MATADOR RESOURCES
 Young Deep Unit #8
 660' FNL & 860' FEL Sec 9 - 18S - 32E
 Lea County, NM
 API: 30-025-27535

Planned P&A WELLBORE SCHEMATIC

Spudded: 10/05/1981

Marker @ Surface



Casing Information						
	Hole Size	Casing Size	Type	Weight lb/ft	Joints	Depth Set
Surface	17 1/2	13 3/8	ST&C J-55	48	10	666
Intermediate	11	8 5/8	ST&C J-55	24 + 32	88	3600
Production	7 7/8	5 1/2	LT&C J-55	15 1/2 + 17	213	8,710
	DV Tool					
	Marker Jt.					
	Float Collar					

Cementing Record	
Surface	750 sx Cl "C" (Circulated)
Intermediate	1400 sx 65/35 "C" & 200 sx "C" (300sx back)
Production	350 sx 65/35 Cl "H"

Geologic Markers	
Rustler	1189
Yates	2697
Bowers	3575
Queen	3830
Prenrose	4066
Grayburg	4346
Bone Springs	6208
1st BS Sand	7862
1st BS Sand (Base)	8081
2nd BS Sand	8558

720': Perf & Sqz Class C cmt to surface on all strings (Est. ~200 sks)

2,750': Perf & Sqz 200 sks Class C cmt (Req. 2,000') (Salt section)

3,650': Perf & Sqz 50 sks Class C cmt (Req. 3,550') (Intermediate Shoe)

(12/99) Located holes from 4,754' - 5,204'; Set packer at 4,645' & Sqz 250 SXS LITE PREMIUM PLUS & 150 SXS CLASS C; Tag @ 4,836' drill out to CIBP

5,500': Spot a 125 sk Class C cmt balanced plug (Est. 4,233') (Old cement Squeeze)

6,258': Perf & Sqz 50 sks Class C cmt (Req. 6,150') (Bone Springs)

(11/99) Shot Sqz holes at 6,925'; Sqz 430 sks Class H cmt & tag at 6,210'

8,375': Set CIBP @ Spot 25 sks Class H cmt of top of CIBP; Load Casing & Pressure test to 500 psi for 30 minutes

(10/99) Perfs: 8,432' - 56'; 2SPF 30 Holes

(11/81) Perfs: 8,430' - 54' 48 Holes

Ac dz 250 gal w/ 10% Acetic; 7500 gal 20% DS-30

(10/99) Set CIBP @ 8,625'

(3/86) Perfs: 8,468' - 96'; 25holes

Ac dz w/ 4400 gal of 15% SRA + 50 Ball Sealers

(10/87) Sqzd Perfs: 8,430' - 96'

(10/99) Perfs: 8,432' - 36'; 8,446' - 56'; 2SPF 30 Hole Ac dz 6000 gal

(2/94) Frac Open hole (8,713' - 8,902')

11/87 Drilled 85' OH lateral
 KOP @ 8,713' North 1° East True
 85' 4-1/2" Lateral (8,713' - 8,798')

10/87 Drilled 180' OH lateral
 KOP @ 8,902' North 75° East True 180' 4-1/2" Lateral (8,902' - 9,082')

TD @ 9,082'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 227118

CONDITIONS

Operator: MATADOR PRODUCTION COMPANY One Lincoln Centre Dallas, TX 75240	OGRID: 228937
	Action Number: 227118
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
john.harrison	Accepted for record - NMOCD JRH 6/15/23. BLM approved P&A 6/9/23	6/15/2023