Sundry Print Repor

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Number: 28

Well Name: YOUNG DEEP UNIT Well Location: T18S / R32E / SEC 9 / County or Parish/State: LEA /

SESE /

Allottee or Tribe Name:

Type of Well: OIL WELL

Unit or CA Name: YOUNG DEEP UNIT

- DELAWAR

Unit or CA Number:

NMNM71067D

US Well Number: 3002531048 Well Status: Producing Oil Well **Operator: MATADOR**

PRODUCTION COMPANY

Accepted for Record Only

SUBJECT TO LIKE APPROVAL BY BLM



NMOCD 7/19/23

Notice of Intent

Lease Number: NMLC065580

Sundry ID: 2741017

Type of Submission: Notice of Intent Type of Action: Plug and Abandonment

Date Sundry Submitted: 07/14/2023 Time Sundry Submitted: 09:37

Date proposed operation will begin: 07/30/2023

Procedure Description: Matador is requesting to plug and abandon the Young Deep Unit #028, per the required BLM COAs, following the procedure below: Notify BLM 24 hrs before MIRU. Safety mtg, MIRU, check pressures, ND wellhead, NU & test BOPs, POOH w/ rods & tbg. RIH & set CIBP at 5,500'; Pressure test csg to 500 psi for 30 minutes; Circulate and displace hole w/ MLF. Spot 120 sks Class C cmt on top of CIBP; WOC & Tag (Isolate perforations, Delaware, San Andres, & Grayburg). Spot a 150 sk balanced plug of CI C cmt at 2,775'. (Yates & Salt) Perf @ 460' & Sqz Cl C cmt to surface on all strings. (Surface Shoe) Cut off wellhead and ensure cmt to surface on all csg strings. Install dry hole marker per BLM/NMOCD specifications. *Current and proposed wellbore diagrams attached **Mud laden fluid (MLF) mixed at 25sx/100 bbls water will be spotted between each plug.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Young_Deep_Unit__028_Planned_P_A_WBD_20230714093613.pdf

Young_Deep_Unit__028_Current_WBD_20230714093603.pdf

Page 1 of 2

eceived by OCD: 7/17/2023 12:52:38 PM Well Name: YOUNG DEEP UNIT

Well Location: T18S / R32E / SEC 9 /

SESE /

County or Parish/State: LEA/ 2 of

M

Well Number: 28

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMLC065580

US Well Number: 3002531048

Unit or CA Name: YOUNG DEEP UNIT

Well Status: Producing Oil Well

- DELAWAR

Unit or CA Number: NMNM71067D

ELAWAR

Operator: MATADOR

PRODUCTION COMPANY

Conditions of Approval

Specialist Review

Young_28_Revised_Plugging_Procedure_20230717072403.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: BRETT JENNINGS Signed on: JUL 14, 2023 09:37 AM

Name: MATADOR PRODUCTION COMPANY

Title: Regulatory Analyst

Street Address: 5400 LBJ FREEWAY, STE 1500

City: DALLAS State: TX

Phone: (972) 629-2160

Email address: BRETT.JENNINGS@MATADORRESOURCES.COM

Field

Representative Name:

Street Address:

City: State:

Phone:

Email address:

BLM Point of Contact

Signature: Zota Stevens

BLM POC Name: ZOTA M STEVENS

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345998 BLM POC Email Address: ZSTEVENS@BLM.GOV

Zip:

Disposition: Approved **Disposition Date:** 07/17/2023

Disposition: Approved

Page 2 of 2

Revised Plugging Procedure

Matador is requesting to plug and abandon the Young Deep Unit #28, per the required BLM COAs, following the procedure below:

- Notify BLM 24 hrs before MIRU.
- Safety mtg, MIRU, check pressures, ND wellhead, NU & test BOPs, POOH w/ rods & tbg.
- RIH & set CIBP at 5,500'; Pressure test csg to 500 psi for 30 minutes; Circulate and displace hole w/ MLF.
- Spot 120 sks Class C cmt on top of CIBP; WOC & Tag (Isolate perforations, Delaware, San Andres, & Grayburg).
- Spot a balanced plug of Cl C cmt at 2,775'-1220'. (Yates & T/Salt) WOC and TAG
- Perf @ 460' & Sqz Cl C cmt to surface on all strings. (Surface Shoe)
- Cut off wellhead and ensure cmt to surface on all csg strings.
- Install dry hole marker per BLM/NMOCD specifications.
- *Current and proposed wellbore diagrams attached
- **Mud laden fluid (MLF) mixed at 25sx/100 bbls water will be spotted between each plug.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:

From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any/all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip (across the slope and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech/Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Jose Martinez-Colon Environmental Protection Specialist 575-234-5951

Mark Mattozzi Environmental Protection Specialist 575-234-5713

Robert Duenas Environmental Protection Specialist 575-234-2229 Matador is requesting to plug and abandon the Young Deep Unit #028, per the required BLM COAs, following the procedure below:

Notify BLM 24 hrs before MIRU.

Safety mtg, MIRU, check pressures, ND wellhead, NU & test BOPs, POOH w/ rods & tbg.

RIH & set CIBP at 5,500'; Pressure test csg to 500 psi for 30 minutes; Circulate and displace hole w/ MLF.

Spot 120 sks Class C cmt on top of CIBP; WOC & Tag (Isolate perforations, Delaware, San Andres, & Grayburg).

Spot a 150 sk balanced plug of Cl C cmt at 2,775'. (Yates & Salt)

Perf @ 460' & Sqz Cl C cmt to surface on all strings. (Surface Shoe)

Cut off wellhead and ensure cmt to surface on all csg strings.


Install dry hole marker per BLM/NMOCD specifications.

*Current and proposed wellbore diagrams attached

^{**}Mud laden fluid (MLF) mixed at 25sx/100 bbls water will be spotted between each plug.

Received by OCD: 7/17/2023 12:52:38 PM

Young Deep Unit #028 330' FSL & 990' FEL Sec. 9-T18S-R32E Lea County, NM LC-065580 API: 30-025-31048 CURRENT WELLBORE SCHEMATIC



	Casing	Information				
	Hole Size	Casing Size	Туре	Weight (lb/ft)	Joints	Depth Set
Surface	12-1/4"	8-5/8"	J-55	32#	9	410
Production	7-7/8"	5-1/2"	J-55	17#	136	5,950
•					MKR Joint	4,504' - 4,532'

	Cementing Record		TOC	Date Run
Surface	3	00 sks CI C	Surface	3/9/1992
Production	1500 s	ks x 250 sks Cl H	Surface	3/23/1992

	Tubing Information	
Item	Notes	Depth
Tubing	(168) tubing	
TAC	Tubing Anchor	5,453
Tubing	(10) tubing	
SN	Seating Nipple	5,778
SND SCRN	Sand Screen	
ВР	ВР	5,802
PBTD	Plug Back Total Depth	5,903'

Geologic Markers				
Rustler	1,147			
Yates	2,713			
7 Rivers	3,101			
Bowers	3,560			
Queen	3,820			
Penrose	4,078			
Grayburg	4,401			
San Andres	4,911			
Delaware	5,143			
Brushy Canyon	5,371			

	Rod String Information	
Item	Notes	
Pony Rod	8' & 6' & 2' Pony Rods	
Rod	(60) 7/8" Rods	
Rod	(148) 3/4" Rods	
Rod	(21) 7/8" Rods	
Pump	2" x 1.25" x 24' W/BOC	


	Perforation Information	
Date	Formation	Depth
5/5/2000	Delaware perfs	(5,556'-5,571')
3/30/1992	Delaware perfs	(5,719'-5,732')

Received by OCD: 7/17/2023 12:52:38 PM Page 10 of 12

Young Deep Unit #028 330' FSL & 990' FEL Sec. 9-T18S-R32E Lea County, NM LC-065580 API: 30-025-31048


PLANNED P&A WELLBORE SCHEMATIC

Spudded:	3/9	/1992
----------	-----	-------



300 sks Cl C

1500 sks x 250 sks Cl H



Geologic	Geologic Markers				
Rustler	1,147				
Yates	2,713				
7 Rivers	3,101				
Bowers	3,560				
Queen	3,820				
Penrose	4,078				
Grayburg	4,401				
San Andres	4,911				
Delaware	5,143				
Brushy Canyon	5,371				

TOC

Surface

Surface

Date Run

3/9/1992

3/23/1992

5,500': Set CIBP; Load & Test Casing to 500 psi for 30 minutes; Spot 120 sks Class C cmt on CIBP; WOC & Tag (Req. 4,350' / Est. 4,284') (Isolate Perfs, Delaware, & Grayburg)

	Perioration information	
Date	Formation	Depth
5/5/2000	Delaware perfs	(5,556'-5,571')
3/30/1992	Delaware perfs	(5,719'-5,732')

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 240992

COMMENTS

Operator:	OGRID:
MATADOR PRODUCTION COMPANY	228937
One Lincoln Centre	Action Number:
Dallas, TX 75240	240992
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartine	z DATA ENTRY PM	7/20/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 240992

CONDITIONS

Operator:	OGRID:
MATADOR PRODUCTION COMPANY	228937
One Lincoln Centre	Action Number:
Dallas, TX 75240	240992
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	Like approval from BLM	7/19/2023