Received by OCD: 8/7/2023 7:55:19 AM

cectrea by 0 eD. o						1 480 1 0	
Form 3160-5 (June 2019)					FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2021 5. Lease Serial No.		
					6. If Indian, Allottee or Tribe Name		
			to drill or to re-enter an PD) for such proposals.				
	SUBMIT IN	TRIPLICATE - Other instru	uctions on page 2		7. If Unit of CA/Agree	ment, Name and/or No.	
1. Type of Well					NMNM78407E		
Oil Well	x Gas V	Vell Other			8. Well Name and No. Rosa Unit 165D		
2. Name of Operator				9. API Well No.			
LOGOS Operating, LLC					30-039-30690		
3a. Address 2010 Afton Place, Farmington NM 87401			3b. Phone No. <i>(include area code)</i> 505-278-8720		10. Field and Pool or Exploratory Area		
					Blanco Mesaverde / Basin Dakota / Basin Mancos		
4. Location of Well (Fo	otage, Sec., T., F	R.,M., or Survey Description)			11. Country or Parish,	State	
Unit C, Section 25 T	31N R06W 12	80' FNL & 1635' FWL			Rio Arriba, NM		
	12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOTI	CE, REPORT OR OTH	ER DATA	
TYPE OF SUBM	IISSION		ТҮР	PE OF AC	ΓΙΟΝ		
x Notice of Intent		Acidize	Deepen	=	uction (Start/Resume)	Water Shut-Off	
		Alter Casing Hydraulic Fracturing Rec		amation	Well Integrity		
Subsequent Report		Casing Repair New Construct		Reco	mplete	x Other Wellbore Isolation/	
		Change Plans	Plug and Abandon Tem		porarily Abandon	Pressure Monitoring	
Final Abandonm	ent Notice	Convert to Injection	Plug Back	Wate	er Disposal		
the proposal is to de Attach the Bond un following completion	eepen directiona der which the w on of the involv npleted. Final A	ally or recomplete horizontall work will be performed or pro- ed operations. If the operation abandonment Notices must be	rtinent details, including estimated ly, give subsurface locations and m ovide the Bond No. on file with BL n results in a multiple completion of e filed only after all requirements,	easured an M/BIA. R or recomp	nd true vertical depths of equired subsequent repo- letion in a new interval,	orts must be filed within 30 days a Form 3160-4 must be filed once	

LOGOS Operating request to conduct a wellbore isolation for subject well. The Rosa Unit 165D is at risk of catastrophic failure from the nearby Pad 29 completions. In order to preserve wellbore integrity and protect the remaining reserves of the well, it is recommended to isolate the wellbore and actively monitor pressure via downhole gauge for a total well observation period of 9-12 months. See attached procedure.

14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/Typed</i>)					
Etta Trujillo	Title	Regulatory Specialist			
Signature Eta Trujillo	Date	8/2/2023			
THE SPACE FOR FEDERAL OR STATE OFICE USE					
Approved by					
	Tit	tle	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		ffice			
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					

(Instructions on page 2)

Released to Imaging: 8/11/2023 9:31:41 AM

Page	1 oj	f 7
------	------	-----



Well Name	Well Number	US Well Number	Lease Number	Case Number	Operator
ROSA UNIT	165D	300393069000C3	NMSF078766	NMNM78407A	LOGOS
ROSA UNIT	165D	300393069000C2	NMSF078766	NMNM78407E	LOGOS
ROSA UNIT	165D	300393069000C1	NMSF078766	NMNM78407B	LOGOS

Notice of Intent

Sundry ID: 2744188

Type of Submission: Notice of Intent

Date Sundry Submitted: 08/02/2023

Date proposed operation will begin: 08/02/2023

Type of Action: Other

Time Sundry Submitted: 01:16

Procedure Description: LOGOS Operating request to conduct a wellbore isolation for subject well. The Rosa Unit 165D is at risk of catastrophic failure from the nearby Pad 29 completions. In order to preserve wellbore integrity and protect the remaining reserves of the well, it is recommended to isolate the wellbore and actively monitor pressure via downhole gauge for a total well observation period of 9-12 months. See attached procedure.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

3160_5_Rosa_Unit_165D_NOI_Wellbore_Isolation_Pressure_Monitoring_20230802_20230802131518.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: ETTA TRUJILLO

Signed on: AUG 02, 2023 01:16 PM

Name: LOGOS OPERATING LLC

Title: Regulatory Specialist

Street Address: 2010 AFTON PLACE

City: Farmington

Phone: (505) 324-4154

Email address: ETRUJILLO@LOGOSRESOURCESLLC.COM

State:

State: NM

Field

Representative Name: Street Address: City: Phone: Email address:

Zip:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK BLM POC Phone: 5055647742 Disposition: Approved Signature: Kenneth Rennick BLM POC Title: Petroleum Engineer BLM POC Email Address: krennick@blm.gov Disposition Date: 08/03/2023



WELLBORE ISOLATION/PRESSURE MONITORING-NMOCD (2023)

Rosa Unit 165D

30-039-30690 1280' FNL & 1635' FWL Section 25, T31N, R06W Rio Arriba, New Mexico <u>LAT</u>: 36.8743362° N <u>LONG</u>: -107.417572° W Mesaverde/Mancos/Dakota

PROJECT OBJECTIVE:


The Rosa Unit 165D is at risk of catastrophic failure from the nearby Pad 29 completions. In order to preserve wellbore integrity and protect the remaining reserves of the well, it is recommended to isolate the wellbore and actively monitor pressure via downhole gauge for a total well observation period of 9-12 months.

WORKOVER PROCEDURE:

- 1. Hold safety meeting. MIRU workover rig. Place fire and safety equipment in strategic locations. Comply with all LOGOS, BLM, and NMOCD rules and regulations.
- 2. Lay flow lines. Check and record casing and tubing pressures. Sell pressure down to line. Kill well if necessary.
- 3. Nipple down wellhead and nipple up BOP.
- 4. TOOH and stand back tubing.
- 5. Set bridge plug within 50' of the Dakota perforations.
- 6. TIH and set cement retainer at ~6910'.
- 7. RIH with pressure gauge and tubing and sting into retainer.
- 8. Leave well shut in during offset completions and post completions for pressure monitoring.
- 9. Once offset completions are complete and adequate pressure monitoring data has been collected, TOOH with tubing and laydown pressure gauge.
- 10. Trip in hole and mill out cement retainer and bridge plug.
- 11. Run 2-3/8" tubing back in hole and return well to production.




Wellbore Schematic





Proposed Wellbore Schematic



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:	
LOGOS OPERATING, LLC	289408	
2010 Afton Place	Action Number:	
Farmington, NM 87401	248733	
	Action Type:	
	[C-103] NOI General Sundry (C-103X)	

CONDITIONS

Created By		Condition Date
dmcclure	None	8/11/2023

Page 7 of 7

.

Action 248733