Sundry Pr	Int Rep 10/20/20
County or Parish/ JUAN / NM	State: SAN
Allottee or Tribe I	Name:
Unit or CA Numbe	ər:
Operator: SIMCO	E LLC
Ор	erator: SIMCO

Notice of Intent

Sundry ID: 2757230 Type of Submission: Notice of Intent Date Sundry Submitted: 10/19/2023 Date proposed operation will begin: 11/14/2023

Type of Action: Temporary Abandonment Time Sundry Submitted: 12:21

Procedure Description:

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Kernaghan_B_004_WBD_TA_20231019122134.pdf Kernaghan_B_004_WBD_20231019122129.pdf Kernaghan_B_004_TA_Procedure_20231019122123.pdf

Received by OCD: Well Name: Ki	10/26/2023 11:02:21 AM ERNAGHAN B	Well Location: T31N / R8W / SEC 30 / SENE / 36.871735 / -107.709549	County or Parish/State: SAN	12
Well Number:	4	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:	
Lease Numbe	r: NMSF078387A	Unit or CA Name:	Unit or CA Number:	
US Well Numb	ber: 3004510338	Well Status: Gas Well Shut In	Operator: SIMCOE LLC	

Conditions of Approval

Specialist Review

Kernaghan_B_4_ID_2757230_TA_COAs_MHK_10.20.2023_20231020084122.pdf

State: CO

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: CHRISTY KOST

Name: SIMCOE LLC

Title: Permitting Agent

Street Address: 1199 MAIN AVE STE 101

City: DURANGO

Phone: (719) 251-7733

Email address: CHRISTY.KOST@IKAVENERGY.COM

Field

Representative Name: Street Address:

State:

Email address:

City:

Phone:


BLM Point of Contact

BLM POC Name: MATTHEW H KADE BLM POC Phone: 5055647736 Disposition: Approved Signature: Matthew Kade BLM POC Title: Petroleum Engineer BLM POC Email Address: MKADE@BLM.GOV


Zip:

Signed on: OCT 19, 2023 12:21 PM

Disposition Date: 10/20/2023



Kernaghan B #4 (H) Sec 30, T31N, R8W San Juan County 30-045-10338



Procedure - Temporary Abandonment Kernaghan B #4 (H) Sec 30, T31N, R8W San Juan County

30-045-10338

MIRU service unit.

Pull rodstring/pump/tubing if present in well.

RIH cast iron bridge plug and set at 5150'

Top off casing with 2% KCl w/biocide and corrosion inhibitor

Pressure test casing to 500 psi for 30 min. Pressure shall not decrease more than 50 psi over the 30 min period

Open casing valves to check for flow or pressure change.

Test shall be recorded using a chart recorder with a maximum two hour clock and 1000 pound spring, calibrated within six months prior to MIT of casing

Submit chart, C-103, and wellbore diagram showing well details and plug set depth.

Air gap and blind flange production flow lines.

After a period not to exceed 5 years after the temporary abandoment has been completed, a workover rig will remove the cast iron bridge plug and monitor pressure buildup of the well for a two week period to determine if the well will return to a production status. If the decision is made to not produce the well, a request for plugging and abandonment will be submitted.

If the decision is made to produce the well, all necessary flow and production lines will be reinstalled for a flow ready status up to and including any removed flowmeters and well ties. Surface facilitlies will be placed for production puroposes.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington District Office 6251 College Boulevard, Suite A Farmington, New Mexico 87402 <u>http://www.blm.gov/nm</u>



October 20, 2023

CONDITIONS OF APPROVAL

Sundry Notice of Intent ID # 2757230 Proposed Work to Temporary Abandonment

Operator:	Simcoe LLC
Lease:	NMSF 078387A
Agreement:	
Well(s):	Kernaghan B 4, API # 30-045-10338
Location:	SENE Sec 30 T31N R8W (San Juan County, NM)

The request to temporarily abandon the above well is accepted with the following conditions of approval:

- 1. After work is completed, send in Sundry Notice Subsequent Report detailing actual work completed with exact dates (month, day, year). And the updated wellbore schematic. The report must be submitted within 30 days after work is completed.
- 2. Also, after work is completed, send in a Sundry Notice Notice of Intent requesting temporary abandonment status. Note approval is based on the discretion of this agency. This request must be submitted within 30 days after work is completed.

Include in the Notice of Intent the following:

- a. Proposed exact expiration date (month, day, year). Cannot be later than 12-months from date of submission. The date can also be when the current TA approval will expire.
- b. Confirmation of other production on lease, or agreement.
- c. Plans for the well.
- 3. This agency reserves the right to modify or rescind approval. A plug or produce order may still be issued at the discretion of the authorized officer.
- 4. The lease is currently held by production from other wells. Should production from the lease cease, the BLM may require this well be returned to production or P&A, regardless of the amount of time the TA status is still approved for.

.

For questions concerning this matter, please contact Matthew Kade, Petroleum Engineer at the BLM Farmington Field Office, at (505) 564-7736 or mkade@blm.gov.

Office	State of New Mex	ico		Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natura	ll Resources	WELL API NO. 3	Revised July 18, 2013 0-045-22023
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION I	DIVISION		
<u>District III</u> – (505) 334-6178	1220 South St. Franc		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 875		6. State Oil & Gas I	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sunta 1 C, 1401 075	05		Lease INO.
87505			NM-012711	
(DO NOT USE THIS FORM FOR PROPOSALS T DIFFERENT RESERVOIR. USE "APPLICATION			7. Lease Name or U Lawson	nit Agreement Name
PROPOSALS.) 1. Type of Well: Oil Well Gas W	Vell 🖌 Other		8. Well Number #	1A
2. Name of Operator SIMCOE LLC			9. OGRID Number	
3. Address of Operator			10. Pool name or W	ïldcat
	e, Suite 101, Durango, CO 813	01	Blanco-Mesaverd	e
4. Well Location				
Unit LetterE:1835fe	et from theNorth line	e and1060	feet from theWes	tline
Section 10 Township	30N Range 8W	NMPM	San Juan Cou	
	Elevation (<i>Show whether DR, K</i> 6,300', GL	RKB, RT, GR, etc.)	
12. Check Appro NOTICE OF INTEN	priate Box to Indicate Nat		Report or Other D	
		REMEDIAL WOR	· _	
		COMMENCE DRI	LLING OPNS.	AND A
		CASING/CEMEN		_
	_		_	
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
 Describe proposed or completed or of starting any proposed work). S proposed completion or recompleted 	EE RULE 19.15.7.14 NMAC.	rtinent details, and For Multiple Co	d give pertinent dates, mpletions: Attach wel	including estimated date lbore diagram of
1				
AIRU service unit. Pull rodstring/pump/tubing orrosion inhibitor. Pressure test casing to 500 p heck for flow or pressure change. Test shall be ix months prior to MIT of casing. Submit chart low lines. After a period not to exceed 5 years a ind monitor pressure buildup of the well for a to produce the well, a request for plugging and aba ines will be reinstalled for a flow ready status up	psi for 30 min. Pressure shall not de recorded using a chart recorder wi c, C-103, and wellbore diagram show after the temporary abandoment ha wo week period to determine if the ndonment will be submitted. If the	ecrease more than 5 th a maximum two wing well details and s been completed, a well will return to a decision is made to	0 psi over the 30 min per hour clock and 1000 pou d plug set depth. Air gap workover rig will remove production status. If the produce the well, all nee	iod. Open casing valves to nd spring, calibrated within and blind flange production e the cast iron bridge plug decision is made to not ressary flow and production
MIRU service unit. Pull rodstring/pump/tubing corrosion inhibitor. Pressure test casing to 500 p check for flow or pressure change. Test shall be ix months prior to MIT of casing. Submit chart low lines. After a period not to exceed 5 years a und monitor pressure buildup of the well for a two produce the well, a request for plugging and aba ines will be reinstalled for a flow ready status up puroposes.	psi for 30 min. Pressure shall not de recorded using a chart recorder with c, C-103, and wellbore diagram show after the temporary abandoment ha wo week period to determine if the indonment will be submitted. If the p to and including any removed flo	ecrease more than 5 th a maximum two wing well details and s been completed, a well will return to a decision is made to wmeters and well tion	i0 psi over the 30 min per hour clock and 1000 pou d plug set depth. Air gap a workover rig will remove production status. If the produce the well, all nec es. Surface facilitlies will	tiod. Open casing valves to nd spring, calibrated within and blind flange production the cast iron bridge plug decision is made to not ressary flow and production
MIRU service unit. Pull rodstring/pump/tubing corrosion inhibitor. Pressure test casing to 500 p check for flow or pressure change. Test shall be ix months prior to MIT of casing. Submit chart low lines. After a period not to exceed 5 years a and monitor pressure buildup of the well for a two produce the well, a request for plugging and aba ines will be reinstalled for a flow ready status up puroposes.	psi for 30 min. Pressure shall not de recorded using a chart recorder with c, C-103, and wellbore diagram show after the temporary abandoment ha wo week period to determine if the indonment will be submitted. If the p to and including any removed flow Rig Release Date	ecrease more than 5 th a maximum two i wing well details and s been completed, a well will return to a decision is made to wmeters and well time : t of my knowledg	i0 psi over the 30 min per hour clock and 1000 pou d plug set depth. Air gap a workover rig will remove production status. If the produce the well, all nec es. Surface facilitlies will e and belief.	tiod. Open casing valves to nd spring, calibrated within and blind flange production e the cast iron bridge plug decision is made to not ressary flow and production be placed for production
MIRU service unit. Pull rodstring/pump/tubing corrosion inhibitor. Pressure test casing to 500 peheck for flow or pressure change. Test shall be the chart of the prior to MIT of casing. Submit chart low lines. After a period not to exceed 5 years a und monitor pressure buildup of the well for a two produce the well, a request for plugging and aba ines will be reinstalled for a flow ready status up puroposes.	psi for 30 min. Pressure shall not de recorded using a chart recorder with c, C-103, and wellbore diagram show after the temporary abandoment ha wo week period to determine if the indonment will be submitted. If the p to and including any removed flow Rig Release Date	ecrease more than 5 th a maximum two i wing well details and s been completed, a well will return to a decision is made to wmeters and well time : t of my knowledg	i0 psi over the 30 min per hour clock and 1000 pou d plug set depth. Air gap a workover rig will remove production status. If the produce the well, all nec es. Surface facilitlies will e and belief.	tiod. Open casing valves to nd spring, calibrated within and blind flange production e the cast iron bridge plug decision is made to not ressary flow and production be placed for production
AIRU service unit. Pull rodstring/pump/tubing corrosion inhibitor. Pressure test casing to 500 p check for flow or pressure change. Test shall be ix months prior to MIT of casing. Submit chart low lines. After a period not to exceed 5 years a and monitor pressure buildup of the well for a two produce the well, a request for plugging and aba ines will be reinstalled for a flow ready status up puroposes.	psi for 30 min. Pressure shall not de recorded using a chart recorder wi c, C-103, and wellbore diagram show after the temporary abandoment ha wo week period to determine if the indonment will be submitted. If the p to and including any removed flow Rig Release Date is true and complete to the best Strue	ecrease more than 5 th a maximum two i wing well details and s been completed, a well will return to a decision is made to wmeters and well time : t of my knowledg	i0 psi over the 30 min per hour clock and 1000 pou d plug set depth. Air gap a workover rig will remove production status. If the produce the well, all nec es. Surface facilitlies will e and belief.	 Copen casing valves to nd spring, calibrated within and blind flange production is the cast iron bridge plug decision is made to not ressary flow and production be placed for production 10/26/23

•

Procedure - Temporary Abandonment Lawson #1A (E) Sec 10, T30N, R8W San Juan County 30-045-22023

MIRU service unit.

Pull rodstring/pump/tubing if present in well.

RIH cast iron bridge plug and set at 2750'

Top off casing with 2% KCl w/biocide and corrosion inhibitor

Pressure test casing to 500 psi for 30 min. Pressure shall not decrease more than 50 psi over the 30 min period

Open casing valves to check for flow or pressure change.

Test shall be recorded using a chart recorder with a maximum two hour clock and 1000 pound spring, calibrated within six months prior to MIT of casing


Submit chart, C-103, and wellbore diagram showing well details and plug set depth.


Air gap and blind flange production flow lines.

After a period not to exceed 5 years after the temporary abandoment has been completed, a workover rig will remove the cast iron bridge plug and monitor pressure buildup of the well for a two week period to determine if the well will return to a production status. If the decision is made to not produce the well, a request for plugging and abandonment will be submitted.

If the decision is made to produce the well, all necessary flow and production lines will be reinstalled for a flow ready status up to and including any removed flowmeters and well ties. Surface facilitlies will be placed for production puroposes.

Lawson #1A (E) Sec 10, T30N, R8W San Juan County 30-045-22023





District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 279657

CONDITIONS

Operator:	OGRID:
SIMCOE LLC	329736
1199 Main Ave., Suite 101	Action Number:
Durango, CO 81301	279657
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

CON	NDITIONS		
Cre	eated By	Condition	Condition Date
m	kuehling	schematics required to have formation tops - Notify NMOCD 24 hours prior to testing - pressure during testing cannot drop below 500 psi on ta well - bradenhead test required prior to mit day of mit	10/26/2023