Completed Weby Po Appropriate Historia 34 AM	State of New Mexico	Form C-103 <sup>1</sup>	
Office District I – (575) 393-6161 Energy,	Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	ONSERVATION DIVISION	30-025-05541	
511 5.1 list 5t., Artesia, 14M 66210	220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Salita Fe, INIVI 67303	6. State Oil & Gas Lease No.	
87505		19520	
SUNDRY NOTICES AND RE	PORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		North Hobbs G/SA Unit	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	Other	8. Well Number 311	
Name of Operator     Occidental Permian LTD		9. OGRID Number 157984	
3. Address of Operator		10. Pool name or Wildcat	
P.O. Box 4294 Houston, TX 77210-4294		HOBBS; GRAYBURG-SAN ANDRES	
4. Well Location		· ·	
	t from the NORTH line and	1650 feet from the EAST line	
	wnship 18S Range 38E	NMPM County LEA	
	n (Show whether DR, RKB, RT, GR, etc.	3	
3651' (GR)	ii (Show whether DR, RRD, RT, GR, etc.	.,	
3031 (611)			
12. Check Appropriate	Box to Indicate Nature of Notice,	Report or Other Data	
NOTICE OF INTENTION	TO:	SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND	<u> </u>		
TEMPORARILY ABANDON CHANGE PL		ALTERING CASING	
PULL OR ALTER CASING  MULTIPLE (		<del></del>	
DOWNHOLE COMMINGLE	CASING/CEIVIEN	11 30B	
CLOSED-LOOP SYSTEM			
OTHER:	□ OTHER:	П	
	_	nd give pertinent dates, including estimated date	
of starting any proposed work). SEE RUI			
proposed completion or recompletion.	1	1	
See procedure attached.			
oce procedure actabilea.			
	1		
Spud Date:	Rig Release Date:		
I hereby certify that the information above is true a	nd complete to the best of my knowleds	ge and belief.	
	-F Sest of my monitor	p- ·· · · ·	
$\mathcal{D}$ . $\mathcal{M}$ 11			
SIGNATURE Roni Mathew	TITLE Regulatory Advisor	DATE <u>02/07/2024</u>	
Type or print name Roni Mathew		<u> </u>	
T 0 1	E-mail address: <u>roni_mathew(</u>	@oxy.com PHONE: (713) 215-7827	
For State Use Only	E-mail address: roni_mathew(	@oxy.com PHONE: (713) 215-7827	
-		Λ	
APPROVED BY: Kerry Forther Conditions of Approval (if any):	E-mail address: roni_mathew@		

Well: NHSAU 311-36

Job Summary: Well Enhancement/Deepened

API: 30 - 25-05541

Job Dates: 07/09/2022 - 07/29/2022

7/9/22: Move Equip from NHU 33-524- LO/TO- Attempt to spot in rig, no able due mud hole by wellhead-Attempt to spot rig w/ winch truck, NO luck- SION.

7/11/22: Check psi- Tbg 100psi, Csg 150psi- Spot Rig- RUPU- Unhang well- LT to 1000 psi, Good- Unseat Pump-Pooh LD 155x3/4 rods, 6x3/4 guided, 4x1 1/2 sinker bars & pump- Kill well w/ 130 bbls Fw- NDWH- NU Bop-Release Tac- SION.

7/12/22: Check psi- Tbg & Csg Opsi- Kill well w/ 120 bbls Fw- Pooh LD 131jts 2 3/8 Prod Tbg- PU Rih w/ 4 3/4 shoe, 2 jts 4.5 Wp, PU 127 jts 2 7/8 Prod Tbg- NU stripper head- Broke Cir w/ 150 bbls Fw- SION.

7/13/22: Held TGSM, tbg had 0psi, csg had 0psi, rups, caught circ, washed over fish from 4224' down to 4278', plugged off shoe, rdps, nd stripperhead, pooh w/128jts, laid down 2jts of 4.5"washpipe, shoe, didn't have fish, secured well in, and sion.

7/14/22: Held TGSM, csg had 100psi, killed well, rih w/4.5"box tap, 129jts tagging top of fish 4233', worked box tap, pooh w/129jts, but had nothing inside box tap. Ran back in w/4.5" box tap, 129jts, worked box tap again using tbg tongs, pooh w/129jts, box tap w/nothing inside box tap, rih w/4.5" shoe, junk basket, 2jts of 4.5"washpipe, 128jts, worked shoe trying to swallow fish, pooh w/128jts, 2jts of 4.5" washpipe, 4-3/4" shoe w/no fish inside, secured well in, and sion.

7/15/22: Held TGSM, csg had 80psi, killed well, rih w/4-3/4"shoe, Tdog, 2jts of 4.5" washpipe, 128jts, nu stripperhead, washed over from 4248' down to 4281' then we got stuck, and worked tbg trying to get free but was unsuccessful. Ruwl, ran free point on tbg, cut tbg @4191', rdwl, pooh w/128jts, 1/2jts, and sion.

7/16/22: Check psi- Tbg & Csg 100psi- Kill well w/ 100 bbls Brn- Rih w/ 4 11/16 OS, BS, Jars, 6x3 1/2 Dc & 122 jts 2 7/8 Tbg- Tag & latch on fish @4191'- Jar on fish 4 times something came free- Pooh w/ fishing tools-Found Pin break on 4th DC(left 2 DC, Jars, BS, OS) Rih w/ 4 11/16 OS( 3 1/2 grapple) 126 jts 2 7/8 Tbg- Attempt Latch on Fish @4191'- It would latch, PU 4 points & slip off-SION.

7/18/22: Held TGSM, tbg had 100psi, csg had 100psi, killed well, pooh w/124jts, 4-11/16"overshot, added extension, rih w/overshot, 124jts latched onto fish @4108', jarred on fish which came free on 2nd try, pooh w/125jts, 4-11/16' overshot, 2-3.5" dcs, 3.3/4" jars, 3.3/4" bumper sub, 4.11/16" overshot w/half a jt of 2.7/8" tbg, 2 jts of 4.5" wash pipe, 4.3/4" shoe recovering 1-1/2jts of 2-3/8", and 2 3/8" bull plug inside the washpipe. Rih w/4-3/4"bit, 4-3/4" stringmill, 4 3.5"dc's, 127jts, tagging @4281', nu stripperhead, rups, caught circ, drilled new formation from 4281' down to 4310', circ well clean, rdps, pooh above perfs, and sion.

7/19/22: Crew attended Rod School Training, drove back to Hobbs, held tgsm, tbg had Opsi, csg had Opsi, rups, cont drilling new formation from 4310' down to 4375', circ well clean, rdps, pooh above openhole, and sion.


7/20/22: Held TGSM, tbg ha d0psi, csg had 0psi, rih w/8jts, rups, caught circulation, cont drilling new OH from 4375' down to new TD@4411', circ well clean, rdps, and nd stripperhead. Pooh w/131jts, laid down 4dc's, 4-3/4" stringmill, 4-3/4"bit, ruwl, ran CNL in the open hole from 4411' up to 4225', sent log to engineer, rdwl, and sion.

7/21/22: Held TGSM, csg had 80psi, killed well, rih w/2-7/8"smart nozzle, 135jts, ru Petroplex acid truck, acid washed OH from 4411' up to 4276' w/ 5000gals of acid 15%HCL NEFE, flushed tbg, rd acid truck, nd stripperhead, pooh w/135jts, and smart nozzle Dodd tool. Rih 5.5"rbp, 122jts, set rbp@4004', circ well w/120bbls, l&t csg to 600psi, pooh laying down 40jts, and sion.

7/22/2022: HTGSM: tbg/csg had 0 psi, laid down 52 2 7/8" jts on float, Rih w 5 ½" RBP set it @ 998' w 30 2 7/8" jts, laid down 30 jts, dumped sand on top of RBP, NDBOP, NU cap flage, RDPU, cleaned location.

7/28/2022: HTGSM: Moved rig & equipment from NHSAU 25-341 to NHSAU 36-311, RUPU, pressured tested wellhead to 600 psi held good, NDWH, NUBOP, Rih w r/h, latched on to rbp and pooh w rbp, Rih w r/h, 122 2 7/8" jts, latched on to rbp @ 4004' and released it, pooh w 122 2 7/8" jts and laid down rbp, performed bope closing drill, SION.

7/29/2022: HTGSM: csg had 200 psi, pumped 110 bbls of 10# brine down csg, R/u line spooler, picked up 6 2 3/8" fiber glass jts w Ct line, picked up/assembled Summit esp equipment, Rih w esp, 6' sub, 2 7/8" SN, 122 2 7/8" new L-80 jts, 6' sub w esp hanger, R/d spooler, performed PFT cable penetrator, n/d Bop, landed tbg hanger only, RDPU, cleaned location. SION.



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 312283

## **CONDITIONS**

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	312283
	Action Type:
	[C-103] Sub. Workover (C-103R)

## CONDITIONS

Created By		Condition Date
kfortner	None	2/7/2024