
Sitted by Opy Po Appropriate Bistrict 1 PM Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 Energy, 1625 N. French Dr., Hobbs, NM 88240	, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	ONSERVATION DIVISION	30-025-24272 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178	<u>III</u> – (505) 334-6178 1220 South St. Francis Dr.	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	•	2. State S.I. & San Deale 110.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Injection		7. Lease Name or Unit Agreement Name Arrowhead Grayburg Unit
		8. Well Number 160
Name of Operator Empire Petroleum Corporation		9. OGRID Number 330679
3. Address of Operator		10. Pool name or Wildcat
2200 S. Utica Place, Suite 150, Tulsa, Oklahoma	74114	Arrowhead; Grayburg
4. Well Location	Const. North Process	1020 Cat Care the Foot Pro
-	from the <u>North</u> line and	
	wiship 22S Range 36E	NMPM Lea County
11. Elevation	on (Show whether DR, RKB, RT, GR, etc.	:.)
NOTICE OF INTENTION OF PERFORM REMEDIAL WORK ☐ PLUG AND OF TEMPORARILY ABANDON ☐ CHANGE PUPULL OR ALTER CASING ☐ MULTIPLE OF TEMPORARILY ABANDON ☐ MULTIPLE OF TEMPORARILY ABAN	ABANDON REMEDIAL WORL LANS COMMENCE DR	RILLING OPNS. P AND A
CLOSED-LOOP SYSTEM DTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues	LE 19.15.7.14 NMAC. For Multiple Co	Condition of Approval: notify OCD Hobbs office 24 hours
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code.	completions: Attach a wellbore diagram of Condition of Approval: notify
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code.	Condition of Approval: notify OCD Hobbs office 24 hours
CLOSED-LOOP SYSTEM There: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code. 3. g and set @ 3618'. side.	Condition of Approval: notify OCD Hobbs office 24 hours
CLOSED-LOOP SYSTEM There: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code. 3. g and set @ 3618'. side.	Condition of Approval: notify OCD Hobbs office 24 hours
CLOSED-LOOP SYSTEM There: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code. 3. g and set @ 3618'. side.	Condition of Approval: notify OCD Hobbs office 24 hours
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO. 11. RTI.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Const. S. grand set @ 3618'. side. MOCD.	Condition of Approval: notify OCD Hobbs office 24 hours
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO. 11. RTI.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code. 3. g and set @ 3618'. side.	Condition of Approval: notify OCD Hobbs office 24 hours
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO. 11. RTI.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Const. S. grand set @ 3618'. side. MOCD. Rig Release Date:	Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO. 11. RTI.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Const. S. grand set @ 3618'. side. MOCD. Rig Release Date:	Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO. 11. RTI.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Const. S. grand set @ 3618'. side. MOCD. Rig Release Date:	Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart ge and belief.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO. 11. RTI. pud Date: hereby certify that the information above is true a lignature. Mathan Sandel ype or print name Nathan Sandel	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code. S. g and set @ 3618'. side. MOCD. Rig Release Date: Indicate the best of my knowled. TITLE Production Engine.	Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart ge and belief.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE RUI proposed completion or recompletion. 1. MIRU WOR. 2. Release packer and scan tubing OOH 3. RIH with RBP and set @ 3618'. 4. Pressure test casing. 5. Remediate any casing integrity issues 6. RIH with redressed packer and tubing 7. Circulate packer fluid down the backs 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to N. 10. RDMO. 11. RTI. pud Date: hereby certify that the information above is true a light and submit and submit results to N. 10. RDMO.	ns. (Clearly state all pertinent details, and LE 19.15.7.14 NMAC. For Multiple Code. S. grand set @ 3618'. side. MOCD. Rig Release Date: TITLE Production Engine E-mail address: nsandel@empire.	Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart ge and belief. er DATE 04/04/2024 epetrocorp.com PHONE: 918-404-4202

Current and Proposed WBD



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 330225

CONDITIONS

Operator:	OGRID:
Empire New Mexico LLC	330679
2200 S. Utica Place	Action Number:
Tulsa, OK 74114	330225
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
kfortner	Run PWOT MIT/BHT	4/8/2024