(June 2019) DEPARTMENT OF THE INTERIOR				FORM APPROVED Page 1 o OMB No. 1004-0137 Expires: October 31, 2021	
BUREAU OF LAND MANAGEMENT			5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					
SUBMIT IN	TRIPLICATE - Other instruct	ions on page 2	7. If Unit of CA/Agr	eement, Name and/or No.	
1. Type of Well			9 Well Mana and M	-	
✓ Oil Well Gas Well Other			8. well Name and N	^{0.} Paye Federal No. 6	
2. Name of Operator Bureau of Land Management formerly Cano Petro of NM, Inc			9. API Well No. 30-0		
3a. Address 3b. Phone No. (include area code)				10. Field and Pool or Exploratory Area Tom Tom: San Andres	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Paris		
	, Section 4, T08S, R31E		Chaves, New Me		
12. CHE	CK THE APPROPRIATE BOX	(ES) TO INDICATE NATUR	E OF NOTICE, REPORT OR OT	THER DATA	
TYPE OF SUBMISSION		TY	PE OF ACTION		
✓ Notice of Intent	Acidize	Deepen	Production (Start/Resume) Water Shut-Off	
Le rouce of miten.	Alter Casing .	Hydraulic Fracturing	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon Water Disposal		
the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.)				3 100-4 must be filed once testing has been the operator has detennined that the site	
completion of the involved operati completed. Final Abandonment No	otices must be filed only after all				
completion of the involved operati completed. Final Abandonment No is ready for final inspection.)	otices must be filed only after all	l requirements, including recla	mation, have been completed and		
completion of the involved operatic completed. Final Abandonment Not is ready for final inspection.)	SEE AT	TACHMENTS	mation, have been completed and	the operator has detennined that the site	
completion of the involved operatic completed. Final Abandonment Not is ready for final inspection.)	SEE AT	I requirements, including recla ITACHMENTS General ed/Typed)	mation, have been completed and	the operator has detennined that the site	
completion of the involved operatic completed. Final Abandonment Not is ready for final inspection.)	SEE AT	TTACHMENTS	mation, have been completed and SAPUla	the operator has detennined that the site	
completion of the involved operatic completed. Final Abandonment Not is ready for final inspection.)	SEE AT	TTACHMENTS	mation, have been completed and SAPUla	the operator has detennined that the site	
completion of the involved operatic completed. Final Abandonment Not is ready for final inspection.)	SEE AT SEE AT NANGES s true and correct. Name (Printe THE SPACE I ched Approval of this notice do equipable title to those rights in	TTACHMENTS	mation, have been completed and SAPUla	the operator has detennined that the site	
completion of the involved operatic completed. Final Abandonment Not is ready for final inspection.)	SEE AT SEE AT MANS & s true and correct. Name (Printe THE SPACE I ched Approval of this notice doo ceputable titler to these rights in mouch operations thereon. 43 U.S.C Section 1212, make it j	TACHMENTS TACHMENTS TACHMENTS Ed/Typed) Title Date TOR FEDERAL OR S Constraint or the subject lease Office Confice Con	mation, have been completed and SAPU(A) TATE OFICE USE	the operator has detennined that the site	

.


Cano Petro of NM Inc Paye Federal # 6 30-005-20494 UL – F, Sec 4, T8S, R31E 1980' FNL & 1980' FWL

8 5/8" 23 # csg @ 405' w/ 200 sx 4 ½" 11.6# csg @ 3973' w/ 400 sx Perfs 3832' – 3864' TD 3973'

- 1. Set CIBP at 3735'.
- 2. Circulate mud laden fluid. Pressure test casing.
- 3. Spot 25 sx cmt on CIBP. TAG
- 4. Perf at 1858' Soz W/ 50 sx cmt. WOC & Tag. (Base of Salt) 7146 18 76
- 5. Perf at 1500'. Sqz w/ 30 sx cmt. WOC & Tag. (Top of Salt) 776 1383
- Perf at 455'. Pump sufficient cmt to circulate to surface. (Fill 8 5/8" x 4 ½" annulus and 4 ½" csg to surface).
- 7. Cut off wellhead. Verify cement to surface all strings. Install dry hole marker.







Released to Imaging: 8/12/2024 8:36:37 AM

• Received by OCD: 8/12/2024 8:29:53 AM

8 5/8" 23# @ 405'

w/200 sx cmt

PAYE FEDERAL # 6

INSTALL P&A MARKER CUT OFF WELLHEAD

CIRC CMT TO SURFACE INSIDE/OUTSIDE 4 1/2" CASING PERFORATE AT 455'

WOC & TAG SQZ W/ 30 SX CMT PERFORATE AT 1500'

WOC & TAG SQZ W/ 50 SX CMT PERFORATE AT 1858'

Perfs 3849'-3866' 4 1/2 "11.6# @ 3973' w/ 400 sx cmt TD 3973' SPOT 25 SX CMT CIRC MUD LADEN FLUID & PRESSURE TEST CSG SET CIBP AT 3735'

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from this approval:

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification: Contact the BLM Roswell Field Office at least 24 hours prior to the</u> <u>commencing of any plugging operations. For wells in Chaves and Roosevelt County, during</u> <u>office hours or after office hours call (575) 627-0205. Engineer on call during office hours</u> phone (575) 627-0237 or phone (after hours) call (575) 626-5871.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>

.

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
CANO PETRO OF NEW MEXICO, INC.	248802
801 Cherry Street	Action Number:
Fort Worth, TX 76102	372500
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
jagarcia	RECORD CLEAN UP	8/12/2024

Page 7 of 7

.

Action 372500