WAFMSS Sundry Print Report U.S. Department of the Interior BUREAU OF LAND MANAGEMENT Well Name: SAN JUAN 29-7 NP Well Location: T29N / R7W / SEC 19 / County or Parish/State: RIO SWNE / 36.714996 / -107.611038 ARRIBA / NM Well Number: 512 Type of Well: OTHER Allottee or Tribe Name: Lease Number: NMSF078503A Unit or CA Name: Unit or CA Number: **US Well Number: 3003924342 Operator: HILCORP ENERGY** COMPANY

Subsequent Report

Sundry ID: 2811873

Type of Submission: Subsequent Report

Date Sundry Submitted: 09/13/2024

Date Operation Actually Began: 09/06/2024

Type of Action: Cement Remediation

Time Sundry Submitted: 12:57

Actual Procedure: Hilcorp Energy completed cement remediation on the intermediate casing string. Shot perf hole @ 3730'. Pumped 60 sx squeeze cement, pressure tested with NMOCD witness (passed). Please see attached reports.

SR Attachments

Actual Procedure

SJ_29_7_Unit_NP_512_Cmt_Remediation_Sundry_20240913125654.pdf

Well Name: SAN JUAN 29-7 NP	Well Location: T29N / R7W / SEC 19 / SWNE / 36.714996 / -107.611038	County or Parish/State: RIO ARRIBA / NM
Well Number: 512	Type of Well: OTHER	Allottee or Tribe Name:
Lease Number: NMSF078503A	Unit or CA Name:	Unit or CA Number:
US Well Number: 3003924342	Operator: HILCORP ENERGY COMPANY	

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: CHERYLENE WESTON

Name: HILCORP ENERGY COMPANY

Title: Operations/Regulatory Tech - Sr

Street Address: 1111 TRAVIS STREET

City: HOUSTON

State: TX

Phone: (713) 289-2615

Email address: CWESTON@HILCORP.COM

Field

Representative Name:	
treet Address:	
ity:	State:
hone:	
ress:	

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK BLM POC Phone: 5055647742 Disposition: Accepted Signature: Kenneth Rennick BLM POC Title: Petroleum Engineer BLM POC Email Address: krennick@blm.gov Disposition Date: 09/13/2024

Signed on: SEP 13, 2024 12:56 PM

ceived by OCD: 9/13/2024 1:27:		Page 3 of
Hilcorp Energy Company	Well Operations Summary	L48
Well Name: SAN JUAN 29-7 U		
API: 3003924342	Field: BASIN (FRUITLAND COAL)	State: NEW MEXICO
vermit to Drill (PTD) #: bs	Sundry #:	Rig/Service: HEC 101
tual Start Date: 8/26/2024	End Date:	
port Number	Report Start Date	Report End Date
	9/6/2024 Operation	9/6/2024
EW TRAVEL TO LOCATION	oporation	
	CSG (180 PSI), TBG (0 PSI) BDW 5 MIN.	
I WIRELINE IN SET CIBP @ 3750' , RU I GET WATER RETURNS, CIRCULATE		N IN PERF HOLE @ 3730', PUMP INTO WELL MAKE SURE
	T CICR @3720' RU MAKE SURE WELL CIRCULATED OU	IT INTERMEDIATE WITH NO PROBLEM,
UTDOWN, SECURE WELL, DEBRIEF		
EW TRAVEL TO YARD	Report Start Date	Report End Date
	9/9/2024	9/9/2024
EW TRAVEL TO LOCATION	Operation	
LD PJSM, CREW CHECK PRESSURE	CSG (0PSI), TBG (0 PSI) BDW 0 MIN.	
		MENT, 60 SXS TYPE III LEAD, 23 BBL, 2.15 YLD, 12.5#, .5
.L/SX. 14 BBLS DISP, @ 750PSI, LD 10 OH, LD SETTING TOOL.	יטי אין אין אין אין אין אין אין אין אין אי	
UTDOWN SECURE WELL		
EW DROVE TO YARD		
ort Number	Report Start Date 9/10/2024	Report End Date 9/10/2024
	Operation	0,10,2021
TEND BAYWATER SAFETY MEETING	•	
LD PJSM, CREW CHECK PRESSURE		
	RS, TIH TAG CEMENT 3717' , PU POWER SWVL, START D KUP OFF FLOAT TO 7675' TAG ISOLATION PLUG, CIRCL	
UTDOWN SECURE WELL	· · · · · · · · · · · · · · · · · · ·	
REW DROVE TO YARD		
ort Number	Report Start Date 9/11/2024	Report End Date 9/11/2024
	Operation	
<u>TEND HILCORP SAFETY MEETING, C</u> SM. SICP- 340 PSI, SITP- 0 PSI, SIBHF		
	DH, RACK BACK DRILL COLLARS, LD JUNK MILL	
	SI, PERFORM MIT WITH NMOCD REP JOHN DURHAM WI	
ST WHILE PERFORMING MIT, BRADE	NHEAD TEST PASSED, PERFORM INTERMEDIATE TES	T WHILE PERFORMING MIT, INTERMEDIATE
BASIN WIRELINE, RUN CBL, RD WIF	RELINE,	
I, LD DRILL DOLLARS, TIH W/TBG, LE	D TBG,	
UTDOWN SECURE WELL DEBRIEF C	REW	
AVEL TO HILCORP YARD		
www.poloton.com		
www.peloton.com	Page 1/1	Report Printed: 9/13/2024

Hilcorp Energy Company Current Schematic - Version 3

<u> Page 4 of 1</u>1

Well Name: SAN JUAN 29-7 UNIT NP #512 ST1

PI/UWI 30039243	342	Surface Legal Location 019-029N-007W-G	Field Name BASIN (FRUITLAND COA	AL) Route	State/Province NEW MEXICO	Well Configuration Type VERTICAL
round Eleva	ation (ft)	Original KB/RT Elevation (ft) 6.686.00	Tubing Hanger Elevation (ft)	RKB to GL (ft) 13.00	KB-Casing Flange Distance (ft)	KB-Tubing Hanger Distance (ft)
ubing S	trings	0,000.00		13.00		
un Date 2/8/1988	-	Set Depth (ftKB) 3.371,66	String Max Nominal OD (in) 2 3/8	String Min Nominal ID (in) 2.00	Weight/Length (lb/ft) 4,70	Original Spud Date 11/26/1988 22:00
218/1988	3 00:00	3,37 1.00	2 3/8	2.00	4.70	11/26/1988 22:00
			Sidetrack	1 [VERTICAL]		
MD	TVD			Vertical schematic (actual)		
(ftKB)	(ftKB)					
13.1 —	- 12.2 -	անենումեներերություններությունություններուն	3333	nalaladala mandalanalanina damahkada	522.40; 1988-11-26; CEM	asing, 11/26/1988 00:00; 13.00- ENT W/ 300 SXS CLASS 'B' W/ 5 CACL (448 CUFT). CIRCULATED
63.0 —	- 62.1 -				TO SURFACE 1; Surface, 522.40ftKB; 9 5 ftKB; 522.40 ftKB	5/8 in; 9.00 in; 32.30 lb/ft; 13.00
522.3 –	- 521.3 -				1,275.00-2,927.00; 1988-1	nt, Casing, 11/30/1988 00:00; 11–30; TOC 1275' RAN BY TEMP CEMENT W/ 420 SXS CLASS 'B'
1,274.9 —	- 1,273.9 -	— OJO ALAMO (OJO ALAMO (fii	nal)) —		65/35 W/ 6% GEL, 2% CA CUFT) FOLLOWED BY 100	CL, 1/2 CUFT PERLITE/SX (811 SXS CLASS 'B' W/ 2% CACL (11)
2,555.1 -	- 2,554.0 -	— KIRTLAND (KIRTLAND (final))				VEEN STAGES e, 12/3/1988 00:00; 3,090.00- UEEZE W/ 25 SXS CLASS 'B' W/
2,925.2 -	- 2,924.1 -				2% CACL2. REVERSE OUT Cement Squeeze, Squeeze	. HESITATE SQUEEZE e, 12/3/1988 00:00; 2,921.00-
2,927.2 -	- 2,926.1 - - 3,114.0 -))			C 2921' BY CALCULATION USING NCY. SQUEEZE W/ 80 SXS CLAS EE OUT 24 BBLS CMT
3,200.1 -	- 3,199.0 -				1988-12-03	988 00:00 (SQUEEZE PERFS); nt, Casing, 11/30/1988 00:00;
3,377.0 -	- 3,375.8 -		Ŕ		2,927.00-3,416.10; 1988-1 B' 65/35 W/ 6% GEL, 2%	11–30; CEMENT W/ 50 SXS CLAS CACL, 1/2 CUFT PERLITE/SX (10
3,392.1 -	- 3,390.9 -	<typ> (PBTD Origina</typ>	Hole); 3,390.00		CUFT). CIRCULATED BETW 3115-3377ftKB on 12/6/1	SXS CLASS 'B' W/ 2% CACL (11 VEEN STAGES 988 00:00 (PERF - FRUITLAND
3,415.0 —	- 3,413.9 -					e, 12/5/1988 00:00; 3,275.00- SQUEEZE W/ 50 SXS CLASS 'B'
3,730.0 —	- 3,728.2 -					DUT 1.5 BBLS 988 00:00 (SQUEEZE PERFS);
5,060.0 -	- 4,989.1 -	4 in, Packer, 5,060.0, 5,067.	0; MODEL D 4.5		1988-12-03 2; Production1, 3,416.10ft 13.00 ftKB; 3,416.10 ftKB	KB; 7 in; 6.46 in; 20.00 lb/ft;
5,455.1 —	- 5,360.1 -	4 in, Bridge Plug - Ten 5,457.0; HILCORP 4			-09-06 09:30	24 09:30 (SQUEEZE PERFS); 202- ent, Casing, 8/21/2024 09:00
5,467.8 —	- 5,372.2 -				(Production Casing Ceme 21 09:00; LOST RETURNS	ent, casing, 8/21/2024 09:00 nt); 3,200.00-6,072.00; 2024-08- @ 90 BBLS OF DISPLACEMENT
6,070.2 -	- 5,942.3 -				5468-6042ftKB on 9/12/2 LOOKOUT / MENEFEE LOV	
6,072.5 -	- 5,944.5 - - 5,973.2 -	4 in, Bridge Plug - Ten				ent, Casing, 8/21/2024 09:00;
7,616.1 -	- 5,973.2 -	6,102.0;	SELECT 4.5 CBP			08-21 09:00; 8 BBLS CEMENT OF
7,676.8	- 7,540.8 -	4 in, Bridge Plug - Ten 7,677.0;	porary, 7,675.0, 4.5 SELECT CBP			
7,846.1 -	- 7,710.1 -				7782-7846ftKB on 8/31/2 UPPER); 2024-08-31 12:20	024 12:20 (PERF - DAKOTA 0
7,857.0 -	- 7,720.9 -	4 in, Bridge Plug - Ten 7,857.0;	iporary, 7,855.0, 4.5 SELECT CBP			
7,967.8 —	- 7,831.8 -				7861-7968ftKB on 8/31/2 LOWER); 2024-08-31 08:5	024 08:58 (PERF - DAKOTA 8
8,112.9 —	- 7,976.8 -					
8,152.9 -	- 8,016.8 -				3; Production2, 8,153.00ft 1.84 ftKB; 8,153.00 ftKB	:KB; 4 1/2 in; 4.00 in; 11.60 lb/ft;
	101011-001			Page 1/1		Report Printed: 9/13/20

Released to Imaging: 9/16/2024 7:01:29 AM

Cheryl Weston

From:	Rennick, Kenneth G <krennick@blm.gov></krennick@blm.gov>
Sent:	Wednesday, September 11, 2024 3:32 PM
То:	Rikala, Ward, EMNRD; Matthew Esz; Kuehling, Monica, EMNRD
Cc:	Farmington Regulatory Techs
Subject:	Re: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

The BLM finds the proposed MV perforations appropriate.

Kenneth (Kenny) Rennick

Petroleum Engineer

Bureau of Land Management Farmington Field Office 6251 College Blvd Farmington, NM 87402

Email: <u>krennick@blm.gov</u> Mobile & Text: 505.497.0019

From: Rikala, Ward, EMNRD <Ward.Rikala@emnrd.nm.gov> Sent: Wednesday, September 11, 2024 2:09 PM To: Matthew Esz <Matthew.Esz@hilcorp.com>; Kuehling, Monica, EMNRD <monica.kuehling@emnrd.nm.gov> Cc: Rennick, Kenneth G <krennick@blm.gov>; Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

CBL looks good. Good to proceed with MV completion.

Ward

From: Matthew Esz <Matthew.Esz@hilcorp.com> Sent: Wednesday, September 11, 2024 1:54 PM To: Rikala, Ward, EMNRD <Ward.Rikala@emnrd.nm.gov>; Kuehling, Monica, EMNRD <monica.kuehling@emnrd.nm.gov> Cc: Rennick, Kenneth G <krennick@blm.gov>; Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

Good afternoon,

Attached is the CBL pulled today, 9/11 on the San Juan 29-7 Unit NP 512 after completing the required cement remediation work to satisfy the following COA:

1

TOC is required to be 100' above the top perforation in the Fruitland formation.

The MIT was witnessed and passed today. We would like approval to continue with the MV completion prep within the following interval: **5,080'- 6,066'.** Let me know if you have any questions or concerns, thank you.

Matthew Esz

From: Rikala, Ward, EMNRD <<u>Ward.Rikala@emnrd.nm.gov</u>> Sent: Thursday, September 5, 2024 1:55 PM To: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>>; Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>> Cc: Rennick, Kenneth G <<u>krennick@blm.gov</u>>; Farmington Regulatory Techs <<u>FarmingtonRegulatoryTechs@hilcorp.com</u>> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Matthew-

I approve of this procedure.

Ward

From: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>> Sent: Thursday, September 5, 2024 12:52 PM To: Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>>; Rikala, Ward, EMNRD <<u>Ward.Rikala@emnrd.nm.gov</u>> Cc: Rennick, Kenneth G <<u>krennick@blm.gov</u>>; Farmington Regulatory Techs <<u>FarmingtonRegulatoryTechs@hilcorp.com</u>> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

Monica & Ward,

Attached is the updated cmt remediation procedure after previous conversations. Please verify this satisfies all the requirements and respond with written verification/approval. The rig is moving there this afternoon and will begin the work shortly.

Thanks!

From: Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>> Sent: Thursday, September 5, 2024 12:29 PM To: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>>; Rikala, Ward, EMNRD <<u>Ward.Rikala@emnrd.nm.gov</u>> Cc: Rennick, Kenneth G <<u>krennick@blm.gov</u>> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Matthew

In answer to below

NMOCD requires cement from top of cement on 4 $\frac{1}{2}$ by log ran 8/27/2024 – (toc looks to be around 3700 feet). Through shoe of intermediate at 3416 to 100 feet above fruitland coal perforations which is the top of fruitland coal formation (stated on Hilcorp schematic at 3115) -

The COA dated 7/23/2024 on NOI for deepening the well stated TOC is required to be 100' above the top perforation in the Fruitland formation.

There were two documents submitted first was approved on 7/16/2024 second with the above highlighted statement was dated 7/23/2024.

The email dated 8/30/2024 states

<mark>Notice</mark>

Depth of your 7" is 3416 – tieback was not achieved between 41/2 and 7" – remediation is required within 30 days after frac.

It was not stated how high to go with tieback which would refer back to COA on NOI dated 7/23/2024.

In other words after all of that – cement needs to be ran from top of cement on 41/2 to 100 feet above fruitland coal perforations.

Thank you

Monica Kuehling Compliance Officer Supervisor Deputy Oil and Gas Inspector New Mexico Oil Conservation Division North District Office Phone: 505-334-6178 ext. 123 Cell Phone: 505-320-0243 Email - <u>monica.kuehling@emnrd.nm.gov</u>

From: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>> Sent: Thursday, September 5, 2024 7:24 AM To: Rikala, Ward, EMNRD <<u>Ward.Rikala@emnrd.nm.gov</u>> Cc: Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

Ward,

I think there is some confusion on what we have done so far. Could you please give me a call to discuss this further: 770-843-9226. We intend to have a rig on location today and need to agree on a procedure asap.

Thank you!

From: Rikala, Ward, EMNRD <<u>Ward.Rikala@emnrd.nm.gov</u>> Sent: Thursday, September 5, 2024 8:17 AM To: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>> Cc: Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342 **CAUTION:** External sender. DO NOT open links or attachments from UNKNOWN senders.

Matthew-

On the COA, it stated that is cement was not circulated to surface, then a CBL is required. Another COA stated that the TOC was to be 100' minimum over the Fruitland. It appears from you procedure that you want to perforate squeeze hole just above the shoe of the 7" and then pump a squeeze to cover the 7" shoe. The purpose for wanting cement behind your production string is for zonal isolation. I don't recall where the TOC is behind the production casing; however, where ever the TOC is, OCD wants you to perforate just above the TOC(< 50' above) and then circulate cement up to a minimum of 100' above the top of the Fruitland.

Ward

From: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>> Sent: Wednesday, September 4, 2024 3:15 PM To: Rikala, Ward, EMNRD <<u>Ward.Rikala@emnrd.nm.gov</u>> Subject: FW: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

You don't often get email from matthew.esz@hilcorp.com. Learn why this is important

Ward,

Please see the attached cmt remediation procedure and give me a call when you have time. 770-843-9226. Thanks!

From: Rennick, Kenneth G <<u>krennick@blm.gov</u>> Sent: Wednesday, September 4, 2024 11:46 AM To: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>>; Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>> Cc: Farmington Regulatory Techs <<u>FarmingtonRegulatoryTechs@hilcorp.com</u>>; Kade, Matthew H <<u>mkade@blm.gov</u>> Subject: Re: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

The BLM finds the proposal appropriate.

Please include this email conversation in the subsequent report of work completed.

Kenneth (Kenny) Rennick

Petroleum Engineer

Bureau of Land Management Farmington Field Office 6251 College Blvd Farmington, NM 87402 Email: <u>krennick@blm.gov</u> Mobile & Text: 505.497.0019

From: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>> Sent: Wednesday, September 4, 2024 10:12 AM To: Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>>; Rennick, Kenneth G <<u>krennick@blm.gov</u>> Cc: Farmington Regulatory Techs <<u>FarmingtonRegulatoryTechs@hilcorp.com</u>> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

Kenny & Monica,

Attached is the proposed cmt remediation procedure for the San Juan 29-7 Unit NP 512 sidetrack. The DK was completed on 8/31. Our plan is to remediate cmt according to this procedure **prior** to the MV completion. Let me know if you have any questions or need anything else.

Thanks, Matthew

From: Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>> Sent: Friday, August 30, 2024 10:55 AM To: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>>; Rennick, Kenneth G <<u>krennick@blm.gov</u>> Cc: Farmington Regulatory Techs <<u>FarmingtonRegulatoryTechs@hilcorp.com</u>> Subject: RE: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Matthew

NMOCD approval is given to continue with recomplete through MV formation in perforations from 5080 to 6066 and Dakota formation in perforations from 7782 to 7968.

Notice

Depth of your 7" is 3416 – tieback was not achieved between 41/2 and 7" – remediation is required within 30 days after frac.

Thank you

Monica Kuehling Compliance Officer Supervisor Deputy Oil and Gas Inspector New Mexico Oil Conservation Division North District Office Phone: 505-334-6178 ext. 123 Cell Phone: 505-320-0243 Email - <u>monica.kuehling@emnrd.nm.gov</u>

From: Matthew Esz <<u>Matthew.Esz@hilcorp.com</u>> Sent: Thursday, August 29, 2024 3:24 PM To: Kuehling, Monica, EMNRD <<u>monica.kuehling@emnrd.nm.gov</u>>; Rennick, Kenneth G <<u>krennick@blm.gov</u>> Subject: [EXTERNAL] San Juan 29-7 Unit NP 512, API # 3003924342

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Kenny & Monica,

Attached is the CBL pulled on the San Juan 29-7 Unit NP 512 deepening. The witnessed MIT was passed yesterday, 8/28. We would like approval to continue with the completion process and the perforation intervals shown below:

Mesa Verde: 5,080'- 6,066' Dakota: 7,782'- 7,968'

Please reach out to me if you have any questions. Thank you!

Matthew Esz Operations Engineer San Juan South Asset Team Hilcorp Energy Company c: (770) 843-9226

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	383466
	Action Type:
	[C-103] Sub. Drilling (C-103N)
CONDITIONS	

CONDITIONO		
Created By		Condition Date
ward.rikala	None	9/16/2024

CONDITIONS

Page 11 of 11

Action 383466