
Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	PM State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-12321 5. Indicate Type of STATE X	
1220 S. St. Francis Dr., Santa Fe, NM 87505	,		6. State Oil & Gas B-9519	Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or West Dollarhide Dr	Unit Agreement Name rinkard Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTION			8. Well Number 42	2
Name of Operator Scout Energy Management, LLC.			9. OGRID Number 330949	г
3. Address of Operator 13800 Montfort Dr., STE 100 Dallas Tx 75240			10. Pool name or V Dollarhide; TUBB	
4. Well Location				
	he NORTH line and <u>660</u> feet from			
Section 32 Township 245	S Range 38E NMPM 11. Elevation (Show whether DR,	County Le		
	11. Elevation (Snow whether DR,	KKD, KI, GK, etc	.)	
12. Check Ap	ppropriate Box to Indicate N	ature of Notice,	, Report or Other I	D ata
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WO			SSEQUENT REP	ORT OF: ALTERING CASING □
				PAND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB	_
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM OTHER:		OTHER:		
13. Describe proposed or comple	ted operations. (Clearly state all r		nd give pertinent dates	, including estimated date
	k). SEE RULE 19.15.7.14 NMAC			
Scout Energy's plan of action: release BHT. RDMO and return to injection.	packer, drill to bottom perf, acid	ob, unload tubing	and set Packer @ 647	5. Conduct MIT and
Spud Date:	Rig Release Da	ite:		
I hereby certify that the information ab	pove is true and complete to the bo	est of my knowled	ge and belief.	
SIGNATURE DORNANKE	TITLE: SR. Reg	<u>Specialist</u> D <i>A</i>	ATE: <u>03/19/2024</u>	
Type or print name <u>Dorian K. Fuentes</u> <u>For State Use Only</u>	E-mail address: dfuentes@scoute	p.com PHONE: 9	72-325-1005	
APPROVED BY:Conditions of Approval (if any):	TITLE		DAT	E


PROCEDURE WDDU 42: 03-19-2025

- 1. Flow back and kill well
- 2. MIRU NDWH NUBOP release packer TOH w/tbg
- 3. PU bit and bit sub tih on tbg tag fill and drill to bottom perf
- 4. Blow down pressure and toh lay down bit
- 5. PU crest packer and tih w/tbg set packer and pressure test to 500#
- 6. MIRU pump acid job 2100 gal 15 HCL
- 7. Close well open up let well flow back to tank
- 8. Release packer and CWI
- 9. Unload 2 3/8 IPC tbg PU and set new packer down the csg w/FW
- 10. MIRU pump truck and run MIT and BHT
- 11. RDMO return to injection

West Dollarhide Drinkard # 42



West Dollarhide Drinkard # 42



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 443958

CONDITIONS

Operator:	OGRID:
SCOUT ENERGY MANAGEMENT LLC	330949
13800 Montfort Road	Action Number:
Dallas, TX 75240	443958
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By	Condition	Condition Date
anthony.harris	After completing well work, MIT and Bradenhead test to be performed with OCD as witness. Failure of either test shall require the well to be shut-in and a forward plan submitted to OCD.	4/22/2025