Santa Fe Main Office Phone: (505) 476-3441 General Information Phone: (505) 629-6116 State of New Mexico
Energy, Minerals and Natural Resources

Revised July 18, 2013

Phone: (505) 629-6116 WELL API NO. OIL CONSERVATION DIVISION 30-039-05469 1220 South St. Francis Dr. Online Phone Directory Visit: 5. Indicate Type of Lease Santa Fe, NM 87505 https://www.emnrd.nm.gov/ocd/contact-us/ STATE Χ 6. State Oil & Gas Lease No. **FEE** SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A **CANYON LARGO UNIT** DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 22 1. Type of Well: Oil Well Gas Well Other 9. OGRID Number 2. Name of Operator **Hilcorp Energy Company** 372171 3. Address of Operator 10. Pool name or Wildcat 382 Road 3100 Aztec, NM 87410 PC - BALLARD::PICTURED CLIFFS 4. Well Location Unit Letter J Footage 1650' FSL & 1650' FEL **RIO ARRIBA COUNTY** Section 15 Township 024N Range 006W 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6558' GR 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON Х REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Hilcorp Energy Company requests permission to P&A the subject well per the attached procedures, current and proposed wellbore schematics. A closed loop system will be used. Spud Date: Rig Released Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. Tammy Jones **TITLE** Operations/Regulatory Tech - Sr. **SIGNATURE DATE** 5/23/2025 Type or print name Tammy Jones E-mail address: tajones@hilcorp.com **PHONE:** 505.324.5185

TITLE

DATE

APPROVED BY:

Conditions of Approval (if any):



HILCORP ENERGY COMPANY CANYON LARGO UNIT 22 P&A NOI

API #:

3003905469


JOB PROCEDURES

- 1. Contact NMOCD and BLM (where applicable) 24 hours prior to MIRU.
- 2. Hold pre-job safety meeting. Verify cathodic is off. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.
- 3. MIRU service rig and associated equipment; NU and test BOP.
- 4. POOH w/ production tubing and LD.
- 5. Set a 5-1/2" CICR at +/- 2,092' to isolate the PC Perfs.
- 6. Load the well as needed. Pressure test the casing above the plug to 560 psig.
- 7. RU Wireline. Run CBL. Record Top of Cement. All subsequent plugs below are subject to change pending CBL results.
- 8. PU & TIH w/ work string and stinger. Sting into CICR at +/- 2,092', establish injection.
- 9. PLUG #1: 88sx of Class G Cmt (15.8 PPG, 1.15 yield); PC Perfs-2,114' | PC Top-2,112' | FRD Top-1,806' | KRD Top-1,692' | OJO Top-1,516': Pump 9sx of cement beneath the 5-1/2" CICR (est. TOC @ +/- 2,092' & est. BOC @ +/- 2,162'). Pump 79 sack balanced cement plug on top of the CICR. (est. TOC @ +/- 1,416' & est. BOC @ +/- 2,092'). WOC for 4 hrs, tag TOC w/ work string. *Note cement plug lengths and volumes account for excess.
- 10. PUH w/ work string. TIH & perforate squeeze holes @ +/- 1,107'. Establish circulation/injection.
- 11. PLUG #2: 49sx of Class G Cement (15.8 PPG, 1.15 yield); NAC Top @ 1,057':
 Pump 31sx of cement in the 5-1/2" casing X 7-7/8" open hole annulus (est. TOC @ +/- 907' & est. BOC @ +/- 1,107'). Pump an 18 sack balanced cement plug inside the 5-1/2" casing (est. TOC @ +/- 957' & est. BOC @ +/- 1,107'). WOC for 4 hrs, tag TOC w/ work string. *Note cement plug lengths and volumes account for excess.
- 12. POOH w/ work string. TIH & perforate squeeze holes @ +/- 145'. Establish circulation.
- 13. PLUG #3: 41sx of Class G Cement (15.8 PPG, 1.15 yield); Surf. Casing Shoe @ 95':

 Pump 8sx of cement in the 5-1/2" casing X 7-7/8" open hole annulus (est. TOC @ +/- 95' & est. BOC @ +/- 145'). Continue pumping 16sx of cement in the 5-1/2" casing X 8-5/8" casing annulus (est. TOC @ +/- 0' & est. BOC @ +/- 95'). Pump a 17 sack balanced cement plug inside the 5-1/2" casing (est. TOC @ +/- 0' & est. BOC @ +/- 145'). WOC for 4 hrs, tag TOC w/ work string. *Note cement plug lengths and volumes account for excess.
- 14. ND BOP, cut off Wellhead. Top off cement in surface casing annulus, if needed. Install a P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.




HILCORP ENERGY COMPANY CANYON LARGO UNIT 22 P&A NOI





HILCORP ENERGY COMPANY CANYON LARGO UNIT 22 P&A NOI



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 466891

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	466891
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
mkuehling	NMOCD call on Fruitland Coal top is 1860 - Notify NMOCD 24 hours prior to moving on - monitor string pressures daily report on subsequent - submit all logs prior to subsequent	5/28/2025