## State Of New Mexico Energy, Minerals and Natural Resources Department

23-Jun-25

## **CROSS TIMBERS ENERGY, LLC**

**Pre Enforcement Notification** 

400 West 7th Street Fort Worth, TX 76102

## Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

[30-039-22918] MILES FEDERAL #001E		OGRID: 298299	N-05-26N-07W 900 FSL 1670 FWL	
Inspection Date	Type Inspection	Inspector	Inspection No.	
6/23/2025	Routine Inspection	[JVH] Jason Heslop	iJVH2517450101	
Violation				Corrective Action Due
cJVH2517459042 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Noncompliance with Requirements (Construction, Operations or Closure)				9/21/2025
(BGT has hydrocarbons in it. Please remove the hydrocarbons.)				
cJVH2517459043 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Substandard Equipment and/or Needs Repair				9/21/2025
(The containment around the BGT is starting to cave in. Please repair the containment.)				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.