	State of New N	Invino	Form C ² 483 ¹
Cesined by OFF State District In PM Office			FOFIII C-105 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Na	itural Resources	WELL API NO.
<u>District II</u> – (575) 748-1283	OIL CONCEDUATIO		30-025-08532
811 S. First St., Artesia, NM 88210	OIL CONSERVATIO		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fr		STATE X FEE
District IV - (505) 476-3460	Santa Fe, NM	87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	S AND REPORTS ON WELL	LS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATI	ON FOR PERMIT" (FORM C-101)	FOR SUCH	CENTRAL VACUUM UNIT
PROPOSALS.) 1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other		8. Well Number 047H	
2. Name of Operator			9. OGRID Number
-	R OPERATING LLC		330132
3. Address of Operator			10. Pool name or Wildcat
•	FORT WORTH, TX 76102		
4. Well Location			
Unit LetterA:660f	eet from the N line an	nd 660 feet fro	om the E line
Section31			
	L. Elevation (Show whether D	U	<u>j</u>
1.	L. Elevation (Snow whether L	<i>и</i> , <i>кк</i> , <i>к</i> , <i>с</i> , <i>с</i> .)
TEMPORARILY ABANDONCPULL OR ALTER CASINGMDOWNHOLE COMMINGLEMCLOSED-LOOP SYSTEM	LUG AND ABANDON	REMEDIAL WOR COMMENCE DR CASING/CEMEN	ILLING OPNS. P AND A
OTHER:		OTHER:	
		11 montinent details on	
of starting any proposed work). proposed completion or recomp			d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
proposed completion or recomp The following is in response to Violatic In July 2024 this well was found to hav 7/15/24-7/26/24 to repair this issue by s wellhead just below ground level. The well. On 4/4/25 MSO rigged up on the	letion. on cGR2425656189 and cGR2 e a wellhead/casing issue at s etting an RBP downhole @ 3 bad 8-5/8" & 5-1/2" were cut well to test and return the we	AC. For Multiple Co 2425656190: urface. To address th 3500', and then cutting t off and replaced at se ell to production, how	mpletions: Attach wellbore diagram of
proposed completion or recomp The following is in response to Violatic In July 2024 this well was found to hav 7/15/24-7/26/24 to repair this issue by s wellhead just below ground level. The well. On 4/4/25 MSO rigged up on the leak between 37-70'. To fix this issue I this well.	letion. on cGR2425656189 and cGR2 e a wellhead/casing issue at s etting an RBP downhole @ 3 bad 8-5/8" & 5-1/2" were cut well to test and return the we MSO is proposing the followi	AC. For Multiple Co 2425656190: urface. To address th 3500', and then cutting t off and replaced at se ell to production, how	mpletions: Attach wellbore diagram of the issue MSO worked on the well from g off and replacing the bad casing and the urface and a new wellhead was installed on the ever it was determined that the well has a casing
proposed completion or recomp The following is in response to Violatic In July 2024 this well was found to hav 7/15/24-7/26/24 to repair this issue by s wellhead just below ground level. The well. On 4/4/25 MSO rigged up on the leak between 37-70'. To fix this issue I this well.	letion. on cGR2425656189 and cGR2 e a wellhead/casing issue at s etting an RBP downhole @ 3 bad 8-5/8" & 5-1/2" were cut well to test and return the we MSO is proposing the followi	AC. For Multiple Co 2425656190: urface. To address th 3500', and then cutting t off and replaced at se ell to production, how	mpletions: Attach wellbore diagram of the issue MSO worked on the well from g off and replacing the bad casing and the urface and a new wellhead was installed on the ever it was determined that the well has a casing
proposed completion or recomp The following is in response to Violatic In July 2024 this well was found to hav 7/15/24-7/26/24 to repair this issue by s wellhead just below ground level. The well. On 4/4/25 MSO rigged up on the leak between 37-70'. To fix this issue I	letion. on cGR2425656189 and cGR2 e a wellhead/casing issue at s etting an RBP downhole @ 3 bad 8-5/8" & 5-1/2" were cut well to test and return the we MSO is proposing the followi	AC. For Multiple Co 2425656190: urface. To address th 3500', and then cutting t off and replaced at se ell to production, how	mpletions: Attach wellbore diagram of the issue MSO worked on the well from g off and replacing the bad casing and the urface and a new wellhead was installed on the ever it was determined that the well has a casing

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Connis Blaylock	_TITLE_Regulatory Analyst	_DATE_04/11/2025
Type or print name <u>Connie Blaylock</u> For State Use Only	_ E-mail address: <u>_cblaylock@txoenergy.com</u>	_ PHONE: <u>817-334-7882</u>
APPROVED BY: Conditions of Approval (if any):	_TITLE	_DATE

.

MORNINGSTAR OPERATING LLC PROPOSED PROCEDURE

CENTRAL VACUUM UNIT # 047H

30-025-08532

- 1. MIRU.
- 2. Perf 5-1/2" casing ~2900'. Test injection.
- 3. Run and set cement retainer above perf.
- 4. Circulate/squeeze cement into the 5-1/2" annulus attempting to place cement from 2950'- ~500'.
- 5. Wait on cement.
- 6. Pick up on 5-1/2" csg. Backoff casing at first collar below 70'.
- 7. Run replacement 5-1/2" casing, screw into collar. Land 5-1/2" casing.
- 8. Drill out cement retainer.
- 9. Test 5-1/2" casing above RBP. Circulate sand off RBP.
- 10. Run retrieval tool and pull RBP from 3500'.
- 11. Run tubing. Return well to production.

CVU #47H Wellbore Diagram



CVU #47H Wellbore Diagram - PROPOSED



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
MorningStar Operating LLC	330132
	Action Number:
Fort Worth, TX 76102	477183
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
gcordero	None	7/9/2025

Page 5 of 5