State Of New Mexico Energy, Minerals and Natural Resources Department

14-Jul-25

HILCORP ENERGY COMPANY

Pre Enforcement Notification

1111 Travis Street Houston, TX 77002

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-039-26595] SAN JUAN 27 5 UNIT #123F			OGRID: 372171	O-17-27N-05W 800 FSL 2265 FE	L
Inspection	n Date	Type Inspection	Inspector	Inspection No.	
7/9/2025		Routine Inspection	[TV] Thomas Vermersch	iTV2519048610	
Violation			Title		Corrective Action Due
cTV2519560211 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Noncompliance with Requirements (Construction, Operations or Closure)					10/12/2025
	(The base of the be	elow grade tank needs du	ug out all the way around.)		
cTV2519560212	/2519560212 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Substandard Equipment and/or Needs Repair				10/12/2025
	(The metal netting	on the BGT is pulled up	and needs repaired.)		

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.