Form C-103 Revised July 18, 2013 ZELL API NO. 2-045-28653 Indicate Type of Lease STATE FEE State Oil & Gas Lease No. Lease Name or Unit Agreement Name Unit of the content of the
Indicate Type of Lease STATE FEE State Oil & Gas Lease No. Lease Name or Unit Agreement Name unco Disposal Well Number OGRID Number 47130 D. Pool name or Wildcat WD-MV feet from theWestline County San Juan port or Other Data EQUENT REPORT OF:
STATE
State Oil & Gas Lease No. Lease Name or Unit Agreement Name unco Disposal Well Number OGRID Number 47130 D. Pool name or Wildcat WD-MV feet from theWestline County San Juan Port or Other Data GUENT REPORT OF: ALTERING CASING NG OPNS P AND A
Lease Name or Unit Agreement Name unco Disposal Well Number OGRID Number 47130 D. Pool name or Wildcat WD-MV feet from theWestline County San Juan port or Other Data EQUENT REPORT OF:
Well Number OGRID Number 47130 D. Pool name or Wildcat WD-MV feet from theWestline County San Juan Port or Other Data CQUENT REPORT OF:
OGRID Number 47130 D. Pool name or Wildcat WD-MV _feet from theWestline
OGRID Number 47130 D. Pool name or Wildcat WD-MV feet from theWestline
D. Pool name or Wildcat WD-MV _feet from theWestline
reet from theWestline County San Juan port or Other Data CQUENT REPORT OF:
County San Juan port or Other Data QUENT REPORT OF: ALTERING CASING NG OPNS. P AND A
County San Juan port or Other Data QUENT REPORT OF: ALTERING CASING NG OPNS. P AND A
port or Other Data QUENT REPORT OF: ALTERING CASING NG OPNS. P AND A
GUENT REPORT OF: ALTERING CASING NG OPNS. P AND A
GUENT REPORT OF: ALTERING CASING NG OPNS. P AND A
ve pertinent dates, including estimated date etions: Attach wellbore diagram of
according to the attached procedure.
nd belief.
alist DATE7/10/2025_
PHONE:505-486-1171_
a

Conditions of Approval (if any):

Released to Imaging: 7/29/2025 11:45:41 AM

AGUA MOSS, LLC PLAN FOR PRESSURE FALL-OFF TEST (FOT)

MIT Procedure:

Checklist

- Chart recorder w/ 1000# spring
- Calibration sheet (Calibration completed within a year)
- Charts 1 hr x 1000 psi

Procedure

- 1. Record initial tubing and casing pressure
- Connect flowback line to the casing (Pre setup)
- 3. Bleed casing pressure down to the flowback tank
- 4. Set chart timer to 1 hr interval and install chart
- 5. Verify 0 psig on chart
- 6. Attach chart recorder line to the casing
- 7. Shut in flowback line to isolate casing
- 8. Pressure casing up to 500 psig using the pressure washer
- 9. Isolate pressure washer from casing
- 10. Record test for 30 min
- 11. Record tubing and casing pressures
- 12. Open flowback line and bleed casing pressure down to the flowback tank
- 13. Record final tubing and casing pressures
- 14. Shut in the casing and flowback tank and disconnect the chart recorder.
- 15. Verify 0 psig on chart recorder
- 16. Remove chart from recorder

Follow all applicable permit conditions.

On the chart, have OCD Rep. include chart test information: test type, date, start csg pressure, end csg pressure, start time, end time, and witness signatures.

Give Agua Moss Rep. the chart and report to file.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS

Action 489236

COMMENTS

Operator:	OGRID:
AGUA MOSS, LLC	247130
P.O. Box 600	Action Number:
Farmington, NM 87499	489236
	Action Type:
	[C-103] NOI General Sundry (C-103X)

COMMENTS

С	reated By	Comment	Comment Date
C	chavez	MIT (30 minute) & Bradenhead Test FY25 Q4	7/29/2025

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 489236

CONDITIONS

Operator:	OGRID:
AGUA MOSS, LLC	247130
P.O. Box 600	Action Number:
Farmington, NM 87499	489236
	Action Type:
	[C-103] NOI General Sundry (C-103X)

CONDITIONS

Created		Condition Date
cchave	1. Contact OCD Aztec Office to schedule date and time for well testing in order to witness tests. 2. OCD Inspector(s) may modify testing procedures as needed during inspection.	7/29/2025