State Of New Mexico Energy, Minerals and Natural Resources Department

20-Oct-25

ADVANCED WIRELESS COMMUNICATIONS, L.L.C.

Pre Enforcement Notification

24 Road 1956 Farmington, NM 87401

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-045-28876] WEST BISTI COAL 24 COM #002

OGRID: 371710

N-24-25N-13W 1107 FSL 2307 FWL

Inspection DateType InspectionInspectorInspection No.10/20/2025Routine Inspection[JVH] Jason HeslopiJVH2529347492ViolationTitleCorrective Action DuecJVH2529358524 19.15.16.8 Sign on Wells Illegible or Unreadable1/18/2026

(Well sign needs to be updated with the correct information. No API #. Please update the well sign with correct information.)

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.