

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

WELL API NO. 30-021-20553	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> P <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name West Bravo Dome Unit	
8. Well Number 142N	
9. OGRID Number 495	
10. Pool name or Wildcat West Bravo Dome CO2 Gas	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5355 GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: tag and rePerf ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

WBDGU 1829-142N

Date: 8/1/2013

MIRU Wireline services. Pumped 6 bbls PW to cushion guns, well went on vacuum and RIH w/guns, CCL & GR tools. Tagged well @ 2933 (uncorrected for KB). GR reading too hot. TOHw/tools and flow back well.

Date: 8/2/2013

Renegade wireline services had to send a new truck and equipment to resolve the previous day's issues. Arrived on location @ 1:30 pm (their truck had a blowout on the way up to West Bravo Dome). MIRU wireline services. RIH w/ gun & GR & CCL tools but line kept unraveling and slacking. TOH w/tools and TIH at a slower rate. Had trouble correlating again as CBL & GR were not adjusted (tool diagram missing). Decided to postpone perforating till all data and equipment were in good condition.

Spud Date:

05/02/2012

Rig Release Date:

8/2/2013

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rita C Smith TITLE Senior Regulatory Analyst DATE 8-9-2013

Type or print name Rita C Smith E-mail address: rsmith@hess.com PHONE: 432-758-6726

For State Use Only

APPROVED BY: Ed Martin TITLE DISTRICT SUPERVISOR DATE 8/20/2013

Conditions of Approval (if any):