

SEE UP NORTH ✓

Top

Submit One Copy To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240District II
811 S. First St., Artesia, NM 88210District III
1000 Rio Brazos Rd., Aztec, NM 87410District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505State of New Mexico
Energy, Minerals and Natural ResourcesOIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-103
Revised November 3, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		WELL API NO. 30-021-20598
2. Name of Operator WHITING OIL AND GAS CORPORATION		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 400 W ILLINOIS STE 1300 MIDLAND, TEXAS 79701		6. State Oil & Gas Lease No. 40366
4. Well Location Unit Letter F: 1980 feet from the NORTH line and 1980 feet from the WEST line Section 36 Township 22N Range 29E NMPM County HARDING		7. Lease Name or Unit Agreement Name STATE 2229 36
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5455' GR		8. Well Number 01
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> OTHER: <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> <input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- ☒ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Kay Maddox TITLE REGULATORY SUPERVISOR DATE 01/25/2016TYPE OR PRINT NAME KAY MADDOX E-MAIL: kay.maddox@whiting.com PHONE: 432-686-6709
For State Use OnlyAPPROVED BY: Inspector TITLE Inspector DATE 3-09-10
Conditions of Approval (if any):

Lowe, Leonard, EMNRD

From: Danny Holcomb <djholcomb75@gmail.com>
Sent: Tuesday, February 16, 2016 3:12 PM
To: Lowe, Leonard, EMNRD
Subject: Driving Directions to State 2229-36 #1

Leonard,

From Roy, NM, go east on state highway 120 about 25 miles to mile marker 101, just past the mile marker, turn right onto the caliche county road. There is a large blue and white sign there with the lettering "L-9 Ranch ----->" at that intersection. Go east on the county road for 5 miles, you will come to a 90 degree left turn in the county road. There are several houses at that turn, you go straight through the cattleguard onto a dirt two track road. Follow the road southeast about 0.6 miles, turn right into the well. Cell coverage is spotty in that area.

If you have any questions or need any assistance, please let me know.

Thanks,

Danny Holcomb

63
25

88

Lat

Long

N 36.049434

W. 103.80585

Sturdy

1

21.5482

1128 "P2A Marker"

TI 10:00

TO 10:10

Put

36.04475

- 103.80595

21.5464

No resolution

Cow shot everywhere

4 photos P2A Marker