Submit 3 Copies To Appropriate District	State of New M	exico	Form C-103
Office District I	Energy, Minerals and Nat	ural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-007-20695 7. Indicate Type of Lease
District III	1220 South St. Francis Dr.		STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		7. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			
87505	ICES AND DEPORTS ON WELL	<u> </u>	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name of Omit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		VPR A	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Coalbed Methane		8. Well Number 249	
2. Name of Operator	en 📋 Gas wen 🖾 Other Coansed Methane		9. OGRID Number
-	O E & P COMPANY, L.P.		7, GORD Hamber
3. Address of Operator		····	10. Pool name or Wildcat
P.O. BOX	X 190, RATON, NM 87740		
4. Well Location			
Unit LetterF_:	1538feet from theNorth	_ line and1390_	feet from theWestline
Section 25 To	wnship 31N Range	19E NMP	M Colfax County
	11. Elevation (Show whether Di		
	8,305	(GL)	
Pit or Below-grade Tank Application	or Closure		
Pit typeDepth to Groundv	vaterDistance from nearest fresh	water well Dist	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT OF:
		-	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR	K ☐ ALTERING CASING ☐ LLING OPNS.☑ P AND A ☐
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR	K ☐ ALTERING CASING ☐ LLING OPNS.☑ P AND A ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORL COMMENCE DRI CASING/CEMENT	K ☐ ALTERING CASING ☐ LLING OPNS.☑ P AND A ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER:	K ☐ ALTERING CASING ☐ LLING OPNS.☑ P AND A ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and	K ☐ ALTERING CASING ☐ LLING OPNS.☑ P AND A ☐ FJOB ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and	ALTERING CASING LLING OPNS. P AND A COMPANY P
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OR Starting any proposed or composed or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state alork). SEE RULE 1103. For Multiple Complex of the control of	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. P AND A DOT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or composed or composed was recompletion. 04/14/06 Spud @ 7:30 a.m. D	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detected operations. (Clearly state all ork). SEE RULE 1103. For Multiple 11" surface hole to 326'. Run	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. P AND A DOT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or composed or composed was recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed was recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detected operations. (Clearly state all ork). SEE RULE 1103. For Multiple 11" surface hole to 326'. Run pumped 100 sx Midcon II ceme	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 nt, 14 ppg, yield 1.60	ALTERING CASING LLING OPNS. P AND A DOT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or composed or composed was recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed was recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detected operations. (Clearly state all ork). SEE RULE 1103. For Multiple 11" surface hole to 326'. Run	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 nt, 14 ppg, yield 1.60	ALTERING CASING LLING OPNS. P AND A DOT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed work or recompletion. 04/15/06 Drill 7 7/8" hole from	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple 11" surface hole to 326'. Run I pumped 100 sx Midcon II ceme face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 25 m 326' - 2,575'. Reached TD at 25 m 326' - 2,575'.	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 at, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m.	ALTERING CASING LLING OPNS. P AND A DOT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed work or recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple 111" surface hole to 326'. Rund pumped 100 sx Midcon II cemes face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 20 gwell. Logger's TD at 2,578'	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 nt, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m.	ALTERING CASING LLING OPNS. P AND A DOT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed work or recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detected operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 20 gwell. Logger's TD at 2,578'. 5 #, J-55 LT & C casing at 2,522	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 at, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m.	ALTERING CASING LLING OPNS. P AND A DISTRIBUTION DE LLING OPNS. P
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed work or recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple 111" surface hole to 326'. Rund pumped 100 sx Midcon II cemes face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 20 gwell. Logger's TD at 2,578'	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 at, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m.	ALTERING CASING LLING OPNS. P AND A DISTRIBUTION DE LLING OPNS. P
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed work or recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detected operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 20 gwell. Logger's TD at 2,578'. 5 #, J-55 LT & C casing at 2,522	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 at, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m.	ALTERING CASING LLING OPNS. P AND A DISTRIBUTION DE LLING OPNS. P
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or composed was or recompletion. 04/14/06 Spud @ 7:30 a.m. Dull Halliburton mixed and WOC 8 hrs. Test sur 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15 HES mixed and pump	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state allork). SEE RULE 1103. For Multiple fill 11" surface hole to 326'. Run I pumped 100 sx Midcon II cemerate 8 5/8" csg to 500 psi for 30 in 326' - 2,575'. Reached TD at 2.578' csg well. Logger's TD at 2,578'. 5 #, J-55 LT & C casing at 2,52 ed 435 sks Midcon II cement. Ci	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 ont, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m. 1'. reulated 28 bbls of ce	ALTERING CASING LLING OPNS. P AND A Grup P A
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed wor recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15 HES mixed and pump	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state allork). SEE RULE 1103. For Multiple fill 11" surface hole to 326'. Run I pumped 100 sx Midcon II cemerace 8 5/8" csg to 500 psi for 30 in 326' - 2,575'. Reached TD at 2.578'. 5 #, J-55 LT & C casing at 2,52 ed 435 sks Midcon II cement. Ci	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 ont, 14 ppg, yield 1.6 oninutes. 2,575' at 11:00 a.m. 11 reculated 28 bbls of celebrated 28 bbls of c	ALTERING CASING LLING OPNS. P AND A DISTRIBUTION DE LLING OPNS. P
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or compost starting any proposed wor recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed work recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15 HES mixed and pump I hereby certify that the information grade tank has been/will be constructed or the proposed will be constructed or the proposed work will be constructed or the proposed or composed work will be constructed or the proposed or composed work will be constructed or the proposed or composed work will be constructed or the proposed or composed work will be constructed or the proposed or composed work will be constructed or the proposed will be constructed will be constructed or the proposed will be constructed or th	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 2,578' at 2,578'. 5 #, J-55 LT & C casing at 2,52 ed 435 sks Midcon II cement. Circles above is true and complete to the closed according to NMOCD guidelines	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 at, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m. 1'. reculated 28 bbls of cellosest of my knowledge D, a general permit	ALTERING CASING LLING OPNS. P AND A DIJOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed was or recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed was or recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15 HES mixed and pump I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 2,578' at 2,578' at 2,578'. 5 #, J-55 LT & C casing at 2,52' and 435 sks Midcon II cement. Cincaporate according to NMOCD guidelines.	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 nt, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m. 1'. reculated 28 bbls of cell best of my knowledge , a general permit Regulatory Analysis	ALTERING CASING LLING OPNS. P AND A DOB PAND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or composed was or recompletion. 04/14/06 Spud @ 7:30 a.m. Dure Halliburton mixed and WOC 8 hrs. Test sure O4/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15 HES mixed and pump I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Shirley A.M.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 2,578' at 2,578' at 2,578'. 5 #, J-55 LT & C casing at 2,52' and 435 sks Midcon II cement. Cincaporate according to NMOCD guidelines.	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 nt, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m. 1'. reculated 28 bbls of cell best of my knowledge , a general permit Regulatory Analysis	ALTERING CASING LLING OPNS. P AND A DIJOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed was or recompletion. 04/14/06 Spud @ 7:30 a.m. Describe proposed was or recompletion. 04/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15 HES mixed and pump I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 2,578'. 5 #, J-55 LT & C casing at 2,52 ed 435 sks Midcon II cement. Cinciple face according to NMOCD guidelines of the closed according to NMOCD guidelines itchell E-mail address: shi	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 at, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m. 11 reculated 28 bbls of cellost of my knowledge a general permit Regulatory Analytic rley.mitchell@elpas	ALTERING CASING LLING OPNS. P AND A DIT JOB PAND A DIT JOB DI JOB DIT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or composed was or recompletion. 04/14/06 Spud @ 7:30 a.m. Dure Halliburton mixed and WOC 8 hrs. Test sure O4/15/06 Drill 7 7/8" hole from MIRU Patterson and I Run 82 jts 5 ½", 15 HES mixed and pump I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Shirley A.M.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 2,578'. 5 #, J-55 LT & C casing at 2,52 ed 435 sks Midcon II cement. Cinciple face according to NMOCD guidelines of the closed according to NMOCD guidelines itchell E-mail address: shi	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 nt, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m. 1'. reculated 28 bbls of cell best of my knowledge , a general permit Regulatory Analysis	ALTERING CASING LLING OPNS. P AND A DIT JOB PAND A DIT JOB DI JOB DIT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or composed was or recompletion. 04/14/06 Spud @ 7:30 a.m. Dure Halliburton mixed and WOC 8 hrs. Test sure WOC 8 hrs. Test sure MIRU Patterson and I Run 82 jts 5½", 15 HES mixed and pump I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Shirley A ME For State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ork). SEE RULE 1103. For Multiple face 8 5/8" csg to 500 psi for 30 m 326' - 2,575'. Reached TD at 2,578'. 5 #, J-55 LT & C casing at 2,52 ed 435 sks Midcon II cement. Cinciple face according to NMOCD guidelines of the closed according to NMOCD guidelines itchell E-mail address: shi	REMEDIAL WORK COMMENCE DRI CASING/CEMENT OTHER: I pertinent details, and ple Completions: At 11 jts. of 8 5/8", 24 at, 14 ppg, yield 1.6 minutes. 2,575' at 11:00 a.m. 11 reculated 28 bbls of cellost of my knowledge a general permit Regulatory Analytic rley.mitchell@elpas	ALTERING CASING LLING OPNS. P AND A DID A