
₹.		<b>₩</b>				
- <b>ģ</b>	DECEN	<b>-</b>				
Submit 3 Copies To Appropriate District	State of New Me	XICO		Form C-103		
Office District I	Energy, Minerals and Natu	ral Resources -		May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240	** a.i.o. //iiiiiii		WELL API NO.			
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-021-20126			
District III	Oliobannian Pigi	vind Dr.	5. Indicate Type of Lease STATE X FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	1229 and FET NIX 8	<b>3</b> 05	6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM Santa Fe, NM S			L-5816			
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit	Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT	JG BACK TO A	West Bravo Dome CDG Unit				
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other CO2 Supply			8. Well Number 3			
Name of Operator     Hess Corpor		9. OGRID Number 495				
3. Address of Operator		10. Pool name or Wildcat				
P.O. Box 840 Seminole, T.	X 79360		West Bravo Dome			
4. Well Location	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7					
	980 feet from the North	line and	1980 feet from the	West line		
Section 36		nge 29E		inty Harding		
	1. Elevation (Show whether DR,					
Pit or Below-grade Tank Application or C	4521'					
	Distance from nearest fresh w	rater well Dista	ance from negrest surface wa	ter		
Pit Liper Thickness: mil	Below-Grade Tank: Volume		nstruction Material			
	· · · · · · · · · · · · · · · · · · ·			<del></del>		
12. Check App	propriate Box to Indicate N	ature of Notice, I	Report or Other Data	l		
NOTICE OF INTE	ENTION TO:	SUBS	SEQUENT REPOR	RT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASI						
TEMPORARILY ABANDON				ID A 🔲		
PULL OR ALTER CASING   1	MULTIPLE COMPL	CASING/CEMENT	JOB 🗆			
OTHER:	П	OTHER: Casing	Integrity Test	[X]		
13. Describe proposed or complete	ed operations. (Clearly state all					
of starting any proposed work	). SEE RULE 1103. For Multip					
or recompletion.						
8/7/2006						
Dressure tested assists to 500	O poi for 20 min. I lold Ol. Chad	attached Tald				
Pressure tested casing to 590 psi for 30 min. Held OK. Chart attached. TA'd well.  Hess Corporation respectfully requests to continue TA'd status on well.						
	requests to serial as 1710 status	. 0,				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .						
SIGNATURE (MOL)	\1. A	enior Advisor/Regula		ге 8/22/2006		
Time or maint come Corel   Manage		11 01				
Type or print name Carol J. Moore For State Use Only	E-mail ac	dress: cmoore@hes	ss.com Telepho	one No. (432)758-6738		
1/1 11	1-1:	1		_		
APPROVED BY: Conditions of Approval (if any):	arton TITLE D	ISTRICT SU	PERVISOR DA	ге <u><i>9-</i>/2-06</u>		



	• L	less G	αP.	
	Lu Lu	BDCI	ж. )6u	
TBG. PRE	#	3	and the second s	
3G. PRE		Ō		Paris periode de la compo
<u></u> 5	4:30	PSI FOI	1 <u>30</u> 5:00	MN
NAN	B:	Pet	ref	
UNIT Driver N	O107	200 101 m	DATE	8-7-06
	B	ion Pet	rep ATTO	
	ld.	Mart	to NM	OCD

•