

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-021-20126
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-5816
7. Lease Name or Unit Agreement Name WBDU
8. Well Number 361F
9. OGRID Number 495
10. Pool name or Wildcat West Bravo Dome Gas Unit

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other CO2 Supply

2. Name of Operator  
Hess Corporation

3. Address of Operator  
P.O. Box 840 Seminole, Texas 79360

4. Well Location  
Unit Letter F 1980 feet from the North line and 1980 feet from the West line  
Section 36 Township 19N Range 29E NMPM County Harding

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4521'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

**SUBSEQUENT REPORT OF:**  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Change valve pump out plug ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**WBDGU 1929 361F**

8/27

MIRU Key Pressure Truck and Flowback Tank, JSA, TPC 0 psi, CPC 0 psi. Change out Master Tbg Valve to AB body. Drop 4 Soap Sticks, Pump 1 bbls 6% KCL down Tubing to Load and Pump out Plug at 900 psi. Well on Vacuum. Open Well to Tank. RDMO Key Pressure Truck. Rec 5 BLW in 1 hr. Well flowing Dry Gas. SI Well. RD Flowback tank.

Spud Date:

03/16/1981

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Rita C.

Digitally signed by Rita C. Smith  
DN: cn=Rita C. Smith, o=Hess  
Corp, ou=Engineering,  
email=rsmith@hess.com, c=US  
Date: 2009.03.18 15:13:50 -05'00'

*Rita C. Smith*

SIGNATURE Smith

TITLE Engineering Technician DATE 03/18/2009

Type or print name Rita C. Smith E-mail address: rsmith@hess.com PHONE: (432) 758-6726

**For State Use Only**

APPROVED BY: *Al Martin* TITLE **DISTRICT SUPERVISOR** DATE 3/23/09  
Conditions of Approval (if any):