Lynx Petroleum Consultants, Inc.

P.O. Box 1708 3325 Enterprise Drive

Hobbs, New Mexico 88241

505 392-6950

Fax: 505 392-7886

January 24, 2005

RECEIVED

JAN > 11 2005

OIL CONT

New Mexico Oil Conservation Division Engineering Bureau 1220 South St. Francis Drive Santa Fe, NM 87505

Re: ADMINISTRATIVE ORDER SWD-966

Sirs:

Per requirement (a) of the above referenced order, please find attached a copy of the temperature survey run after the cement job on the 8-5/8" casing. We were unable to locate nor do we have any information in our files about any logs that may have been run during the 1994 workover. Per requirement (b), a CIBP will be installed within 200 feet of the lowermost perforation prior to commencing injection operations. Don't hesitate to call or write if there are any additional questions.

Sincerely,

LYNX PETROLEUM CONSULTANTS, INC.

Carry R. Scott

Larry R. Scott

enc

BENNETT WIRE LINE SERVICE

.HYOBB\$\,.NY.M. .RYT A/.BOX /\5/2 .PHONE/.EXY.3+6.987

TEMPERATURE SURVEY



