

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

f MCB 1122746306

Release Notification and Corrective Action

n MCB 1122746582

OPERATOR

Initial Report Final Report

Name of Company: Holly Transportation LLC <i>278421</i>	Contact: Stan Grant
Address: 1602 W. Main, Artesia, NM. 88211	Telephone No. 575-513-2395
Facility Name: Henshaw Station	Facility Type: Crude Oil Unloading Station

Surface Owner: Holly Energy Partners <i>FED SURFACE</i>	Mineral Owner	Lease No.
--	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	23	17 S	30 E					Eddy County

Latitude: N32 48.963 Longitude: W103 56.300
32.9500 103.94700

NATURE OF RELEASE

Type of Release: Crude Oil Spill	Volume of Release: 106 barrels	Volume Recovered
Source of Release: Was from dome of the tank.	Date and Hour of Occurrence: 7-17-11 @ 0500 am	Date and Hour of Discovery: 7-17-11 @ 0500 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Stan Grant	Date and Hour 7-18-11 @ 6:06 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
JUL 26 2011

Describe Cause of Problem and Remedial Action Taken.*
Driver was unloading at station and overfilled the tank causing crude oil to overflow from the dome of the tank spilling into the spill containment wall. It was a Contract Carrier for Holly transportation LLC that had the spill. Hanson Trucking Inc., RR 4 Box 4599, Roosevelt, UT. 84066. Office # 435-722-1891 Owner Rex Hanson.

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*
The spill was contained inside the spill containment wall. Holly Energy will work with NMOCD and a remediation contractor to test and remove the contaminated soil, replace with fresh soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Stanley E. Grant</i>	OIL CONSERVATION DIVISION	
Printed Name: Stanley E. Grant	Signed By <i>Mike Brannon</i> Approved by District Supervisor:	
Title: Regulatory Coordinator	Approval Date: AUG 15 2011	Expiration Date:
E-mail Address: stan.grant@hollycorp.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date:	Phone: 575-513-2395	

* Attach Additional Sheets If Necessary

i MCB 1122746946
Comply # MCB 1122747201

9/15/2011
2RP-848