

**McMillan, Michael, EMNRD**

---

**From:** Robert\_Wilson@oxy.com  
**Sent:** Thursday, August 2, 2018 11:23 AM  
**To:** McMillan, Michael, EMNRD  
**Cc:** Sandra\_Musallam@oxy.com  
**Subject:** Administrative Order CTB-841\_Red Tank 31 State 5H

Michael,

After reviewing the approved Administrative Order CTB-841 for the Red Tank 31 State 5H Battery it was noticed that the API number listed for the Red Tank 30 31 State Com #24Y was incorrect and that the API number for the Red Tank 30 31 State Com #24H (30-025-44062) had been used by mistake. This oversight happened because the 24H well originally was permitted to produce into the facility but the well bore was not completed due to an issue while drilling after the surface casing was set. Operations on the 24H well were stopped, and a new permit was obtained for the Red Tank 30 31 State Com #24Y (30-025-44161) which was drilled and completed to replace the 24H well bore that was abandoned while drilling.

Therefore, we would like to correct the API number listed for the Red Tank 30 31 State Com #24Y on the application from (30-025-44062) to (30-025-44161). Please note that this change in API number for the 24Y well will have no impact on lease ownership or involve any changes to the original scope and intention of the application or pools under consideration. In addition, the API number correction will also match the number as assigned to the Red Tank 30 31 State Com #24Y on the NMOCD web site.

If you have any questions or need any additional information please contact me at your convenience.

**Robert K Wilson**

Regulatory Engineer

Office: 713-985-6991 || 29.125 || Cell: 281-731-8091