

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
OCT 13 2011  
**NMOCD ARTESIA**

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*DCP Midstream 36785* OPERATOR  Initial Report  Final Report

Name of Company: Duke Energy Field Services	Contact: Jon Bebbington
Address: 10 Desta Drive, Suite 400 W., Midland, TX 79705	Telephone No. 432-620-4207
Facility Name A-2-5 4-inch Poly Line	Facility Type: Pipeline

Surface Owner: BLM	Mineral Owner	Lease No.
--------------------	---------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	6, SE Quarter	18S	27E					Eddy

Latitude N32.7736 Longitude W104.3168

**NATURE OF RELEASE**

Type of Release: Natural Gas Gathering Line Condensate	Volume of Release: 8 bbls	Volume Recovered: 0
Source of Release: Pipeline	Date and Hour of Occurrence UNKOWN	Date and Hour of Discovery 10-11-2011 1500
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, OCD & Paul Evans, BLM, & NRC	
By Whom? Jon Bebbington	Date and Hour 10-12-2011 10:00	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Approx 8 bbls reached a dry creek bed	

If a Watercourse was Impacted, Describe Fully.\*  
A 15 foot deep dry creek bed was impacted. Although the bed is typically dry, it is a tributary to the Pecos River near Artesia, NM so was reported to the OCD, BLM, and the NRC

Describe Cause of Problem and Remedial Action Taken.\*  
Cause is attributed to plastic pipeline failure.

Describe Area Affected and Cleanup Action Taken.\*  
The poly line was isolated and repairs initiated. A 3<sup>rd</sup> party contractor, TALON, will initiate soil cleanup on October 17, 2011. The weather forecast is sunny. A final C141 will be submitted with a closure report upon completing cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Jon Bebbington*

Printed Name: Jon Bebbington

Title: Sr. Environmental Specialist

E-mail Address: jdbebbington@dcpmidstream.com

Date 10-13-11 Phone: 432-620-4207

**OIL CONSERVATION DIVISION**

Signed By *Mike Bratcher*  
Approved by District Supervisor

Approval Date: **OCT 20 2011** Expiration Date:

Conditions of Approval: Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 11/20/2011**

Attached  **JRP-927**

\* Attach Additional Sheets If Necessary

MLB 1129347538  
MLB 1129349585  
MLB 1129350176  
VIO# MLB 1129350335

## Bratcher, Mike, EMNRD

---


**From:** Bebbington, Jon D [JDBebbington@dcpmidstream.com]  
**Sent:** Thursday, October 13, 2011 2:19 PM  
**To:** Martin, Ed, EMNRD; Bratcher, Mike, EMNRD  
**Subject:** DCP Midstream A-2-5 Gathering Line Condensate Release  
**Attachments:** A-2-5 Line 10-13-2011.pdf

DCP Midstream submits the attached initial C-141 report for an 8-bbl natural gas condensate release near Artesia, NM. A final C-141 report will be submitted following cleanup.

*Jon Bebbington  
Senior Environmental Specialist  
West Assets*

*DCP Midstream, LP  
10 Desta Drive, Suite 400 West  
Midland, TX 79705  
Ofc: 432-620-4207  
Cell: 432-413-3601  
e-mail: [jdbebbington@dcpmidstream.com](mailto:jdbebbington@dcpmidstream.com)*





Pecos River ↑

DCP Midstream (36785) A-2-5 4" poly GAS Gathering Line 2RP-927

6-18s-27E DOR: 10/11/11 f MLB 1129347538

32.7736 N 104.3168 W