


District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

30-015-21031

**Release Notification and Corrective Action**

nmlb/203326646 OPERATOR  Initial Report  Final Report

Name of Company - Southwest Royalties, Inc. 21355	Contact - Luis Gonzalez
Address - 6 Desta Drive, Ste 6700	Telephone No. 432-661-4708
Facility Name - Wilderspin Federal	Facility Type - Battery
Surface Owner - BLM	Mineral Owner: BLM
Lease No. NM 1478B/16282	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	11	21 S	27 E	1980	N	1980	W	Eddy Co.

Latitude Longitude

**NATURE OF RELEASE**

Type of Release - Oil	Volume of Release - 135Bbls	Volume Recovered - 85 Bbls
Source of Release- External corrosion on a 4" Swage at the Main production oil tank.	Date and Hour of Occurrence 12-19-11 @ Early morning.	Date and Hour of Discovery 12-19-11 @ ~ 0830 Hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM- Jim Amos and NMOCD- Mike Bratcher	
By Whom? Eric Garcia, SWR Environmental Contractor	Date and Hour 12-19-11 @ ~ 0830 Hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A 4" Swage on the product tank developed a leak allowing oil to impact the ground. We have recovered all free fluids standing at present time and New fittings were installed in the Tank and put back in service.

Describe Area Affected and Cleanup Action Taken.\* We have recovered All free fluids standing around the tank and begun proper Delineation/Excavation process as requested. Soils affected with oil will be properly disposed of. Will proceed by collecting soil samples and have soils analyzed, once determined spill area is cleaned, Then will conclude by backfilling excavated areas.... Note... ALL fluids were contained inside the Dikes.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
	Approved by District Supervisor:	
Printed Name: Luis Gonzalez	Approval Date: FEB 02 2012	Expiration Date:
Title: Environmental Regulatory Administrator	Conditions of Approval:	
E-mail Address: lgonzalez@claytonwilliams.com	Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	
Date: 12/27/11 Phone: 432-661-4708	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**PROPOSAL NOT LATER THAN:**  
3/2/2012

2RP-991

**Bratcher, Mike, EMNRD**

---

**From:** Gonzalez, Luis [LGonzalez@claytonwilliams.com]  
**Sent:** Tuesday, December 27, 2011 9:06 AM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov  
**Cc:** eric garcia; Newton, Robert; Brock, Danny  
**Subject:** WILDERSPIN NMCOD-BLM CI41 SPILL REPORT  
**Attachments:** WILDERSPIN NMCOD-BLM CI41 SPILL REPORT.doc