

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*n MCB/204625555*

Name of Company Holly Energy Partners <i>242939</i>		Contact Jeff Stubblefield	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address 1602 W Main Street Artesia, NM 88210		Telephone No. 972-322-5782		
Facility Name Abo Station		Facility Type Pump Station		
Surface Owner State of NM	Mineral Owner	Lease No.		

**LOCATION OF RELEASE**

Unit Letter	Section 3	Township 18S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	-----------	--------------	-----------	---------------	------------------	---------------	----------------	-------------

Latitude N 32.778375 Longitude W -104 269893

**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 5 bbls	Volume Recovered 0 bbl
Source of Release Gaso Pump	Date and Hour of Occurrence 11/7/2011 10 48 a m	Date and Hour of Discovery 11/7/2011 10 48 a m
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES. To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted. Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken * The leak was a result of packing failure on the Gaso pump. Packing has been replaced and pump repaired. Contaminated soil has been removed and placed on plastic at pump station		
Describe Area Affected and Cleanup Action Taken * Product was released under pump and migrated approximately 40-50 feet from fenced area. Employee built earthen dikes around released material to contain. The free product and the contaminated soil was excavated and placed on plastic to allow for natural aeration.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature <i>Lori Coupland</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Lori Coupland	Approved by District Supervisor <i>Signed By Mike Beaman</i>	
Title: Regulatory Compliance Mgr	Approval Date <b>FEB 15 2012</b>	Expiration Date: <i>N/A</i>
E-mail Address: lori.coupland@hollyenergy.com	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: 11/7/2011 Phone: 575 748 4076	<i>Final</i>	

\* Attach Additional Sheets If Necessary

*F MCB 1204624976*

*JRP-1018*