

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 5 2012

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NMLB 1210949851

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ South Water Station	Facility Type	Water Station
Surface Owner	State	Mineral Owner	
		Lease No. (API#)	30-015-10756
		Closest well location	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	17S	29E					Eddy

Latitude 32 48.382 Longitude 104 04.653

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	50bbls	Volume Recovered	25bbls
Source of Release	Injection manifold 2" coupling	Date and Hour of Occurrence	03/28/2012	Date and Hour of Discovery	03/28/2012 8:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Josh Russo	Date and Hour	03/28/2012 11:46 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The injection manifold 2" coupling blew odd of the line causing the release. The injection manifold has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 50bbls were released and we were able to recover 25bbls with a vacuum truck. The release area traveled from the location and streamed into the nearby pasture to a pooling area measuring roughly 15' x 50'. All free fluids have been recovered and the location has been scraped. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Signed By	
Title:	HSE Coordinator	Approved by District Supervisor:	
E-mail Address:	jrusso@conchoresources.com	Approval Date:	APR 18 2012
Date:	04/05/2012	Expiration Date:	
Phone:	432-212-2399	Conditions of Approval:	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:
		Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

5/18/2012

2RP-1097

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Thursday, April 05, 2012 1:44 PM
To: Bratcher, Mike, EMNRD
Cc: Tavaréz, Ike; Dorey, Kim; Franklin, Tom K.
Subject: C-141 Initial Report - GJ SOUTH WATER STATION
Attachments: GJ SOUTH WATER STATION -- DATE OF RELEASE -- 03-28-2012.pdf

Mr. Bratcher,

Please see the attached C-141 Initial Report for the GJ South Water Station. We plan to assess timely.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Thursday, March 29, 2012 10:46 AM
To: Bratcher, Mike, EMNRD
Subject: Spill Notification - GJ SOUTH WATER STATION

Mr. Bratcher,

Please see below a detailed description of a release that occurred on 03/28/2012:

On 03-28-2012, at approximately 8:00am, a produced water spill was discovered at GJ South Water Station. Roughly 50bbls were released onto location measuring an area of 550'x10' and an area in the adjacent pasture of 53'x15'. 25bbls were recovered with a vacuum truck. Contaminated soil on location will be removed and replaced as necessary. The release was caused by failure at manifold. We will follow up with a C-141 Initial Report.

GPS coordinates, legal description, and driving directions are below:

N32* 48.382'
W104* 04.653'

GJ #18
Sec 28 T17S R29E
Eddy Co. NM

Turn South on Valley Gas road for .2 miles, turn right for .1 miles.

Thank you,

Joshua Russo
HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.