


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company JMW 12180 32938 **COG OPERATING LLC 229137** **Contact** Pat Ellis
Address 550 W. Texas, Suite 100, Midland, TX 79701 **Telephone No.** 432-230-0077
Facility Name Burch Keely Unit #100 **Facility Type** Injection line

Surface Owner Federal **Mineral Owner** **Lease No. (API#)** 30-015-04213

LOCATION OF RELEASE

Unit Letter P	Section 18	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 48.877 Longitude 104 00.563

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 30bbls	Volume Recovered 15bbls
Source of Release Steel line	Date and Hour of Occurrence 06/15/2012	Date and Hour of Discovery 06/15/2012 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD	
By Whom? Michelle Mullins	Date and Hour 06/16/2012 6:15 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The Burch Keely Unit #100 steel line ruptured roughly 50 yards from the Burch Keely Unit #279 well. We have replaced the faulty joint of pipe with a new joint.		
Describe Area Affected and Cleanup Action Taken.* Initially 30bbls of produced water was released from the steel line and we were able to recover 15bbls with a vacuum truck. The release was contained by the roadway and measured an area of 31' x 11' in the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor	Signed By:
Title: HSE Coordinator	Approval Date: JUN 28 2012	Expiration Date:
E-mail Address: jrusso@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/22/2012 Phone: 432-212-2399		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

ZRP-1192

7/28/12

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Friday, June 22, 2012 9:59 AM
To: Bratcher, Mike, EMNRD; Jim Amos office (jamos@blm.gov); Gregston, Terry G
Cc: Tavarez, Ike; Dorey, Kim; Franklin, Tom K.; Michelle Mullins
Subject: C-141 Initial Report - BKU 100 INJ LINE
Attachments: BURCH KEELY UNIT #100 INJECTION LINE --¹DATE OF RELEASE -- 06-15-2012.pdf

Please see attached the C-141 Initial Report for a release that occurred on 06/15/2012. We plan to schedule soil sampling of the spill area timely.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.