


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised March 17, 1999  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*nmlb/216.748367* OPERATOR  Initial Report  Final Report

Name of Company	Devon Energy <i>6137</i>	Contact	Tracy Kidd
Address	P. O. Box 250 Artesia, NM 88211	Telephone No.	575-513-062
Facility Name	Cotton Draw 65 SWD	Facility Type	Salt Water Disposal

Surface Owner	Mineral Owner	Lease No.	<i>APZ#</i>
---------------	---------------	-----------	-------------

**LOCATION OF RELEASE**

*30-015-10843*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>6</i>	2	25S	31E	1980	North	1980	East	Eddy

**NATURE OF RELEASE**

Type of Release	Oil Spill	Volume of Release	35 bbls	Volume Recovered	35 bbls
Source of Release	Spill over	Date and Hour of Occurrence	6/8/12, 8:48AM	Date and Hour of Discovery	6/8/12, 8:48AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos / BLM & Mike Bratcher / OCD		
By Whom?	Tracy Kidd & Daniel Suniga	Date and Hour	6/8/12, 9:33AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
At the Cotton Draw 65 SWD, the gun barrel malfunctioned causing a 35 bbl oil spill, all kept within the line containment. All fluid was recovered.

Describe Area Affected and Cleanup Action Taken.\*  
At the Cotton Draw 65 SWD, the gun barrel malfunctioned causing a 35 bbl oil spill, all kept within the line containment. The Gun barrel was overloaded with fluid coming in and was not able to maintain amount of fluid being pushed out, this caused the tanks to fill up with produced water, pushing the oil over the top of the tank. A vacuum truck was called and all 35 bbl of oil were recovered. The produced water was then hauled off to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gracie Bustamante</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Gracie Bustamante	Approved by	Signed By: <i>Mike Bratcher</i> District Supervisor
Title: Field Adm Support	Approval Date: JUN 13 2012	Expiration Date:
Date: 06/08/12 Phone: (575) 746-5561	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 7/13/2012**

*2RP-1169*

