


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nMLB1219234870 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Russell Turner Water Flood Skim Tank- Turner B # 95	Facility Type: Injection Plant
Surface Owner: Federal	Mineral Owner: Federal
API No.: 3001526612	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	20	17S	31E	2610	South	1000	West	Eddy

Latitude: 32.8199711236509 Longitude: -103.897239412252

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 586 / 66	Volume Recovered: 540 / 46
Source of Release: Tank	Date and Hour of Occurrence: 07/06/2012	Date and Hour of Discovery: 07/06/2012 6:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 07/06/2012 9am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Russell Turner Water flood plant pump went off and didn't call anyone on alarm, tanks filled up and skimmed over to skim tank and ran over tank. Haarmeyer electricians were called to fix problem, and found wires inside callout pannel box not properly connected. Connected/shorting out wires and alarms started working and calling out again.

Describe Area Affected and Cleanup Action Taken.* : It ran approximately 1470 feet south west out of dike across road onto pasture. Pulled water/oil out of dike and tanks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: <i>Joe Hernandez</i>	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By <i>Mike Bratcher</i>	
Title: Production Foreman	Approved by District Supervisor:	
E-mail Address: jhernandez@linenergy.com	Approval Date: JUL 11 2012	Expiration Date:
Date: 07/09/2012 Phone: 575-942-9492	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 8/11/2012**


2RA-1200

Bratcher, Mike, EMNRD

From: Theresa McCracken [TMcCracken@linnenergy.com]
Sent: Monday, July 09, 2012 9:18 AM
To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)
Cc: Daniel Frick; Ron Ragland; Joe Hernandez; Gary Wink
Subject: Linn - Russell Turner Wtr. Flood C-141 7-6-12
Attachments: Russell Turner Wtr flood 7-6-12.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken
2130 W Border
Hobbs, NV 88240
T: 575-738-1733 / F: 575-738-1740
tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

Dade, Randy, EMNRD

From: Gregston, Terry G [tgregsto@blm.gov]
Sent: Friday, July 06, 2012 7:04 PM
To: dfrick@linnenergy.com; rragland@linnenergy.com; jhernandez@linnenergy.com; gawink@linnenergy.com; Bratcher, Mike, EMNRD; Dade, Randy, EMNRD
Subject: Russell Turner and Turner B North Tank Battery spills: arch survey required, spill map attached
Attachments: Russel Turner and Turner B Tank Batteries-070612 spills map-070612.jpg

Gentlemen,

This notification is in regard to the following location and undesirable event:

Event Number: NU12151TG
Event Date: 7/6/2012
Event Name: Turner B North Tank Battery
Legals: T17S/R31E, sec. 20,

Event Number: NU12152TG
Event Date: 7/6/2012
Event Name: Russell Turner Injection Plant Skim Tank
Legals: T17S/R31E, sec. 20,

An archeological survey will be required for the above listed undesirable events.
Before reclamation work begins on this site, archeological clearances must be obtained that encompass:

- All disturbed soil and contaminated soil areas
- A 50-foot buffer zone around any area where equipment will be utilized, parked, or driven
- Any required new access routes into the disturbed area, with a 50-foot buffer zone to either side


Archeological surveys must be conducted by third party contractors that are BLM-approved.
In undesirable event cases, archeological surveys must be conducted as soon as possible.
If you have any further questions about archeological surveys, please contact James Smith, BLM CFO Archeologist, at (575)706-6664.

An alternative is to participate in the MOA. Again, Contact James Smith, BLM CFO Archeologist for more information on the MOA.

A spill map is attached for your reference.

Thank you for your attention to these concerns,

Terry Gregston
Environmental Protection Specialist
Bureau of Land Management
620 E. Greene St.
Carlsbad, NM 88220
Office (575) 234-5958
Cell (575) 361-2635
Fax (575) 234-5927



LEE FEDERAL #040

TURNER A #051

TURNER B #095

FREN OIL COMPANY #011

019

020

TURNER B #012

LOVINGTON HWY

137

FREN OIL COMPANY #025

TURNER B #067

OXY CHOCOLATE MOOSE FEDERAL #001

OXY CHOCOLATE MOOSE FEDERAL #001Y

FREN OIL CO #019
STRAIGHT LINE FEDERAL #001
STRAIGHT LINE FEDERAL #001