

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
AUG 01 2012
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1221556317 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO 102 SWD	Facility Type	SWD

Surface Owner State _____ Mineral Owner _____ Lease No (API#) 30-015-21398

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	26S	28E					Eddy

Latitude 32 02.657 Longitude 104 05.431

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	160bbbs	Volume Recovered	100bbbs
Source of Release	Fiberglass header connection	Date and Hour of Occurrence	07/21/2012	Date and Hour of Discovery	07/21/2012 4:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD			
By Whom?	Michelle Mullins	Date and Hour	07/22/2012 12:45 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A fiberglass connection failed at the inlet header on the south side of the SWD. The connection is being repaired.

Describe Area Affected and Cleanup Action Taken.*

Initially 160bbbs were released from the failed connection and were able to recover 100bbbs with a vacuum truck. Some of the fluid was contained inside the dike walls on the south side of the facility. Some of the fluid escaped the dike walls and streamed to a low lying area to the south of the location in the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By 
Title:	HSE Coordinator	Approval Date:	AUG 02 2012
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	08/01/2012	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

9/2/12

2RP-1245

Bratcher, Mike, EMNRD

From: Joshua Russo <jrusso@concho.com>
Sent: Wednesday, August 01, 2012 3:49 PM
To: Bratcher, Mike, EMNRD
Cc: Tarez, Ike; Grubbs, Robert; Dorey, Kim; Franklin, Tom K.
Subject: C-141 Initial Report - SRO 102 SWD
Attachments: SRO 102 SWD -- DATE OF RELEASE -- 07-21-2012.pdf

Mr. Bratcher,

Please find attached a C-141 Initial Report for a release that occurred at our SRO 102 SWD on 07/21/2012. We plan to assess the spill area timely.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins [MMullins@concho.com]
Sent: Sunday, July 22, 2012 11:45 AM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo
Subject: SRO 102 SWD-Immediate Notification

Mr. Bratcher:

At approximately 4:00 p.m. on 07/21/2012, at the SRO State 102 SWD, a produced water leak was discovered. A fiberglass connection failed at the inlet header, located on the south side of the facility. Approximately 160 bbls of produced water was released. A vacuum truck has recovered the free fluid. We will obtain more details and submit a C-141. GPS coordinates, legal description, and driving directions below.

N32* 02.657 W104* 05.431

SRO State 102 SWD
1980' FNL & 1980' FEL
Sec. 16 T26S R28E
Eddy County, NM
API 30-015-21398

From Highway 285 drive south to White City Road. Travel 1 mile, turn left, travel 2.3 miles, turn south into location.

Michelle Mullins
HSE Field Tech
2407 Pecos Avenue
P.O. Box 1630
Artesia, NM 88211-1630
Phone: (575)746-2010
Cell: (432) 934-1052
mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.