


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*n JMW 13113.35700*

**OPERATOR**  Initial Report  Final Report

Name of Company Burnett Oil Co. <i>3080</i>	Contact Belton Mathews
Address Box 188 Loco Hills, NM	Telephone No. 575-677-2313
Facility Name Gissler A - Inj. Line	Facility Type Salt Water Inj. Line
Surface Owner BLM	Mineral Owner
API No. <i>30-015-30275</i>	

**LOCATION OF RELEASE**

Unit Letter A	Section 23	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 33 49 434 Longitude 103 56 208

**NATURE OF RELEASE**

Type of Release Salt Water	Volume of Release 600 to 800 bls	Volume Recovered 400 bls
Source of Release 4 in. injection line broke	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher OCD 4/18/13	
By Whom? Eddie Seay	Date and Hour 4/19/13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* 4 in. poly injection line parted, salt water ran down hill and into a pipeline ditch belonging to Holly Energy.		
Describe Area Affected and Cleanup Action Taken.* From leak - down approximately 400 ft. - 4 to 6 ft. wide, puddled up in an area 25 x 75 and into Holly ditch approximately 225 ft. long. Line was repaired and all available water vacuumed up.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Eddie W. Seay</i>	<b>OIL CONSERVATION DIVISION</b>	
	Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Printed Name: Eddie W. Seay	Approval Date: <b>APR 23 2013</b>	Expiration Date:
Title: Agent	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: seay04@leaco.net		
Date: 4/19/2013	Phone: 575-392-2236	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

*MAY 23, 2012*

*2RP-1632*