

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
JUN 24 2013  
NMOCD ARTESIA

Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nJMW 1318353692* OPERATOR  Initial Report  Final Report

Name of Company	Oxy Permian Ltd. <i>16696</i>	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Harroun 9-1	Facility Type	Well location

Surface Owner	BLM	Mineral Owner		API No.	30-015-34997
---------------	-----	---------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	9	24S	29E	530	South	330	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Oil	Volume of Release	40 bbls oil	Volume Recovered	0 bbls oil
Source of Release	Mechanical error sent oil down a gas line causing tank to overflow	Date and Hour of Occurrence	06/13/2013	Date and Hour of Discovery	06/13/2013
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen, James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	06/17/2013 @ 8:03 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A mechanical error sent oil down the gas line causing the tank to overflow and leak 40 bbls of oil to leak onto the ground. No fluids were recovered and mechanical error was corrected.

Describe Area Affected and Cleanup Action Taken.\*

A mechanical error sent oil down the gas line causing the tank to overflow and leak 40 bbls of oil to leak onto the ground. No fluids were recovered and mechanical error was corrected. Remediation will be conducted in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by Environmental Specialist:	<i>Mike Bratcher</i>
Title:	HES Specialist	Signed By:	
E-mail Address:	Chancey.Summers@oxy.com	Approval Date:	<b>JUL 02 2013</b>
Date:	<i>6-24-13</i>	Expiration Date:	
Phone:	(575) 397-8216	Conditions of Approval:	Attached <input type="checkbox"/>

Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**  
**August 2, 2013**

*2RP-1699*

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Monday, June 24, 2013 12:31 PM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov; jvancure@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141s for Harroun 9-1 and Lost Tank 3 Fed #14  
**Attachments:** Initial C-141, Harroun 9-1.pdf; Initial C-141, signed 6-24-13- Lost Tank 3-14.pdf

Attached are the initial C-141s for a leak occurring at the Harroun 9-1 on 6/13/13 in Eddy County, NM and a leak occurring at the Lost Tank 3 Federal #14 on 6/17/13 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

**From:** Chancey\_Summers@oxy.com  
**Sent:** Monday, June 17, 2013 8:03 AM  
**To:** jamos@blm.gov; Jennifer\_VanCuren@blm.gov; Bratcher, Mike, EMNRD;  
cbrunson@bbcinternational.com; jgilkey@bbcinternational.com;  
kathy@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** Harroun 9-1

All, Oxy Permian Primary had a leak at the Harroun 9-1 Battery Thursday June 13th, 2013. Oxy released 40 bbls of oil due to a mechanical error that sent oil down our gas line causing tank to over fill and spill over. None was recovered. The location of the spill is in Sect 9, T24S, R29E of Eddy County. Oxy will conduct some initial remediation, C-141 to follow. BBC Int'l will delineate at a later date. Driving directions: Go to Malaga turn East on Duarte go 7/10 mile turn North on Harroun Road, go 3 miles turn right on Eddy to Road 788, for 2.5 miles to fork to the left to compressor station where tank is located. If you have any questions let me know.

Thank You  
C.J. Summers  
HES Advisor  
Cell # 575-631-9436  
Office # 575-397-8216  
[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)

"When the blind lead the blind, get out of the way!"