


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*nJMW* 1319840879

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-295 The spill location is 800 ft. east of the PLU-213 Tank Battery and approximately 5080 ft. north east of the well location.	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35549
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	17	24S	30E					Eddy

Latitude N 32.211958 Longitude W 103.911742

**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 2 bbls oil and 18 bbls water	Volume Recovered: 0
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 6/26/13 time unknown	Date and Hour of Discovery: 6/26/13 at 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The flow developed a leak due to external corrosion, a temporary leak clamp was placed on the pipe. The bad section of pipe will be replaced.

Describe Area Affected and Cleanup Action Taken.\*  
Approximately 1000 sq. ft of the rawhide road and approximately 500 sq. ft. of pasture. All of the spilled fluid soaked into the ground, the spill area will be remediated in accordance to the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By <i>Mike Brannon</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <b>JUL 16 2013</b>	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & Attached <input type="checkbox"/> like approval by BLM. <b>SUBMIT REMEDIATION</b>	
Date: 7/14/13	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

**PROPOSAL NO LATER THAN:**  
*August 16, 2013* *2RP-1729*