

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
SEP 16 2011
NMOCD ARTESIA

Form C-14
Revised October 10, 2007
Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NJMW 1321930165 OPERATOR Initial Report Final Report
 Name of Company Enterprise Field Services, L.L.C. **1000347** Contact Dina Babinski
 Address Env. Dept PO Box 4324, Houston, TX 77210-4324 Telephone No. 210-232-4880
 Facility Name Gathering Lines, Eddy County **#4** Facility Type Gathering Pipeline, Pecos River 6H
 Surface Owner- several, pipeline leak Mineral Owner -several, pipeline leak Lease No. N/A

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| | 6 | 21S | 26E | | | | | Eddy |

Latitude N 32 31 11.45 Longitude W 104 19 26.21

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release Natural Gas | Volume of Release: 0.118 MMscf | Volume Recovered 0 |
| Source of Release Pipeline | Date and Hour of Occurrence 09/06/2011, 14:10 pm (Mountain Time) | Date and Hour of Discovery 09/06/2011 14:06 pm (Mountain Time) |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? NA | |
| By Whom? | Date and Hour (Mountain Time) | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |

Describe Cause of Problem and Remedial Action Taken: Internal corrosion suspected to be the cause of the leak. Producers shut in and the line was blown down to prepare the line to safely repair. Total gas loss was 0.118 Mscf.

Describe Area Affected and Cleanup Action Taken.

A standard one-call was initiated to expedite repairs. Gas flow to the line was shut in. First attempt to repair the line was a clamp. The line remains out of service and appropriate section of the line will be replaced with new 4" pipe. Once repairs are complete, the line will be brought back to normal operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|-----------------------------------|-----------------------------------|
| Signature: <i>Dina Babinski</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Dina Babinski | Approved by District Supervisor: | Accepted for record NMOCD |
| Title: Senior Environmental Scientist | Approval Date: AUG 07 2013 | Expiration Date: |
| E-mail Address: <u>djbabinski@eprod.com</u> | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 8/15/11 Phone: 210-232-4880 | | |

Attach Additional Sheets If Necessary

fjmw 1321929956

ijmw 1321930684

2RP-1795

Bratcher, Mike, EMNRD

From: Babinski, Dina [DJBabinski@eprod.com]
Sent: Friday, September 16, 2011 12:02 PM
To: Bratcher, Mike, EMNRD
Cc: Thompson, Roger; Nolan, Shiver
Subject: C-141 09/06/2011
Attachments: 090611.pdf

Mike, attached is the initial and final report for a small leak and repair in southeast New Mexico. If you have questions, please feel free to call. Thanks.

Dina Babinski
Sr Environmental Scientist
Enterprise Products Operating, LLC
(210) 528-3824 (office)
(210) 232-4880 (mobile)
(713) 803-9442 (fax)
DJBabinski@eprod.com

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.