


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
3 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW 1323541848

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street	Facility Name Dolores AIL Federal #2 (Livingston Ridge)	Telephone No. 575-748-1471
Facility Name Dolores AIL Federal #2 (Livingston Ridge)	API Number 30-015-26548	Facility Type Well

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-65418
--------------------------	--------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter I	Section 14	Township 22S	Range 31E	Feet from the 1980'	North/South Line South	Feet from the 430'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.3896 Longitude: 103.74089

NATURE OF RELEASE

Type of Release Produced Water; Crude Oil	Volume of Release 20 B/PW; 1 B/O	Volume Recovered 0 B/PW; 0 B/O
Source of Release Poly pipe rupture	Date and Hour of Occurrence 8/17/2013	Date and Hour of Discovery 8/17/2013
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
A poly pipe ruptured

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 75' X 50'. Spill is approximately 200 yards north of cattle guard where CR29 intersects. The release made a flow path on the east side of the lease road and overspray on the west side of the road. The flow line valves were shut off, leak was isolated, and Dolores water pump was shut off. The overspray that reached vegetation west of the lease road will be sprayed with micro blaze. Flow path on the east side of the lease road will be excavated and the lease road will be scraped. All excavated soils will be disposed of at an approved NMOCD facility. Vertical and horizontal delineation samples will be taken and sent to a NMOCD approved facility. **Depth to Ground Water: >100' (approximately 150', Section 11, T22S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Approved by District Supervisor: Signed By <i>Mike Beaudoin</i>	AUG 23 2013
Title: Environmental Regulatory Agent	Approval Date:	Expiration Date:
E-mail Address: acannon@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Wednesday, August 21, 2013 Phone: 575-748-4111	2RP-	

* Attach Additional Sheets If Necessary

2RP-1859

20f 2

Bratcher, Mike, EMNRD

From: Amber Cannon <ACannon@yatespetroleum.com>
Sent: Wednesday, August 21, 2013 10:17 AM
To: jamos@blm.gov; Bratcher, Mike, EMNRD
Cc: Katie Parker; Lupe Carrasco; Bob Asher
Subject: RE: Release (Livingston Ridge Water System)
Attachments: DoloresAILFederal2_LivingstonRidge_C141_08-17-13 Initial.pdf

Please find attached an Initial C-141 for the release mentioned below.

Thanks,
Amber Cannon

From: Bob Asher
Sent: Monday, August 19, 2013 4:27 PM
To: jamos@blm.gov; (mike.bratcher@state.nm.us)
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Livingston Ridge Water System)

Mr. Amos,

The following release (Other-Than-Major Undesirable Events) was off location and on Federal Surface within the pipe line ROW. Yates will need archeological reports checked before proceeding with clean-up/remediation work.

Yates Petroleum Corporation is reporting a release at the following location (8/12/2013).

Livingston Ridge Water System (Dolores AIL Federal #2)
N32 23.287, W103 44.450
30-015-26548
Section 14, T22S-R31E
Eddy County, New Mexico

Released: Approximately 1 B/O & 20 B/PW; Recovered: Unknown at this time.

Cause of release is from a pipe line. Well(s) shut in. Release area isolated. Vacuum truck(s) and repair crew was called.

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Wednesday, August 21, 2013 7:28 AM
To: Amber Cannon
Cc: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD; Katie Parker; Lupe Carrasco; Bob Asher
Subject: Re: Release (Livingston Ridge Water System/Dolores AIL Federal #2)

Received, thanks

On Tue, Aug 20, 2013 at 4:22 PM, Amber Cannon <ACannon@yatespetroleum.com> wrote:

Please find attached an initial C-141 for the release mentioned below.

Thanks,
Amber Cannon

From: Bob Asher
Sent: Monday, August 12, 2013 4:10 PM
To: (mike.bratcher@state.nm.us); (Randy.Dade@state.nm.us); jamos@blm.gov
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Livingston Ridge Water System/Dolores AIL Federal #2)

Yates Petroleum Corporation is reporting a release at the following location (8/12/2013).

Livingston Ridge Water System (Dolores AIL Federal #2)

30-015-26548

Section 14, T22S-R31E

Eddy County, New Mexico

Released: Approximately 200 B/PW; Recovered: Unknown at this time.

Cause of release is from a pipe line. Well(s) shut in. Release area isolated. Vacuum truck(s) and backhoe crew were called.

A Form C-141 Initial will be submitted with complete information.

Thank you.

Robert Asher

NM Environmental Regulatory Supervisor

Yates Petroleum Corporation

105 S. 4th Street

Artesia, NM 88210

575-748-4217 (Office)

575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
