

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*JMW 1327736656*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	OCCIDENTAL PERMIAN LTD. <i>16696</i>	Contact	RODNEY CAMPBELL
Address	329 MARATHON ROAD LAKEWOOD, NM 88220	Telephone No.	(575) 628-4167
Facility Name	Indian Basin Gas Plant Gathering System	Facility Type	GAS GATHERING SYSTEM
Surface Owner	Mineral Owner	Lease No.	


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release	822 MCF	Volume Recovered	0
Source of Release	Date and Hour of Occurrence	9/27/2013 12:01:00 PM	Date and Hour of Discovery	9/27/2013 12:01:00 PM
BLOWDOWN POINTS ON PIPELINE	Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER
By Whom? RODNEY CAMPBELL	Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour	09/27/2013 12:18 P.M. VOICEMAIL
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.*	N/A			



Describe Cause of Problem and Remedial Action Taken.\*  
Cause:  
OXY'S INDIAN BASIN GAS PLANT GATHERING SYSTEM RELEASED 822 MCF OF GAS TO THE ATMOSPHERE TO PURGE A NEW 16" GAS GATHERING PIPELINE.  
Remedial Action Taken:  
OXY IS PUTTLING NEW 16" GAS GATHERING PIPELINE INTO SERVICE. IN ORDER TO PREVENT THE OXY INDIAN BASIN GAS PLANT FROM FLARING ON HIGH OXYGEN CONTENT, THIS NEW PIPELINE HAD TO BE PURGED.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor:	<b>Accepted for record NMOCD</b>
Title: <i>HE S Specialist</i>	Approval Date: <b>OCT 04 2013</b>	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>9-30-13</i>	Phone: (575) 628-4167	

\* Attach Additional Sheets If Necessary

*FJMW 132703412 S*

*JMW 1327737798*

*2RP-1969*