

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on-back
side of form

RECEIVED OGD

Release Notification and Corrective Action

2012 MAR 22 A 11:00
 Initial Report Final Report

nJMW 1327739706

OPERATOR

Name of Company OXY USA WTP LP 16696	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING PLANT
Surface Owner	Mineral Owner INDIAN BASIN
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21-S	23-E					Eddy

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 1486.99 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 3/10/2012 2:16:00 PM	Date and Hour of Discovery 3/10/2012 2:16:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 03/12/2012 15:28	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

RECEIVED
APR 3 2012

Describe Cause of Problem and Remedial Action Taken.*

Cause:
HAD AN EMERGENCY PLANT SHUT DOWN DUE TO HIGH LIQUID LEVEL ON VERTICAL INLET SCRUBBER. FOR 2 HOURS 44 MINUTES 1480 MCF OF INLET GAS WAS DIVERTED TO ES-42. FOR 30 MINUTES 5.4 MCF WAS DIVERTED TO ES-50
Remedial Action Taken:
OPERATIONS CALLED OUT AUTOMATION GROUP TO TROUBLESHOOT ESD CAUSE. EXTRA OPERATIONS STAFF WAS CALLED IN TO ASSIST IN PUTTING PLANT BACK ONLINE.

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor:	Accepted for record NMOCD
Title: <i>Plant Tech</i>	Approval Date: OCT 01 2013	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>3-14-12</i>	Phone: 575-628-4167	

* Attach Additional Sheets If Necessary

RJMW 132703 4/25 iJMW

ZRP-1970