


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW 1328430519* OPERATOR  Initial Report  Final Report

Name of Company OXY USA WTP LP <i>16696</i>	Contact Campbell, Rodney	
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167	
Facility Name INDIAN BASIN GAS PLANT	Facility Type Gas Processing Plant	
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21-S	23-E					Eddy

Latitude 32.45 271° Longitude 104.57 515°

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 425 MCF	Volume Recovered 0
Source of Release LINE 4 BLOWOUT	Date and Hour of Occurrence 5/10/2012 2:10:00 PM	Date and Hour of Discovery 5/10/2012 2:10:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Rodney Campbell	Date and Hour 5/10/2012 5:20pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a	
If a Watercourse was Impacted, Describe Fully.* n/a		
Describe Cause of Problem and Remedial Action Taken.* Cause: LINE 4-16" RUPTURED CAUSING 425 MCF OF .0800% H2S GAS TO BE RELEASED INTO ATMOSPHERE. INDIAN BASIN PLANT AND FIELD PERSONNEL IMMEDIATELY BEGAN SHUTTING IN THE PIPELINE.		
Describe Area Affected and Cleanup Action Taken.* Approximately 300' around the rupture was covered in iron sulfide which was in the pipeline. Oxy will be replacing all of line 4 main line with 12" pipe. We are waiting for the BLM to inspect the area and offer guidance on cleanup procedures.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Clint Kirkes</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Clint Kirkes	Approved by District Supervisor: <b>Accepted for record NMOCD</b>	
Title: <i>Plant Specialist</i>	Approval Date: <b>OCT 11 2013</b>	Expiration Date:
E-mail Address: clinton_kirkes@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>5/15/2012</i> Phone: 575-628-4113		

\* Attach Additional Sheets If Necessary

*nJMW 132 703 4125*

*nJMW 1328431555*

*2RP-1988*