


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit Copy to Appropriate District Office in accordance with 19.15.29 NMAC

**Release Notification and Corrective Action**

*RTJM* 1327540609  
**OPERATOR**  Initial Report  Final Report  
 Name of Company: Linn Operating *269324* Contact: Brian Wall  
 Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739  
 Facility Name: HE WEST B Battery 2 and 4 - West B #19 Facility Type: Waterflood  
 Surface Owner: Federal Mineral Owner: API No.: 3001505125

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	10	17S	31E	660	North	1980	West	Eddy

Latitude: 32.8545167385998 Longitude: -103.859741264752

**NATURE OF RELEASE**

Type of Release: Produced Water / Oil	Volume of Release: 20bbls/1gal	Volume Recovered: 0 / 0
Source of Release: FiberGlass Pipeline	Date and Hour of Occurrence: 09/19/2013	Date and Hour of Discovery: 09/19/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour 09/20/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: received call from pumper of injection plant about an alarm of low discharge pressure. We shut off headers and pressured up opening valves one by one. Line 1&2 would not hold pressure more than 400 psi. so we left lines shut in. called for a pump truck to pressure up and test line. shut off lateral lines and had truck start pumping on main trunk line but would not pressure up. Walked out line and found leak in pasture. 3" fiberglass line was uncovered from wind blowing sand away.

Describe Area Affected and Cleanup Action Taken.\* : line bowed up and ruptured causing an affected area about 15'x15'. an estimated 20 barrels of dirty black water and a light skim of oil was lost. repair and clean up has to be completed before the line can be re-buried. This line should not operate until it has been buried to prevent it from bowing and breaking. We cant cover the line until clean up has been accomplished

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Brian Wall	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: Construction Foreman II	Approval Date <b>OCT 02 2013</b>	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/30/2013 Phone: 806-367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN: November 2, 2013</b>	


\* Attach Additional Sheets If Necessary

*2RP-1960*

## Bratcher, Mike, EMNRD

---

**From:** McCracken, Theresa <TMcCracken@linnenergy.com>  
**Sent:** Monday, September 30, 2013 9:25 AM  
**To:** mburton@blm.gov; Bratcher, Mike, EMNRD  
**Cc:** Callahan, Terry; Moreno, Laura; Butters, Thomas; Golding, Chris; Wall, Fred; hconder@rice-ecs.com; lweinheimer@rice-ecs.com; jkamplain@rice-ecs.com  
**Subject:** Linn- West B Battery 9-19-13  
**Attachments:** West B Battery WB#19 9-19-13.pdf



Please find attached the initial C-141 for the above referenced location.

Thank you,



*Theresa McCracken*

Field Administrator

**LINN Energy, LLC**

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

[tmccracken@linnenergy.com](mailto:tmccracken@linnenergy.com)

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.