

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1327756448

OPERATOR

Initial Report Final Report

Name of Company Devon Energy <i>60137</i>	Contact Merle Lewis
Address P.O. Box 250, Artesia, NM 88211	Telephone No. 575-748-6304
Facility Name West Shugart 19 Federal 2	Facility Type Oil Well
Surface Owner	Mineral Owner
API No. 30-015-30780	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	19	18S	31E	510	SOUTH	2310	WEST	EDDY

Latitude 32.7271300239255 Longitude -103.909386055786

NATURE OF RELEASE

Type of Release Spill	Volume of Release 7 bbls	Volume Recovered 2
Source of Release Hole in heater treater vessel	Date and Hour of Occurrence <i>* 9-29-13</i> 10/29/13, 3:00 PM	Date and Hour of Discovery 10/29/13, 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeffery Robins/BLM, Mike Bratcher/OCD	
By Whom? Jaime Castillo, Assistant Foreman	Date and Hour 10/01/2013, BLM 2:27pm, OCD 2:31 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

(Spoke w/Gracie via phone 10/4/13 to get a corrected date for the release, Sean Marie Te Arroyo)



Describe Cause of Problem and Remedial Action Taken.*

At the Shugart 19-2, the heater treater developed a hole in the bottom of the vessel and leaked 7 bbls of produced water.

Describe Area Affected and Cleanup Action Taken.*

At the Shugart 19-2, the heater treater developed a hole in the bottom of the vessel and leaked 7 bbls of produced water. Lease operator shut in production, and plans to repair or replace heater treater before putting back into operation. At this time it is still under investigation to see if repairs can be made or it must be replaced. 2 bbls of produced water was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Graciela C. Bustamante</i>		OIL CONSERVATION DIVISION	
Printed Name: Graciela C. Bustamante		Approved by Environmental Specialist: Signed By <i>Mike Bratcher</i>	
Title: Field Admin. Tech		Approval Date: OCT 04 2013	Expiration Date:
E-mail Address: Gracie.Bustamante@dvn.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
Date: 10/02/2013 Phone: 575-746-5561		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
November 4, 2013

2RP-1971