

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW 1329038557*

**OPERATOR**  Initial Report  Final Report

Name of Company <i>OXY USA WTP LP 1166916</i>	Contact KIRKES, CLINT	
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4113	
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY	
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
								Eddy

Latitude 32\*27 52.502" Longitude 104\*34 28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 114.23 MCF	Volume Recovered 0
Source of Release Acid Gas Flare	Date and Hour of Occurrence 8/16/2012 7:44:00 PM	Date and Hour of Discovery 8/16/2012 7:44:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**RECEIVED**  
AUG 22 2012  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Cause:  
ACID GAS COMPRESSOR DOWN DUE TO A LIGHTNING STRIKE WHICH DAMAGED THE ONE OF PLC CARDS AND BOTH CARD AND PROCESSOR RACKS.  
Remedial Action Taken:  
OPERATORS CALLED OUT PLANT AUTOMATION AND PLANT ELECTRICIAN ALONG WITH FIELD AUTOMATION TO TRY TO TROUBLE SHOOT AND REPAIR THE EQUIPMENT DAMAGED DUE TO THE LIGHTNING STRIKE. ACID GAS COMPRESSOR WAS RESTARTED AFTER ALL REPAIRS WERE MADE.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RODNEY CAMPBELL	<b>Accepted for record NMOCD</b>	
Title: <i>HEJ Specialist</i>	Approval Date: <b>OCT 17 2013</b>	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>8-20-12</b> Phone: (575) 628-4167		

\* Attach Additional Sheets If Necessary

*fJMW 1327034125*

*nJMW 1329039010*

*ZRP-1999*