

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1330829263
 OPERATOR Initial Report Final Report
 Name of Company: BOPCO, L.P. 260737 Contact: Tony Savoie
 Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329
 Facility Name: 10" Water transfer mainline. The spill location is 160 ft. S.W. of the PLU-213 SWD well Facility Type: Exploration and Production
 Surface Owner: Federal Mineral Owner: Federal API No.30-015-33859


LOCATION OF RELEASE

| | | | | | | | | |
|------------------|---------------|-----------------|--------------|---------------|------------------|---------------|----------------|-----------------|
| Unit Letter P | Section 18 | Township 24S | Range 30E | Feet from the | North/South Line | Feet from the | East/West Line | County: Eddy |
|------------------|---------------|-----------------|--------------|---------------|------------------|---------------|----------------|-----------------|

Latitude N 32.212260 Longitude W 103.914606

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release: Produced water | Volume of Release: 12 bbls. | Volume Recovered: 0 bbls. |
| Source of Release: Flange connection on 10" mainline | Date and Hour of Occurrence: 10/28/13 time unknown | Date and Hour of Discovery: 10/28/13 at 11:47 a.m. |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A flange on the 10" mainline developed a leak due to loose flange bolts, the bolts were re-torqued and the line was pressure tested.

Describe Area Affected and Cleanup Action Taken.*
Approximately 240 sq.ft. of pasture was affected by the release, all of the fluid soaked into the ground. The area around the leak point was excavated and stockpiled on-site pending removal. The remediation will be in accordance to the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|-----------------------------------|
| Signature: Tony Savoie | OIL CONSERVATION DIVISION | |
| Printed Name: Tony Savoie | Approved by Environmental Specialist | Signed By: Mike Brannon |
| Title: Waste Management and Remediation Specialist | Approval Date: NOV 01 2013 | Expiration Date: |
| E-mail Address: tasavoie@basspet.com | Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION | Attached <input type="checkbox"/> |
| Date: 10/31/13 | Phone: 432-556-8730 | |

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
December 1, 2013 2RP-2042