

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

fJMW1331128022 OPERATOR Initial Report Final Report

| | |
|---|---------------------------------------|
| Name of Company OXY USA WTP LP <i>16696</i> | Contact CAMPBELL, RODNEY |
| Address 329 Marathon Rd, Lakewood | Telephone No. (575) 628-4167 |
| Facility Name INDIAN BASIN GAS PLANT | Facility Type GAS PROCESSING FACILITY |

| | | |
|---------------|----------------------------|-----------|
| Surface Owner | Mineral Owner INDIAN BASIN | Lease No. |
|---------------|----------------------------|-----------|


LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| G | 23 | 21-S | 23-E | | | | | Eddy |

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release Gas | Volume of Release 99.8 MCF | Volume Recovered 0 |
| Source of Release Residue Flare | Date and Hour of Occurrence 10/9/2013 1:47:00 PM | Date and Hour of Discovery 10/9/2013 1:47:00 PM |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 8 MINUTES DUE TO HIGH OXYGEN CONTENT. Remedial Action Taken: OPERATIONS SAMPLED ALL INLET LINES AND STABILIZER DISCHARGE METER BUT DUE TO THE SHORT DURATION OF THE FLARE EVENT, SOURCE OF OXYGEN COULDN'T BE DETERMINED. | | |
| Describe Area Affected and Cleanup Action Taken.* | | |



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|---|-----------------------------------|
| Signature: <i>Rodney Campbell</i> | OIL CONSERVATION DIVISION | |
| Printed Name: RODNEY CAMPBELL | Approved by District Supervisor: Accepted for record NMOCD | |
| Title: <i>HES specialist</i> | Approval Date: NOV 06 2013 | Expiration Date: |
| E-mail Address: RODNEY_CAMPBELL@OXY.COM | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: <i>10-11-13</i> Phone: (575) 628-4167 | Like approval by BLM | |

* Attach Additional Sheets If Necessary
fJMW 1327034125
iJMW 1331128283

2RP-2053