


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

nMLB1407035850 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly # 85	Facility Type: Injection

Surface Owner: Federal	Mineral Owner:	API No.: 30-015-05422
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter B	Section 27	Township 17S	Range 31E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.8110323221284 Longitude: -103.855372475824

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 45 bbls	Volume Recovered: 10 bbls
Source of Release: 2 " nipple and flange	Date and Hour of Occurrence: 01/24/2014	Date and Hour of Discovery: 01/24/2014 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 01/27/2014 0833	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: I drove up to injection well #85 at 11:00am and I found a leak 50 foot north west of this injection well at the injection line header. The one inch line that feeds injection wells #86 and #107 was leaking. I shut the one inch line valve in to prevent the fluids from accumulating on the ground. I called Double R Trucking to pick up the produced water off of the ground.		
Describe Area Affected and Cleanup Action Taken.* : The impacted area was about 105 feet by 27 feet squared south east of the header. Called BSG roustabout to fix the leak. Water truck picked up about 10 barrels of fluid off of the ground. The cause of the leak was a bad steel flange and a bad 2 inch steel nipple.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Brian Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: Construction Foreman II	Approval Date: MAR 11 2014	Expiration Date: <i>N/A</i>
E-mail Address: bwall@linenergy.com Date: 01/27/2014 Phone: 806-367-0645	Conditions of Approval: <i>Remediation per NMOCD Rules & Guidelines - Remediation proposal by 4/11/14</i>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Rules & Guidelines - Remediation proposal by 4/11/14 *2RF-2196*

Bratcher, Mike, EMNRD

From: Natalie Gladden <ngladden@diversifiedfsi.com>
Sent: Tuesday, March 11, 2014 9:36 AM
To: Mike Burton (mburton@blm.gov); Bratcher, Mike, EMNRD
Cc: Rebecca Pons; Traci Jennings
Subject: Emailing: C- 141 Skelly 85 Inj 1-24-14
Attachments: C- 141 Skelly 85 Inj 1-24-14.pdf

Mike/Mike,

I have searched the NMOCD database and do not see that this C141 has been assigned an RP#. Please add this to your list.

We will start the initial phase this week once one-calls are clear.

Thanks,

Natalie Gladden
Environmental Director
DFSI Environmental Services
Cell: 575-602-1786
Office: 575-964-8394
Fax: 575-964-8396
Email: ngladden@diversifiedfsi.com

Your message is ready to be sent with the following file or link attachments:

C- 141 Skelly 85 Inj 1-24-14

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Tuesday, March 11, 2014 10:12 AM
To: 'Natalie Gladden'; Mike Burton (mburton@blm.gov)
Cc: Rebecca Pons; Traci Jennings
Subject: RE: Emailing: C- 141 Skelly 85 Inj 1-24-14

Natalie,

I got notification for this release and for a fire on the St. AZ Battery on 1/27/14, but don't see where we got a C-141 for either event. The RP # for the Skelly 85 will be 2RP-2196.

Thanks,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

-----Original Message-----

From: Natalie Gladden [<mailto:ngladden@diversifiedfsi.com>]
Sent: Tuesday, March 11, 2014 9:36 AM
To: Mike Burton (mburton@blm.gov); Bratcher, Mike, EMNRD
Cc: Rebecca Pons; Traci Jennings
Subject: Emailing: C- 141 Skelly 85 Inj 1-24-14

Mike/Mike,

I have searched the NMOCD database and do not see that this C141 has been assigned an RP#. Please add this to your list.

We will start the initial phase this week once one-calls are clear.

Thanks,

Natalie Gladden
Environmental Director
DFSI Environmental Services
Cell: 575-602-1786
Office: 575-964-8394
Fax: 575-964-8396
Email: ngladden@diversifiedfsi.com

Your message is ready to be sent with the following file or link attachments:

C- 141 Skelly 85 Inj 1-24-14

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

Bratcher, Mike, EMNRD

From: Mail Delivery System <MAILER-DAEMON@messagelabs.com>
To: tjennings@diversifiedfsi.com
Sent: Tuesday, March 11, 2014 10:12 AM
Subject: Undeliverable: Emailing: C- 141 Skelly 85 Inj 1-24-14

Delivery has failed to these recipients or groups:

tjennings@diversifiedfsi.com

A problem occurred during the delivery of this message to this e-mail address. Try sending this message again. If the problem continues, please contact your helpdesk.

The following organization rejected your message: d36569a.ess.barracudanetworks.com.

Diagnostic information for administrators:

Generating server: server-10.bemta-12.messagelabs.com

tjennings@diversifiedfsi.com

d36569a.ess.barracudanetworks.com # <d36569a.ess.barracudanetworks.com #5.0.0 smtp; 550 blocked> #SMTP#

Original message headers:

Return-Path: <mike.bratcher@state.nm.us>

Received: from [216.82.250.99:65334] by server-10.bemta-12.messagelabs.com id 99/32-06875-CB53F135; Tue, 11 Mar 2014 16:11:40 +0000

X-Env-Sender: mike.bratcher@state.nm.us

X-Msg-Ref: server-9.tower-126.messagelabs.com!1394554299!9801614!1

X-Originating-IP: [164.64.4.99]

X-StarScan-Received:

X-StarScan-Version: 6.9.16; banners=-, -, -

X-VirusChecked: Checked

Received: (qmail 9318 invoked from network); 11 Mar 2014 16:11:40 -0000

Received: from unknown (HELO webmail.state.nm.us) (164.64.4.99)

by server-9.tower-126.messagelabs.com with AES128-SHA encrypted SMTP; 11 Mar 2014 16:11:40 -0000

Received: from CEXHUB002.nmes.lcl ([fe80::f050:e955:c6de:7bf0]) by CEXHUB002.nmes.lcl (:::1) with mapi id 14.03.0174.001; Tue, 11 Mar 2014 10:11:38 -0600

From: "Bratcher, Mike, EMNRD" <mike.bratcher@state.nm.us>

To: Natalie Gladden <ngladden@diversifiedfsi.com>, "Mike Burton (mburton@blm.gov)" <mburton@blm.gov>

CC: Rebecca Pons <rpons@diversifiedfsi.com>, Traci Jennings <tjennings@diversifiedfsi.com>

Subject: RE: Emailing: C- 141 Skelly 85 Inj 1-24-14

Thread-Topic: Emailing: C- 141 Skelly 85 Inj 1-24-14

Thread-Index: Ac89P7UFA7sk/IwITJOkAYe1MqYpkAABG0rg
Date: Tue, 11 Mar 2014 16:11:37 +0000
Message-ID: <0D2C770BA7B2C84FAC6A50AD8A893D01A073F328@CEXMB002.nmes.lc|>
References: <C31BADB03EB0D648AB7BC1DE0901DC3DB5E49A@MB1.i.cloudmail.conetrix.com>
In-Reply-To: <C31BADB03EB0D648AB7BC1DE0901DC3DB5E49A@MB1.i.cloudmail.conetrix.com>
Accept-Language: en-US
Content-Language: en-US
X-MS-Has-Attach:
X-MS-TNEF-Correlator:
x-originating-ip: [164.64.106.176]
Content-Type: text/plain; charset="us-ascii"
Content-Transfer-Encoding: quoted-printable
MIME-Version: 1.0