


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nHMP1406634399

OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. 192463	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Tigger 9 State #7	Facility Type	Well Location

Surface Owner	State	Mineral Owner	API No. 30-015-40938
---------------	-------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	9	17S	29E	2253	South	1706	East	Eddy County, NM

Latitude N 32.84811° Longitude W 104.07686°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	1 bbl oil, 7 bbls produced water	Volume Recovered	.5 bbl oil, 3 bbls produced water
Source of Release	4" Poly production flow line	Date and Hour of Occurrence	02/13/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD		
By Whom?	Christopher Jones	Date and Hour	02/18/2014 @ 10:24 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A leak in a 4" poly production flow line caused 1 bbl of oil and 7 bbls of produced water to leak onto the ground. Free-standing fluids including 0.5 bbl of oil and 3 bbls of produced water were recovered via vacuum truck and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 30' x 900' on and off location. The leak is located approximately 1,000 feet North of the well head. Remediation will be completed in accordance with a plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Christopher Jones	Approved by District Supervisor:	
Title:	HES Specialist	Approval Date:	3/7/14
E-mail Address:	Christopher.Jones@oxy.com	Expiration Date:	
Date:	2/27/14	Conditions of Approval:	Remediation per OCD Rule & Guidelines, & Approval by BEM . SUBMIT REMEDIATION PROPOSAL NO LATER THAN:
Phone:	(575) 628-4121	Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

4/7/14

2RP 2187

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, February 27, 2014 2:43 PM
To: Bratcher, Mike, EMNRD
Cc: christopher_jones@oxy.com; cbrunson@bbcinternational.com;
kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Tigger 9 State #7
Attachments: Initial C-141, Tigger 9 State #13.pdf

Attached is the initial C-141 for a leak that occurred at the Tigger 9 State #7 on 02/13/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Tuesday, February 18, 2014 10:24 AM
To: Bratcher, Mike, EMNRD
Cc: kswinney@bbcinternational.com; kathy@bbcinternational.com;
cbrunson@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Tigger 9 St 7.

This is to inform you that Oxy had a leak at the Tigger 9 St 7 on 2-13-14. Oxy released 1 bbl oil and 7 bbls produced water and was able to recover .5 bbl oil and 3 bbl PW.

BBC will be doing some initial delineation and C141 be on its way. Directions to location is followed:

REGULATORY LEASE # 30-015-40938

2253 FSL 1706 FEL

SECT NONE T17S R29E

EDDY COUNTY NEW MEXICO

WEATHER FAIR WARM

FROM ARTESIA GO EAST ON 82, TURN NORTH ON CR 211 GO TO TIGGER SIGN ON RIGHT, TURN RIGHT PAST FLAME SKIMMER FACILITY, STAY STRAIGHT TILL ROAD VEERS LEFT ON LEFT SIDE OF BATTERY

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle