


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

nmlb1403652094 OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner B #7	Facility Type: Injection
Surface Owner: Federal	Mineral Owner:
API No.: 3001505185	

LOCATION OF RELEASE

Unit Letter O	Section 17	Township 17S	Range 31E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.8291123655792 Longitude: -103.889826027795

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 18 bbls	Volume Recovered: 15 bbls
Source of Release: 2" Fiberglass line	Date and Hour of Occurrence: 01/27/2014	Date and Hour of Discovery: 01/27/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton-BLM Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour 01/28/2014 0730	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: On Monday 1/27/14 Isidro Montez was making his morning rounds and I got a call that Diversified had hit a 2" Fiberglass injection line. Then I closed lateral valve that feeds that line to stop line from leaking. The line had been marked with yellow pin flags. It is the opinion of the operator that he didn't see the line. All liquid and contaminated soil was contained within the area were the clean up was taking place. A vacuum truck sucked up all residual liquid which were hauld off apprx 15bbls.		
Describe Area Affected and Cleanup Action Taken.* : Affected area is apprx 20'X20'. The spill was a fault of the contactor digging nearby. One call was turned in and Linn clearly marked site. Contractor is responsible for cleanup and cost.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Brian Wall</i>	Approved by District Supervisor: <i>Heard</i>	
Printed Name: Brian Wall	Approval Date: <i>2-5-14</i>	Expiration Date:
Title: Construction Foreman II	Conditions of Approval:	
E-mail Address: bwall@linenergy.com	Attached <input type="checkbox"/>	
Date: 01/28/2013	Phone: 806-367-0645	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

3-5-14

2RP-2176

Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Tuesday, January 28, 2014 8:43 AM
To: mburton@blm.gov; Bratcher, Mike, EMNRD
Cc: Callahan, Terry; Moreno, Laura; Butters, Thomas; Gonzales, EL; Wall, Fred; Hickert, Aaron; smcghee@diversifiedfsi.com; aruth@diversifiedfsi.com; mpatterson@diversifiedfsi.com
Subject: Linn-Turner B #7 1-27-14
Attachments: Turner B #7 Inj 1-27-14.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator

LINN Energy, LLC

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.